



PROGRESSIVE
CAR CARE PTE LTD

Progressive Car Care Pte Ltd
(Co. Reg. No. 201006949C)
Blk 3022A Ubi Road 1 #01-45/ 46 S408716
T: +65 6741 5336 | F: +65 6741 7208
E: claims@procarcare.com.sg
W: www.procarcare.com.sg

TP INSURER:
NG SENG HIONG

Singapore

India International Insurance Pte Ltd (HQ)

Claimant Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

TP III
Jasper

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP 0820-6055
Policy No:		Date of Loss:	27/08/2020
Vehicle Reg. No.:	SKV2571J	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	PAY LOO SENG		
Make/Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Vehicle Reg. Date:	07/09/2015
Vehicle Colour:	GREY	Chassis No:	MR053REH104537384
Engine No:	1ZRX526504		
Odometer:	98328 KM		
Paint Type:	NO		
Total Loss?	7		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336		
Remarks:	VEHICLE IS NOT IN WORKSHOP		
Present Location:	PROGRESSIVE CAR CARE PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	5,323.20
Miscellaneous Items	351.00
Labour	1,680.00
Paintwork Labour	900.00
Towing	0.00
Gross Total (S\$)	8,254.20
+ GST 7.00% (S\$)	577.79
Nett Amount (S\$)	8,831.99

This claim is handled by: NG PEI WEN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Sep 2020)
 Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Progressive Car Care Pte Ltd/SKV2571J/01/09/2020 09:34
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page.
 Further Info: Items values not in reference catalogue are prefixed with an asterisk.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*REAR BUMPER <i>Depr</i>	0.00	0.00	✓ *556.40 F
2	1	NA	*REAR BUMPER SIDE HOLDER - LH <i>neu</i>	0.00	0.00	✓ *109.00 F
3	1	NA	*REAR BUMPER SIDE HOLDER - RH <i>neu</i>	0.00	0.00	✓ *109.00 F
4	1	NA	*REAR BUMPER BRACKET - LH <i>neu</i>	0.00	0.00	✓ *68.20 F
5	1	NA	*REAR BUMPER BRACKET - RH <i>neu</i>	0.00	0.00	✓ *68.20 F
6	1	NA	*REAR BUMPER CLIPS <i>neu</i>	0.00	0.00	30 ✓ *56.00 F
7	1	NA	*REAR BUMPER SIDE PROTECTOR SEAL - RH <i>Depr</i>	0.00	0.00	✓ *65.10 F
8	1	NA	*REAR BUMPER SIDE PROTECTOR CLIP <i>neu</i>	0.00	0.00	✓ *5.50 F
9	1	NA	*REAR RIM - RH <i>Depr</i>	0.00	0.00	✓ *1,580.40 F
10	1	NA	*REAR RIM HUPCAP - RH <i>neu</i>	0.00	0.00	✓ *49.40 F
11	1	NA	*REAR ABSORBER - RH <i>neu</i>	0.00	0.00	✓ *218.20 F
12	1	NA	*REAR WHEEL BEARING - RH <i>neu</i>	0.00	0.00	✓ *960.50 F
13	1	NA	*REAR FENDER - RH <i>neu</i>	0.00	0.00	✓ *149.80 F
14	1	NA	*ROCKER PANEL - RH <i>neu</i>	0.00	0.00	✓ *482.80 F
15	1	NA	*REAR DOOR - RH <i>Depr</i>	0.00	0.00	✓ *1,248.50 F
16	1	NA	*REAR DOOR STICKER - RH <i>neu</i>	0.00	0.00	✓ *53.50 F
17	1	NA	*REAR DOOR RUBBER - RH <i>neu</i>	0.00	0.00	✓ *180.10 F
18	1	NA	*REAR DOOR CHROME OUTER WINDOW - RH <i>neu</i>	0.00	0.00	✓ *138.00 F
Sub Total (\$\$)						7,097.60
- Add. Disc. on L,N Items 25.00% (\$\$)						1,774.40
Total Parts (\$\$)						5,323.20

Progressive Car Care Pte Ltd/SKV2571J/01/09/2020 09:34. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	REAR TYRE - RH	280.00
2	2	SEALANT	40.00
3	1	SPONGE TAPE	20.00
4	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			351.00

Estimates on Labour

No	Particulars	Lab. Type	Amount
Paintwork Labour			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	600 900.00
Labour Items			
2	TO KNOCK OUT DENTS, CUT/WELD RH REAR FENDER; REMOVE; REPLACE ACCIDENT PARTS	New	800 100.00
3	TO CHECK WIRING	New	20.00
4	TO TUFF-KOTE	New	60 80.00
5	TO REMOVE; REFIX REAR GLASS	New	120.00
6	TO 4 WHEEL ALIGNMENT	New	70.00
7	TO REMOVE; REPLACE REAR UNDERCARRIAGE	New	200.00
8	TO TRANSFER DOOR AND DOOR FITTING	New	80.00
Gross Labour Cost (\$\$)			2,580.00

Progressive Car Care Pte Ltd/SKV2571J/01/09/2020 09:34. Not valid without Reference section
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment includes the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurer's surveyor

Acknowledged by Repairer
Signature:
Date:

Admin Lj
h/s 14/09/20
05 Days

total: 4459.20
L/S: 3.5K