

SURVEYOR NAME 07.09.20 LKK DATE OF SURVEY **ESTIMATE TO REPAIR** TIME OF SURVEY : PC 990 L VEHICLE NO. : 2-Sep-20 : TOYOTA MAKE DATE : 1-Sep-20 : HIACE HIROOF AUTO 14 SEATER DATE OF ACCIDENT MODEL SJW 2026 Z THIRD PARTY REF FWD Singapore Pte LtdFWD Singapore Pte Ltd : 2011 YEAR : JTFST22P800011583 THIRD PARTY REF Amount **CHASSIS NO** Nett Item Amt **Unit Price** Type An Parts Description/ Labour 396.80 Qty DiT 48.70 RU 88.90 rear bumper 1 pc 534.40 rear bumper retainer 1 pc 133.60 tail lamp lower ganish 1 pc 400.80 less 25 % Fin 200.00 (Bill) X NN 600.00 S.Nett rear bumper sensor S.Nett 1 pc 2000 450.00 co's logo 1 pc \$ 2501 To putty & spray paint. 300.00 \$ 1,950.80 labour charges. \$ TOTAL TG/VL Not Nothones Nor ...
1/ Emp &
Ne sony Afre Passey
2-300-11 3days LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting
 To display damaged part(s) during resurvey
 Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #93-09 Sin Ming Autocare Singapore 575721

Tel: 65-64520803 Fax: 65-64589127 Email: edmund@LTM.sg
Cc. Reg No. 199307277D GST Reg No. M2-0019086-0
Cc. Reg No. 199307277D disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd