

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Sep 2020 Sendback Est	02 Sep 2020 10:16 S\$4,632.66	03 Sep 2020 10:22 Edit Adj Rpt	S\$2,997.32 Edit Estimates	S\$2,997.32 View Rpt		Pending for Survey Report Cancel Case
Supp #1	16 Sep 2020 10:13	16 Sep 2020 10:16 S\$20.00	16 Sep 2020 10:16			(Combined)	Combined with Main Uncombine Suppl.

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	LION CITY RENTALS PTE LTD , Co. Reg. No.: 201504621K		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHA1117R	Date of Loss:	01/09/2020 14:00 - :59 [35 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M2004301	Policy/Cover Note No.:	ML000130 (Third Party Only) Coverage: 25/02/2020 - 24/02/2021
Vehicle Reg. No. (Insured):	SLN7351A	Policy No. (Claimant):	
		Excess:	S\$1,600.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Clara Milah Yeo]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 14/09/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHA1117R (M2004301)
[SLN7351A]
TP
COMFORT TRANSPORTATION PTE LTD
Sep 1 2020 2:00PM
[LION CITY RENTALS PTE LTD]
ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser

Assessment Reports			1 per page	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	02/09/20 10:16	Repairer Estimates	 Load HTM	
2	16/09/20 10:16	Repairer Estimates Suppl. #1	 Load HTM	
Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/09/20 15:23	Odometer Reading	 Load JPG	
2	15/09/20 15:23	Chassis Number	 Load JPG	
3	15/09/20 15:23	General View	 Load JPG	
4	15/09/20 15:23	General View	 Load JPG	
5	15/09/20 15:23	General View	 Load JPG	
6	15/09/20 15:23	General View	 Load JPG	
7	15/09/20 15:23	General View	 Load JPG	
8	15/09/20 15:23	General View	 Load JPG	
9	15/09/20 15:23	General View	 Load JPG	
10	15/09/20 15:23	General View	 Load JPG	
11	15/09/20 15:23	General View	 Load JPG	
12	15/09/20 15:23	General View	 Load JPG	
13	15/09/20 15:23	General View	 Load JPG	
14	15/09/20 15:23	General View	 Load JPG	
15	15/09/20 15:23	General View	 Load JPG	
16	15/09/20 15:23	General View	 Load JPG	
17	15/09/20 15:23	General View	 Load JPG	
18	15/09/20 15:23	General View	 Load JPG	
19	15/09/20 15:23	General View	 Load JPG	
20	15/09/20 15:23	After Repair Photo	 Load JPG	
21	15/09/20 15:23	After Repair Photo	 Load JPG	
22	15/09/20 15:23	After Repair Photo	 Load JPG	
23	15/09/20 15:23	After Repair Photo	 Load JPG	
24	15/09/20 15:23	After Repair Photo	 Load JPG	
25	15/09/20 15:23	After Repair Photo	 Load JPG	
Documentation			1 per page	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	02/09/20 10:18	E-filed GIA report	 Load PDF	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
1	03/09/20 10:14	WSHP EMAIL REQ PRS WITH ESTIMATE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI20009378/T1YF3S2**Date:** 18/09/2020REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	ML000130		
Claimant Vehicle No :	SHA1117R	Insured Vehicle No :	SLN7351A		
Date of Loss:	01/09/2020	Nature of Claim:	TP	Claim No:	M2004301

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1117R	Engine No:	2ZRS064106
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 (A)	Chassis No:	JTDKB3FU703564385
Reg. Date:	28/09/2017 (Man. Year: 2017)	Odometer:	387836 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,831.66	1,666.32	1,165.34	41.15
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,810.00	1,320.00	490.00	27.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,652.66	2,997.32	1,655.34	35.58
+ GST 7.00/7.00% (S\$)	325.69	209.81	115.88	35.58
Nett Amount (S\$)	4,978.35	3,207.13	1,771.22	35.58

INSPECTION

Date of Assignment:	03/09/2020	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	02/09/2020	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang)
			59 Loyang Drive
			Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** YVONNE WONG YIN CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Sep 2020)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA1117R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER COVER	Repair	458.60 FL	-	*- FL
2	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	-	*- FL
3	1		*REAR BUMPER FILLER EXTENSION LH	Repair	148.40 FL	-	*- FL
4	1		*REAR BUMPER RUBBER MAT	Not Necessary	50.00 F	-	*- F
5	1		*ROCKER PANEL MOULDING LH	Repair	570.11 FL	-	*- FL
6	1		*REAR DOOR APP LOGO LH	Necessary	80.00 F	-	*80.00 F
7	1		*REAR WHEEL RIM LH	Cut	1,555.10 FL	-	*1,555.10 FL
8	1		*REAR WHEEL TYRE LH	Not Necessary	216.00 F	-	*- F
9	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 F	-	*50.00 F
10	1		*REAR FENDER ADVERTISEMENT LOGO LH	Necessary	100.00 F	-	*100.00 F
11	1		*REAR FENDER ADVERTISEMENT LOGO RH	Necessary	100.00 F	-	*100.00 F
12	1		*REAR DOOR ADVERTISEMENT LOGO LH	Necessary	100.00 F	-	*100.00 F
13	1		*ROCKER PANEL ADVERTISEMENT LOGO LH	Cut	50.00 F	-	*50.00 F
Supplementary #1							
14	1		*FUEL TANK LID (PETROL ONLY) LOGO	Necessary	20.00 F	-	*20.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,520.21	2,055.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	688.55	388.78
Total Parts (\$\$)	2,831.66	1,666.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	750.00	480.00
2	SPRAY PAINTING CHARGE	New	850.00	700.00
3	TUFF KOTE	New	50.00	30.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
5	ADJUST REAR WHEEL ALIGNMENT	New	80.00	80.00
Gross Labour Cost (\$\$)			1,810.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >