

# PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 47823

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/0626/2020/NS  
Date : 2-Sep-20

07 Days  
\$ 16587.04.

Vehicle IN workshop. Kindly arrange for survey.

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Nimmi Panchatsharam  
Address : 59 Simei Rise  
#01-57  
Singapore 528793  
Telephone : HP +65 94554220  
Type of Claim : Own Damage Claim  
Policy No. :  
Vehicle No : **SMG 6936 U**  
Model Code : Audi A3 Sedan 1.0 TFSI 8V  
Model / Year : Dec-18  
Engine No : CHZ B22564  
Chassis No : WAUZZZ8V2K1011853  
Mileage : 19596  
Date In : 2-Sep-20  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 2-Sep-20  
Place of Accident : Still Road Entry

# PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SMG 6936 U

| S/N                         | Nature of Jobs                                                                                                                                                                                                         | Estimated Charges                | Surveyor's Recommendations |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|----------------------------|
| 1                           | To remove, check and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy. S/N \$                                                                                   | 280.00 ✓                         | ✓                          |
| 2                           | To remove and transfer lhs headlight control unit and power module. S/N \$                                                                                                                                             | <del>350.00</del> 250 ✓          | ✓                          |
| 3                           | To remove and renew aircon condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas. S/N \$                                       | 1,200.00 ✓                       | ✓                          |
| 4                           | To dismantle and renew front bumper, both front fenders, bonnet and lhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed. ✓ ✓ x x \$ | <del>5,600.00</del> 2250 ✓       | ✓                          |
| * 5                         | To respray front bumper, bonnet, hinges, lhs upper A-pillar and both front fenders. x x \$                                                                                                                             | <del>4,900.00</del> 1100. 1400 ✓ | ✓                          |
| 6                           | To carry out diagnostic check. S/N \$                                                                                                                                                                                  | 384.00 ✓                         | ✓                          |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                                        | <b>: \$ 12,714.00</b>            |                            |

# PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 6936 U

| S/N                           | Parts Description                                      | Damage Parts & Prices |           |
|-------------------------------|--------------------------------------------------------|-----------------------|-----------|
|                               |                                                        | S/Nett                | Remarks   |
| 1                             | FRONT BUMPER <i>Rehnd</i>                              | \$ 1,987.00 +         | 1589.60 ✓ |
| 2                             | FRONT BUMPER FIXING PARTS <i>men</i>                   | \$ 185.00 ✓           |           |
| 3                             | FRONT BUMPER GUIDE SECTION - LH <i>men</i>             | \$ 38.00 +            |           |
| 4                             | FRONT BUMPER GRILLE - CENTRE <i>men</i>                | \$ 159.00 ✓           |           |
| 5                             | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>men</i> | \$ 530.00 +           |           |
| 6                             | FRONT BUMPER CLOSING ELEMENT - LH <i>Not Nec</i>       | \$ 293.00 ? X         |           |
| 7                             | FRONT BUMPER COVER TRIM - LH <i>men</i>                | \$ 161.00 +           |           |
| 8                             | RADIATOR GRILLE <i>Cracked</i>                         | \$ 1,406.00 ✓         | 1124.80   |
| 9                             | RADIATOR GRILLE CLOSING ELEMENT <i>2 cracked.</i>      | \$ 189.00 ?           | 150.80 ✓  |
| 10                            | AIRCON STICKER <i>2</i>                                | NEC \$ 8.00 ✓         | 5.68      |
| 11                            | CAUTION SIGN STICKER <i>2</i>                          | NEC \$ 14.00 ✓        | 10.80     |
| 12                            | FRONT BUMPER AIR GUIDE GRILLE - LH <i>Not Nec</i>      | \$ 186.00 ? X         |           |
| 13                            | FRONT BUMPER SIDE REINFORCEMENT BEAM <i>Not Nec</i>    | \$ 715.00 ? X         |           |
| 14                            | FRONT BUMPER FOAM FILLER PIECE <i>Not Nec</i>          | \$ 187.00 ? X         |           |
| 15                            | FOAM FILLER PIECE COVER <i>Not Nec</i>                 | \$ 121.00 ? X         |           |
| 16                            | SIGNAL HORN - LH HIGH TONE <i>men</i>                  | \$ 197.00 +           |           |
| 17                            | FRONT FENDER - LH <i>men</i>                           | \$ 841.00 +           |           |
| 18                            | FRONT FENDER ATTACHMENT PARTS <i>2</i>                 | \$ 71.00 +            |           |
| 19                            | FRONT FENDER BRACKET - LH <i>1</i>                     | \$ 27.00 +            |           |
| 20                            | FRONT FENDER BRACKET - LH <i>1</i>                     | \$ 38.00 +            |           |
| SUB TOTAL SPARE PARTS CHARGES |                                                        | : \$ 7,353.00         |           |

# PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMG 6936 U

| S/N                           | Parts Description                        | Damage Parts & Prices |         |
|-------------------------------|------------------------------------------|-----------------------|---------|
|                               |                                          | S/Nett                | Remarks |
| 21                            | FRONT FENDER BRACE                       | \$ 95.00              | +       |
| 22                            | WHEEL HOUSING LINER - LH                 | \$ 167.00             | +       |
| 23                            | WHEEL HOUSING LINER ATTACHMENT PARTS     | \$ 88.00              | +       |
| 24                            | BONNET                                   | \$ 3,134.00           | 2507.20 |
| 25                            | BONNET ATTACHMENT PARTS                  | \$ 163.00             | X       |
| 26                            | BONNET LID HINGE - LH / RH               | 2 \$ 122.00           | 96.48   |
| 27                            | BONNET CATCH HOOK                        | \$ 89.00              | +       |
| 28                            | BONNET STRIKER - LH / RH                 | 2 \$ 218.00           | +       |
| 29                            | BONNET EDGE PROTECTION                   | \$ 28.00              | 21.84   |
| 30                            | SIDE SEAL - LH                           | \$ 41.00              | X       |
| 31                            | BONNET LID LOCK                          | \$ 212.00             | +       |
| 32                            | BONNET BOWDEN CABLE - CENTRE             | \$ 57.00              | +       |
| 33                            | BONNET SOUND ABSORBER                    | \$ 217.00             | +       |
| 34                            | PLENUM CHAMBER COVER                     | \$ 177.00             | 141.60  |
| 35                            | BONNET CATCH HOOK                        | \$ 63.00              | +       |
| 36                            | LED HEADLIGHT - LH                       | \$ 5,455.00           | 4364.00 |
| 37                            | MAIN LIGHT ELECTRONICS POWER MODULE - LH | \$ 749.00             | +       |
| 38                            | LED WITH HEAT SINK - LH                  | \$ 725.00             | +       |
| 39                            | LIGHT CONTROL SYSTEM CONTROL UNIT        | \$ 551.00             | +       |
| 40                            | HEADLAMP REPAIR KIT                      | \$ 130.00             | X       |
| SUB TOTAL SPARE PARTS CHARGES |                                          | : <u>\$ 12,481.00</u> |         |

# **PREMIUM AUTOMOBILES**

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## **Material List for Accident Vehicle Regn No. SMG 6936 U**

| S/N                              | Parts Description                                | Damage Parts & Prices |                  |
|----------------------------------|--------------------------------------------------|-----------------------|------------------|
|                                  |                                                  | S/Nett                | Remarks          |
| 41                               | HEADLIGHT HOSE - LH <i>Neu</i>                   | \$ 40.00              | <i>X</i>         |
| 42                               | LIFT CYLINDER - LH <i>Not Nec</i>                | \$ 141.00             | <i>? X</i>       |
| 43                               | LIFT CYLINDER HOSE <i>Neu</i>                    | \$ 67.00              | <i>X</i>         |
| 44                               | LOCK CARRIER <i>Cracked</i>                      | \$ 719.00             | <i>✓ 575.20</i>  |
| 45                               | READY MIX COOLANT <i>Neu</i>                     | \$ 177.00             | <i>✓ 141.44</i>  |
| 46                               | AIRCON CONDENSER <i>Neu</i>                      | \$ 517.00             | <i>✓</i>         |
| 47                               | TEMPERATURE SENSOR BRACKET <i>Cracked</i>        | \$ 18.00              | <i>? 14.40 ✓</i> |
| 48                               | RADIATOR AIR GUIDE - LH <i>Cracked</i>           | \$ 24.00              | <i>✓ 19.20 ✓</i> |
| 49                               | RADIATOR AIR GUIDE - UPPER CENTRE <i>Not Nec</i> | \$ 12.00              | <i>? X</i>       |
| 50                               | FRONT NO PLATE <i>Neu</i>                        | S/N \$ 60.00          | <i>✓ ✓</i>       |
| 51                               | SUNDRIES <i>Not Nec</i>                          | \$ 300.00             | <i>? X</i>       |
| <b>TOTAL SPARE PARTS CHARGES</b> |                                                  | <b>: \$ 21,909.00</b> |                  |
| <b>TOTAL LABOUR CHARGES</b>      |                                                  | <b>: \$ 12,714.00</b> |                  |
| <b>GRAND TOTAL</b>               |                                                  | <b>: \$ 34,623.00</b> |                  |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name

: Adrian

Surveyed Date

: 03/09/20

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 07 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Please Note

: This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant