

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 47823

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0626/2020/NS
Date : 2-Sep-20

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian,

7 days - ok - Jy - 2 Dec 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Nimmi Panchatsharam
Address : 59 Simei Rise
#01-57
Singapore 528793
Telephone : HP +65 94554220
Type of Claim : Own Damage Claim
Policy No. :
Vehicle No : **SMG 6936 U**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Dec-18
Engine No : CHZ B22564
Chassis No : WAUZZZ8V2K1011853
Mileage : 19596
Date In : 2-Sep-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 2-Sep-20
Place of Accident : Still Road Entry

Telefax

Estimated Labour Charges for Accident Vehicle. SMG 6936 U

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	280.00	\$ 280.00
2	To remove and transfer lhs headlight control unit and power module.	S/N \$	350.00	\$ 250.00
3	To remove and renew aircon condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,200.00	\$ 1,200.00
4	To dismantle and renew front bumper, both front fenders, bonnet and lhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$	5,600.00	\$ 2,250.00
5	To respray front bumper, bonnet, hinges, lhs upper A-pillar and both front fenders.	\$	4,900.00	\$ 1,400.00
6	To carry out diagnostic check.	S/N \$	384.00	\$ 384.00
TOTAL LABOUR CHARGES		:	\$ 12,714.00	\$ 5,764.00

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 6936 U

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 1,987.00	\$ 1,589.60
2	FRONT BUMPER FIXING PARTS	\$ 185.00	
3	FRONT BUMPER GUIDE SECTION - LH	\$ 38.00	
4	FRONT BUMPER GRILLE - CENTRE	\$ 159.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 530.00	
6	FRONT BUMPER CLOSING ELEMENT - LH	\$ 293.00	
7	FRONT BUMPER COVER TRIM - LH	\$ 161.00	
8	RADIATOR GRILLE	\$ 1,406.00	\$ 1,124.80
9	RADIATOR GRILLE CLOSING ELEMENT	\$ 189.00	\$ 150.80
10	AIRCON STICKER	NEC \$ 8.00	\$ 5.68
11	CAUTION SIGN STICKER	NEC \$ 14.00	\$ 10.80
12	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 186.00	
13	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$ 715.00	
14	FRONT BUMPER FOAM FILLER PIECE	\$ 187.00	
15	FOAM FILLER PIECE COVER	\$ 121.00	
16	SIGNAL HORN - LH HIGH TONE	\$ 197.00	
17	FRONT FENDER - LH	\$ 841.00	
18	FRONT FENDER ATTACHMENT PARTS	\$ 71.00	
19	FRONT FENDER BRACKET - LH	\$ 27.00	
20	FRONT FENDER BRACKET - LH	\$ 38.00	
SUB TOTAL SPARE PARTS CHARGES		\$ 7,353.00	\$ 2,881.68

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 6936 U

S/N	Parts Description		Damage Parts & Prices	
			S/Nett	Remarks
		<i>c/f</i>		\$ 2,881.68
21	FRONT FENDER BRACE		\$ 95.00	
22	WHEEL HOUSING LINER - LH		\$ 167.00	
23	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 88.00	
24	BONNET		\$ 3,134.00	\$ 2,507.20
25	BONNET ATTACHMENT PARTS		\$ 163.00	
26	BONNET LID HINGE - LH / RH	2	\$ 122.00	\$ 96.48
27	BONNET CATCH HOOK		\$ 89.00	
28	BONNET STRIKER - LH / RH	2	\$ 218.00	
29	BONNET EDGE PROTECTION		\$ 28.00	\$ 21.84
30	SIDE SEAL - LH		\$ 41.00	
31	BONNET LID LOCK		\$ 212.00	
32	BONNET BOWDEN CABLE - CENTRE		\$ 57.00	
33	BONNET SOUND ABSORBER		\$ 217.00	
34	PLENUM CHAMBER COVER		\$ 177.00	\$ 141.60
35	BONNET CATCH HOOK		\$ 63.00	
36	LED HEADLIGHT - LH		\$ 5,455.00	\$ 4,364.00
37	MAIN LIGHT ELECTRONICS POWER MODULE - LH		\$ 749.00	
38	LED WITH HEAT SINK - LH		\$ 725.00	
39	LIGHT CONTROL SYSTEM CONTROL UNIT		\$ 551.00	
40	HEADLAMP REPAIR KIT		\$ 130.00	
SUB TOTAL SPARE PARTS CHARGES			\$ 12,481.00	\$ 10,012.80

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 6936 U

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
		<i>c/f</i>	\$ 10,012.80
41	HEADLIGHT HOSE - LH	\$ 40.00	
42	LIFT CYLINDER - LH	\$ 141.00	
43	LIFT CYLINDER HOSE	\$ 67.00	
44	LOCK CARRIER	\$ 719.00	\$ 575.20
45	READY MIX COOLANT	\$ 177.00	\$ 141.44
46	AIRCON CONDENSER	\$ 517.00	
47	TEMPERATURE SENSOR BRACKET	\$ 18.00	\$ 14.40
48	RADIATOR AIR GUIDE - LH	\$ 24.00	\$ 19.20
49	RADIATOR AIR GUIDE - UPPER CENTRE	\$ 12.00	
50	FRONT NO PLATE	S/N \$ 60.00	\$ 60.00
51	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS CHARGES		: \$ 21,909.00	\$ 10,823.04
TOTAL LABOUR CHARGES		: \$ 12,714.00	\$ 5,764.00
GRAND TOTAL		: \$ 34,623.00	\$ 16,587.04

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant