

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	02 Sep 2020 19:15	Clm Veh Model Changed		[] Merimen Administrator
2	02 Sep 2020 19:15	Clm Created	Reg No: SMG6936U. Acct Date: 2020/09/02. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Lt d. (SG). Ins.Status => Notification. Created from SAS:MPA120075759	[I] Merimen Administrator
3	03 Sep 2020 15:05	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] LEE SU THING
4	03 Sep 2020 15:05	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] LEE SU THING
5	03 Sep 2020 15:05	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
6	03 Sep 2020 15:05	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/09/14	[A] LEE SU THING
7	03 Sep 2020 15:05	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] LEE SU THING
8	03 Sep 2020 15:05	Clm Registration Modified	Rep:1137->200611.	[A] LEE SU THING
9	03 Sep 2020 15:05	Clm Veh Model Changed	(206113) AUDI A3 999cc SEDAN TFSI (A).	[A] LEE SU THING
10	03 Sep 2020 15:05	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] LEE SU THING
11	04 Sep 2020 10:50	Clm Registration Modified	Acct Time:05:25:00->05:00:00. Pol No:->1800151238. Init.Est.:->5,000 - 6,000.	[I] Nadaraja, Deeban
12	04 Sep 2020 12:31	Adj Rpt Initiated		[A] SHIAU CHAN
13	04 Sep 2020 12:31	Clm Dtl Modified	JPJ Reg. Date: -> 2018/12/28.	[A] SHIAU CHAN
14	04 Sep 2020 12:31	Clm Details Notified		[A] SHIAU CHAN
15	04 Sep 2020 14:13	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2020/09/14	[A] SHIAU CHAN
16	04 Sep 2020 15:21	Adj Mandate Request	Cur.Req:21666.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
17	07 Sep 2020 14:49	Clm Registration Modified	Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Nadaraja, Deeban
18	07 Sep 2020 14:49	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
19	07 Sep 2020 17:12	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/09/14. Mandate Remarks: Authorise repair. No plate not damage to take out. Condenser damage photos? Re-inspection to be done for damage check and supplementary items / labour with clear photos.	[I] Koh, Victor-CK
20	07 Sep 2020 17:12	Adj Mandate Set	Approved:19146.00:Authorise repair. No plate not damage to take out. Condenser damage photos? Re-inspection to be done for damage check and supplementary items / labour with clear photos. Reinsp:Yes.	[I] Koh, Victor-CK

Date From  Date To  Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2577850	04 Sep 2020 12:31:26	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMG6936U		11.00

