

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0628/2020/NS
Date	:	3-Sep-20

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Zou Qibin
Address	:	158 Canberra Drive #07-38 Singapore 768083
Telephone	:	HP +65 81399558
Type of Claim	:	Own Damage Claim
Policy No.	:	1700050003-02
Vehicle No	:	SLS 1885 P
Model Code	:	Audi A3 Sedan 1.0 TFSI 8V
Model / Year	:	Sep-17
Engine No	:	CHZ 528864
Chassis No	:	WAUZZZ8V2J1013309
Mileage	:	67387KM
Date In	:	2-Sep-20
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	2-Sep-20
Place of Accident	:	Yishun Ave 2 And Yishun Ave 5 Junction

Mertan

\$19326k

WIP : 47818

24918k

775

496-00

\$26189-00

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel 6366 2323 Fax 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLS 1885 P

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To tow and recover vehicle from scene of accident.	S/N \$ 280.00	X.
2	To carry out first measurement test on car o-liner.	S/N \$ 800.00	?
3	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 280.00	250 ✓
4	To remove and transfer rhs headlight control unit and power module.	S/N \$ 350.00	250 .
5	To remove and renew aircon condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	?
6	To dismantle rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$ 350.00	280 .
7	To place vehicle on car o-liner.	S/N \$ 1,800.00	?
8	To dismantle and renew front bumper, both front fenders, bonnet and rhs headlight. To cut out and weld rhs front fender top support. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 7,700.00	1500 (without lock carrier) 2750 (with lock carrier)
9	To respray front bumper, bonnet, hinges, both front fenders, rhs front door, rhs front fender top support and rhs A-pillar. To carry out stone chip treatment and joint sealer works.	\$ 6,300.00	Fender top support. 2200 . 2475
10	To carry out pre-wheel alignment test.	S/N \$ 240.00	X
11	To carry out pre and post repair diagnostic check.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 19,684.00	

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1885 P

S/N	Parts Description	S/Nett	Damage Parts & Prices	Remarks
1	FRONT BUMPER <i>Disturbed</i>	\$	1,987.00 ✓	
2	FRONT BUMPER FIXING PARTS ?	\$	185.00 ?	
3	FRONT BUMPER GUIDE SECTION - RH <i>could</i>	\$	38.00 *	
4	FRONT BUMPER GRILLE - CENTRE <i>new</i>	\$	159.00 *	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE ? <i>Torn</i>	\$	530.00 ?	\$530
6	FRONT BUMPER CLOSING ELEMENT - RH ? <i>Crack</i>	\$	293.00 ?	\$293
7	FRONT BUMPER COVER TRIM - RH <i>new</i>	\$	161.00 *	
8	WHEEL HOUSING LINER ADAPTER - RH ?	\$	37.00 ?	
9	RADIATOR GRILLE ?	\$	1,406.00 ?	
10	RADIATOR GRILLE CLOSING ELEMENT ? <i>Crack</i>	\$	189.00 ?	\$189
11	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Disturbed</i>	\$	186.00 ✓	
12	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>But</i>	\$	715.00 ✓	
13	FRONT BUMPER FOAM FILLER PIECE <i>could Crack</i>	\$	187.00 ✓	
14	FOAM FILLER PIECE COVER ? <i>Crack</i>	\$	121.00 ?	\$121
15	AIRCON STICKER <i>new</i>	NEC \$	8.00 ✓	
16	CAUTION SIGN STICKER	NEC \$	14.00 ✓	
17	SIGNAL HORN - RH LOW TONE ? <i>Crack</i>	\$	197.00 ?	\$197.00
18	FRONT FENDER - LH / RH <i>RH Disturbed</i>	2 \$	1,682.00	841
19	FRONT FENDER ATTACHMENT PARTS ?	\$	71.00 ?	
20	FRONT FENDER BRACKET - RH <i>Disturbed</i>	\$	27.00 ✓	
SUB TOTAL SPARE PARTS CHARGES		:	\$ 8,193.00	

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel 6366 2323 Fax 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1885 P

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	FRONT FENDER BRACKET - RH	\$ 38.00	✓
22	FRONT FENDER BRACE	\$ 95.00	✓
23	FRONT FENDER CLOSING ELEMENT - RH	\$ 33.00	✓
24	WHEEL HOUSING LINER SEAL - RH	\$ 34.00	✓
25	FRONT FENDER INSULATION - RH	\$ 42.00	✓
26	WHEEL HOUSING LINER - RH	\$ 167.00	✓
27	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 88.00	✓
28	BONNET	\$ 3,134.00	✓
29	BONNET ATTACHMENT PARTS	\$ 163.00	✓
30	BONNET LID HINGE - LH / RH	2 \$ 122.00	✓
31	BONNET CATCH HOOK	\$ 89.00	✓
32	BONNET GAS FILLED STRUT	\$ 118.00	✓
33	BONNET STRIKER - RH	\$ 109.00	✓
34	BONNET EDGE PROTECTION	\$ 28.00	✓
35	FRONT FENDER TOP SUPPORT COVER - RH	\$ 41.00	✓
36	BONNET CATCH HOOK	\$ 63.00	✓
37	BONNET LID LOCK	\$ 212.00	✓ \$212.00
38	BONNET BOWDEN CABLE - CENTRE	\$ 57.00	✓
39	BONNET LID LOCK CABLE	\$ 73.00	✓
40	BONNET SOUND ABSORBER	\$ 217.00	✓
SUB TOTAL SPARE PARTS CHARGES		\$ 4,923.00	

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1885 P

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
41	PLENUM CHAMBER COVER ? <i>Ce</i>	\$ 177.00	\$177
42	LED HEADLIGHT - RH <i>smashed</i>	\$ 5,455.00	✓
43	MAIN LIGHT ELECTRONICS POWER MODULE - RH ? <i>Ce</i>	\$ 749.00	\$749-00
44	LED WITH HEAT SINK - RH ? <i>Myge</i>	\$ 725.00	\$725-00
45	LIGHT CONTROL SYSTEM CONTROL UNIT ? <i>Myge</i>	\$ 551.00	\$551-00
46	HEADLAMP REPAIR KIT ?	\$ 130.00	?
47	HEADLIGHT HOSE - RH <i>new</i>	\$ 40.00	x
48	LIFT CYLINER <i>crushed</i>	\$ 141.00	✓
49	LIFT CYLINDER HOSE <i>new</i>	\$ 67.00	x
50	FRONT FENDER TOP SUPPORT - RH ? <i>Buckled</i>	\$ 73.00	\$73
51	LOCK CARRIER ? <i>Crack</i>	\$ 719.00	\$719
52	AIRCON CONDENSER <i>new</i>	\$ 517.00	x
53	TEMPERATURE SENSOR BRACKET ?	\$ 18.00	?
54	READY MIX COOLANT ? <i>new</i>	\$ 91.00	\$91-00
55	ADDITIONAL RADIATOR ?	\$ 859.00	?
56	RADIATOR ? <i>Broken</i>	\$ 941.00	\$941-00
57	RADIATOR AIR GUIDE - RH ? <i>leak</i>	\$ 24.00	\$24-00
58	RADIATOR AIR GUIDE - UPPER CENTRE ?	\$ 12.00	?
59	AIR INTAKE AIR DUCT COVER ?	\$ 28.00	?
60	AIR INTAKE AIR GUIDE ?	\$ 54.00	?

SUB TOTAL SPARE PARTS CHARGES : \$ 11,371.00

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1885 P

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
61	AIR INTAKE AIR GUIDE ?	\$ 64.00 ?	
62	AIR INTAKE AIR FILTER ?	\$ 269.00 ?	
63	AIR INTAKE AIR GUIDE ?	\$ 19.00 ?	
64	WATER DRAINAGE HOSE <i>new</i>	\$ 32.00 X	
65	WINDOW SLOT SEAL - RH FRONT <i>new</i>	\$ 305.00 +	
66	WATER DEFLECTOR STRIP - RH <i>Missing</i>	\$ 92.00 ✓	
67	CAVITY WAX ?	S/N \$ 140.00 ?	
68	STONE CHIP ?	S/N \$ 180.00 ?	
69	ACRYLIC SEALANT ?	S/N \$ 180.00 ?	
70	FRONT NO PLATE ?	S/N \$ 60.00 ?	
71	SUNDRIES ?	\$ 400.00 ?	
TOTAL SPARE PARTS CHARGES		: \$ 26,228.00	
TOTAL LABOUR CHARGES		: \$ 19,684.00	
GRAND TOTAL		: \$ 45,912.00	

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :

Surveyed Date :

Authorised Date :

Excess Cost :

Liability :

Remarks :

Adnan Ly
03/04/20

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--

Not Authorised, - 2 days (without lock carrier)
10 days (with lock carrier)

11 day

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 47818

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0628/2020/NS
Date : 3-Sep-20

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Zou Qibin
Address : 158 Canberra Drive
#07-38
Singapore 768083
Telephone : HP +65 81399558
Type of Claim : Own Damage Claim
Policy No. : 1700050003-02
Vehicle No : **SLS 1885 P**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Sep-17
Engine No : CHZ 528864
Chassis No : WAUZZZ8V2J1013309
Mileage : 67387KM
Date In : 2-Sep-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 2-Sep-20
Place of Accident : Yishun Ave 2 And Yishun Ave 5 Junction

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLS 1885 P

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To tow and recover vehicle from scene of accident.	S/N \$ 280.00 X	
2	To carry out first measurement test on car o-liner.	S/N \$ 800.00 ?	
3	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 280.00 250 ✓	
4	To remove and transfer rhs headlight control unit and power module.	S/N \$ 350.00 250 ✓	
5	To remove and renew aircon condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00 ?	
6	To dismantle rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$ 350.00 280 ✓	
7	To place vehicle on car o-liner.	S/N \$ 1,800.00 ?	
8	To dismantle and renew front bumper, both front fenders, bonnet and rhs headlight. To cut out and weld rhs front fender top support. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 7,700.00 3250 = 1500 (Without Lock Carrier) 2750 (With Lock Carrier) + 500 (Fender Top Support) (Fender top support.)	
9	To respray front bumper, bonnet, hinges, both front fenders, rhs front door, rhs front fender top support and rhs A-pillar. To carry out stone chip treatment and joint sealer works.	\$ 6,300.00 2200 + 275 = 2475	
10	To carry out pre-wheel alignment test.	S/N \$ 240.00 X	
11	To carry out pre and post repair diagnostic check.	S/N \$ 384.00 ✓	
TOTAL LABOUR CHARGES		: \$ 19,684.00	

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1885 P

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER Disturbed	\$ 1,987.00	✓
2	FRONT BUMPER FIXING PARTS ?	\$ 185.00	?
3	FRONT BUMPER GUIDE SECTION - RH could could	\$ 38.00	+
4	FRONT BUMPER GRILLE - CENTRE new	\$ 159.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE torn	\$ 530.00	✓
6	FRONT BUMPER CLOSING ELEMENT - RH could	\$ 293.00	✓
7	FRONT BUMPER COVER TRIM - RH new	\$ 161.00	+
8	WHEEL HOUSING LINER ADAPTER - RH ?	\$ 37.00	?
9	RADIATOR GRILLE ?	\$ 1,406.00	?
10	RADIATOR GRILLE CLOSING ELEMENT could	\$ 189.00	✓
11	FRONT BUMPER AIR GUIDE GRILLE - RH Disturbed	\$ 186.00	✓
12	FRONT BUMPER SIDE REINFORCEMENT BEAM But	\$ 715.00	✓
13	FRONT BUMPER FOAM FILLER PIECE could	\$ 187.00	✓
14	FOAM FILLER PIECE COVER ? could could	\$ 121.00	✓
15	AIRCON STICKER new	NEC \$ 8.00	✓
16	CAUTION SIGN STICKER new	NEC \$ 14.00	✓
17	SIGNAL HORN - RH LOW TONE could	\$ 197.00	✓
18	FRONT FENDER - LH / RH RH Disturbed	2 \$ 1,682.00	841
19	FRONT FENDER ATTACHMENT PARTS ?	\$ 71.00	?
20	FRONT FENDER BRACKET - RH Disturbed	\$ 27.00	✓
SUB TOTAL SPARE PARTS CHARGES		: \$ 8,193.00	

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1885 P

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	FRONT FENDER BRACKET - RH ? <i>Dislodged</i>	\$ 38.00	✓
22	FRONT FENDER BRACE	\$ 95.00	✓
23	FRONT FENDER CLOSING ELEMENT - RH <i>Dislodged</i>	\$ 33.00	✓
24	WHEEL HOUSING LINER SEAL - RH <i>Dislodged</i>	\$ 34.00	✓
25	FRONT FENDER INSULATION - RH ?	\$ 42.00	?
26	WHEEL HOUSING LINER - RH <i>top</i>	\$ 167.00	✓
27	WHEEL HOUSING LINER ATTACHMENT PARTS ?	\$ 88.00	?
28	BONNET <i>Dislodged</i>	\$ 3,134.00	✓
29	BONNET ATTACHMENT PARTS	\$ 163.00	?
30	BONNET LID HINGE LH / RH ?	2 \$ 122.00	?
31	BONNET CATCH HOOK ?	\$ 89.00	?
32	BONNET GAS FILLED STRUT ?	\$ 118.00	?
33	BONNET STRIKER - RH ?	\$ 109.00	?
34	BONNET EDGE PROTECTION <i>new</i>	\$ 28.00	✓
35	FRONT FENDER TOP SUPPORT COVER - RH ?	\$ 41.00	?
36	BONNET CATCH HOOK ?	\$ 63.00	?
37	BONNET LID LOCK <i>PH Dislodged</i>	\$ 212.00	✓
38	BONNET BOWDEN CABLE - CENTRE ?	\$ 57.00	?
39	BONNET LID LOCK CABLE ?	\$ 73.00	?
40	BONNET SOUND ABSORBER ?	\$ 217.00	?
SUB TOTAL SPARE PARTS CHARGES		: \$ 4,923.00	

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1885 P

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
41	PLENUM CHAMBER COVER <i>crushed</i>	\$ 177.00	✓
42	LED HEADLIGHT - RH <i>crushed</i>	\$ 5,455.00	✓
43	MAIN LIGHT ELECTRONICS POWER MODULE - RH <i>crushed</i>	\$ 749.00	✓
44	LED WITH HEAT SINK - RH <i>crushed</i>	\$ 725.00	✓
45	LIGHT CONTROL SYSTEM CONTROL UNIT <i>crushed</i>	\$ 551.00	✓
46	HEADLAMP REPAIR KIT	\$ 130.00	?
47	HEADLIGHT HOSE - RH <i>new</i>	\$ 40.00	✓
48	LIFT CYLINER <i>RH</i> <i>crushed</i>	\$ 141.00	✓
49	LIFT CYLINDER HOSE <i>new</i>	\$ 67.00	✓
50	FRONT FENDER TOP SUPPORT - RH <i>crushed</i>	\$ 73.00	✓
51	LOCK CARRIER <i>crushed</i>	\$ 719.00	✓
52	AIRCON CONDENSER <i>new</i>	\$ 517.00	✓
53	TEMPERATURE SENSOR BRACKET	\$ 18.00	?
54	READY MIX COOLANT <i>new</i>	\$ 91.00	✓
55	ADDITIONAL RADIATOR	\$ 859.00	?
56	RADIATOR	\$ 941.00	?
57	RADIATOR AIR GUIDE - RH <i>crushed</i>	\$ 24.00	✓
58	RADIATOR AIR GUIDE - UPPER CENTRE	\$ 12.00	?
59	AIR INTAKE AIR DUCT COVER	\$ 28.00	?
60	AIR INTAKE AIR GUIDE	\$ 54.00	?
SUB TOTAL SPARE PARTS CHARGES		: \$ 11,371.00	

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1885 P

S/N Parts Description		Damage Parts & Prices		Remarks
S/N	Parts Description	S/Nett		
61	AIR INTAKE AIR GUIDE ?	\$	64.00 ?	
62	AIR INTAKE AIR FILTER ?	\$	269.00 ?	
63	AIR INTAKE AIR GUIDE ?	\$	19.00 ?	
64	WATER DRAINAGE HOSE <i>the m</i>	\$	32.00 X	
65	WINDOW SLOT SEAL - RH FRONT <i>new</i>	\$	305.00 +	
66	WATER DEFLECTOR STRIP - RH <i>missing</i>	\$	92.00 ✓	
67	CAVITY WAX ?	S/N \$	140.00 ?	
68	STONE CHIP ?	S/N \$	180.00 ?	
69	ACRYLIC SEALANT ?	S/N \$	180.00 ?	
70	FRONT NO PLATE ?	S/N \$	60.00 ?	
71	SUNDRIES ?	\$	400.00 ?	
TOTAL SPARE PARTS CHARGES		:	\$ 26,228.00	
TOTAL LABOUR CHARGES		:	\$ 19,684.00	
GRAND TOTAL		:	\$ 45,912.00	

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ly
Surveyed Date : 03/09/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not authorised, 14 days.
inclusive of lock carrier
and bumper support

Please Note : This estimate is based on visual inspection of the affected vehicle. 11/09/20.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1885 P

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
41	PLENUM CHAMBER COVER <i>included</i>	S 177.00	✓
42	LED HEADLIGHT - RH <i>sampled</i>	S 5,455.00	✓
43	MAIN LIGHT ELECTRONICS POWER MODULE - RH <i>sampled</i>	S 749.00	✓
44	LED WITH HEAT SINK - RH <i>sampled</i>	S 725.00	✓
45	LIGHT CONTROL SYSTEM CONTROL UNIT <i>sampled</i>	S 551.00	✓
46	HEADLAMP REPAIR KIT	S 130.00	✓
47	HEADLIGHT HOSE - RH	S 40.00	✓
48	LIFT CYLINER <i>RH included</i>	S 141.00	✓
49	LIFT CYLINDER HOSE <i>not in</i>	S 67.00	✓
50	FRONT FENDER TOP SUPPORT - RH <i>included</i>	S 73.00	✓
51	LOCK CARRIER <i>included</i>	S 710.00	✓
52	AIRCON CONDENSER	S 517.00	✓
53	TEMPERATURE SENSOR BRACKET	S 18.00	✓
54	READY MIX COOLANT <i>not in</i>	S 91.00	✓
55	ADDITIONAL RADIATOR	S 859.00	✓
56	RADIATOR <i>Broken</i>	S 941.00	✓ 15/09/20 Adrian G
57	RADIATOR AIR GUIDE - RH <i>included</i>	S 24.00	✓
58	RADIATOR AIR GUIDE - UPPER CENTRE	S 12.00	✓
59	AIR INTAKE AIR DUCT COVER	S 28.00	✓
60	AIR INTAKE AIR GUIDE	S 54.00	✓
SUB TOTAL SPARE PARTS CHARGES		: \$ 11,371.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0628/2020/NS 12-Sep-20 Glory Tan 1 of 1 SLS 1885 P Audi A3 Sedan 1.0 TFSI 8V
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Aircon refrigerant line <i>Best</i> (Compressor to cut off point)	\$ 476.00	<i>380.40</i> ✓
2	Socket for signal horn RHS <i>cracked</i>	\$ 20.00	<i>15.76</i> ✓
TOTAL		\$ 496.00	

For Premium Automobiles Pte Ltd

Adrian Ling
14/09/20
HL/S

Authorised Signature