

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 47818

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0628/2020/NS
Date : 03-Sep-20

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Hi Adrian,

13 days - ok - Jy - 11 Feb 21

Owner's Name : Mr Zou Qibin
Address : 158 Canberra Drive
#07-38
Singapore 768083
Telephone : HP +65 81399558
Type of Claim : Own Damage Claim
Policy No. : 1700050003-02
Vehicle No : **SLS 1885 P**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Sep-17
Engine No : CHZ 528864
Chassis No : WAUZZZ8V2J1013309
Mileage : 67387KM
Date In : 02-Sep-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 02-Sep-20
Place of Accident : Yishun Ave 2 And Yishun Ave 5 Junction



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLS 1885 P

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To tow and recover vehicle from scene of accident.	S/N \$	280.00	
2	To carry out first measurement test on car o-liner.	S/N \$	800.00	\$ 800.00
3	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assembly.	S/N \$	280.00	\$ 280.00
4	To remove and transfer rhs headlight control unit and power module.	S/N \$	350.00	\$ 250.00
5	To remove and renew aircon condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,200.00	\$ 1,200.00
6	To dismantle rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$	350.00	\$ 280.00
7	To place vehicle on car o-liner.	S/N \$	1,800.00	\$ 1,800.00
8	To dismantle and renew front bumper, both front fenders, bonnet and rhs headlight. To cut out and weld rhs front fender top support. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$	7,700.00	\$ 3,250.00
9	To respray front bumper, bonnet, hinges, both front fenders, rhs front door, rhs front fender top support and rhs A-pillar. To carry out stone chip treatment and joint sealer works.	\$	6,300.00	\$ 2,475.00
10	To carry out pre-wheel alignment test.	S/N \$	240.00	
11	Supplementary	\$	280.00	\$ 280.00
12	To carry out pre and post repair diagnostic check.	S/N \$	384.00	\$ 384.00
TOTAL LABOUR CHARGES		:	\$ 19,964.00	\$ 10,999.00

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1885 P

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 1,987.00	\$ 1,589.60
2	FRONT BUMPER FIXING PARTS	\$ 185.00	
3	FRONT BUMPER GUIDE SECTION - RH	\$ 38.00	
4	FRONT BUMPER GRILLE - CENTRE	\$ 159.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 530.00	\$ 424.00
6	FRONT BUMPER CLOSING ELEMENT - RH	\$ 293.00	\$ 234.40
7	FRONT BUMPER COVER TRIM - RH	\$ 161.00	
8	WHEEL HOUSING LINER ADAPTER - RH	\$ 37.00	
9	RADIATOR GRILLE	\$ 1,406.00	
10	RADIATOR GRILLE CLOSING ELEMENT	\$ 189.00	\$ 150.80
11	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 186.00	\$ 148.40
12	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$ 715.00	\$ 571.60
13	FRONT BUMPER FOAM FILLER PIECE	\$ 187.00	\$ 149.60
14	FOAM FILLER PIECE COVER	\$ 121.00	
15	AIRCON STICKER	NEC \$ 8.00	
16	CAUTION SIGN STICKER	NEC \$ 14.00	
17	SIGNAL HORN - RH LOW TONE	\$ 197.00	\$ 157.60
18	FRONT FENDER - LH / RH	2 \$ 1,682.00	\$ 672.80
19	FRONT FENDER ATTACHMENT PARTS	\$ 71.00	
20	FRONT FENDER BRACKET - RH	\$ 27.00	\$ 21.52
SUB TOTAL SPARE PARTS CHARGES		: \$ 8,193.00	\$ 4,120.32

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1885 P

S/N	Parts Description		Damage Parts & Prices	
			S/Nett	Remarks
		<i>c/f</i>		\$ 4,120.32
21	FRONT FENDER BRACKET - RH		\$ 38.00	\$ 30.40
22	FRONT FENDER BRACE		\$ 95.00	\$ 75.68
23	FRONT FENDER CLOSING ELEMENT - RH		\$ 33.00	\$ 25.92
24	WHEEL HOUSING LINER SEAL - RH		\$ 34.00	
25	FRONT FENDER INSULATION - RH		\$ 42.00	
26	WHEEL HOUSING LINER - RH		\$ 167.00	\$ 133.20
27	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 88.00	
28	BONNET		\$ 3,134.00	\$ 2,507.20
29	BONNET ATTACHMENT PARTS		\$ 163.00	
30	BONNET LID HINGE - LH / RH	2	\$ 122.00	
31	BONNET CATCH HOOK		\$ 89.00	
32	BONNET GAS FILLED STRUT		\$ 118.00	
33	BONNET STRIKER - RH		\$ 109.00	
34	BONNET EDGE PROTECTION		\$ 28.00	\$ 21.84
35	FRONT FENDER TOP SUPPORT COVER - RH		\$ 41.00	
36	BONNET CATCH HOOK		\$ 63.00	
37	BONNET LID LOCK		\$ 212.00	\$ 169.20
38	BONNET BOWDEN CABLE - CENTRE		\$ 57.00	
39	BONNET LID LOCK CABLE		\$ 73.00	
40	BONNET SOUND ABSORBER		\$ 217.00	
SUB TOTAL SPARE PARTS CHARGES		:	\$ 4,923.00	\$ 7,083.76

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1885 P

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
	<i>c/f</i>		\$ 7,083.76
41	PLENUM CHAMBER COVER	\$ 177.00	\$ 141.60
42	LED HEADLIGHT - RH	\$ 5,455.00	\$ 4,364.00
43	MAIN LIGHT ELECTRONICS POWER MODULE - RH	\$ 749.00	\$ 599.20
44	LED WITH HEAT SINK - RH	\$ 725.00	\$ 580.00
45	LIGHT CONTROL SYSTEM CONTROL UNIT	\$ 551.00	\$ 440.80
46	HEADLAMP REPAIR KIT	\$ 130.00	
47	HEADLIGHT HOSE - RH	\$ 40.00	
48	LIFT CYLINER	\$ 141.00	\$ 112.40
49	LIFT CYLINDER HOSE	\$ 67.00	
50	FRONT FENDER TOP SUPPORT - RH	\$ 73.00	\$ 58.40
51	LOCK CARRIER	\$ 719.00	\$ 575.20
52	AIRCON CONDENSER	\$ 517.00	
53	TEMPERATURE SENSOR BRACKET	\$ 18.00	
54	READY MIX COOLANT	\$ 91.00	\$ 72.32
55	ADDITIONAL RADIATOR	\$ 859.00	\$ 687.20
56	RADIATOR	\$ 941.00	
57	RADIATOR AIR GUIDE - RH	\$ 24.00	\$ 19.20
58	RADIATOR AIR GUIDE - UPPER CENTRE	\$ 12.00	
59	AIR INTAKE AIR DUCT COVER	\$ 28.00	
60	AIR INTAKE AIR GUIDE	\$ 54.00	
SUB TOTAL SPARE PARTS CHARGES		\$ 11,371.00	\$ 14,734.08

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 1885 P

S/N	Parts Description		Damage Parts & Prices	
			S/Nett	Remarks
		c/f		\$ 14,734.08
61	AIR INTAKE AIR GUIDE		\$ 64.00	
62	AIR INTAKE AIR FILTER		\$ 269.00	
63	AIR INTAKE AIR GUIDE		\$ 19.00	
64	WATER DRAINAGE HOSE		\$ 32.00	
65	WINDOW SLOT SEAL - RH FRONT		\$ 305.00	
66	WATER DEFLECTOR STRIP - RH		\$ 92.00	\$ 72.88
67	CAVITY WAX	S/N	\$ 140.00	\$ 140.00
68	STONE CHIP	S/N	\$ 180.00	\$ 180.00
69	ACRYLIC SEALANT	S/N	\$ 180.00	\$ 180.00
70	FRONT NO PLATE	S/N	\$ 60.00	
71	SUPPLEMENTARY		\$ 496.00	\$ 396.16
72	SUNDRIES		\$ 400.00	\$ 36.32
TOTAL SPARE PARTS CHARGES			: \$ 26,724.00	\$ 15,739.44
TOTAL LABOUR CHARGES			: \$ 19,964.00	\$ 10,999.00
GRAND TOTAL			: \$ 46,688.00	\$ 26,738.44

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0628/2020/NS
Date 12-Sep-20
Service Advisor Glory Tan
Pages 1 of 1
Regn No SLS 1885 P
Model No Audi A3 Sedan 1.0 TFSI 8V

Quantity	Description	Unit Price	Amount
Parts			
1	Aircon refrigerant line (Compressor to cut off point)	\$ 476.00	\$ 380.40
2	Socket for signal horn RHS	\$ 20.00	\$ 15.76
			<u>\$ 396.16</u>
Labours			
1	To renew aircond refrigerant line and to carry out vaccum and regas.	s/n \$ 280.00	\$ 280.00
TOTAL		<u><u>\$ 776.00</u></u>	\$676.16

For Premium Automobiles Pte Ltd

Authorised Signature

