

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 3 Sept 2020

ASSESSMENT FOR REPAIR: HONDA NC750XA - FBN9093A

Chassis No.:
 Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front mudguard	\$345.00 / CRK
1 pc	• Front mudguard brace	\$145.00 ? / BT
1 pc	• Front wheel axle	\$135.00 x SVL
1 pc	• Front brake disk	\$335.00 ?
1 pc	• Front brake ABS disk	SVC X \$235.00 ? / SCR
1 pc	Front brake caliper	SVC X \$395.00 ? / SCR, NEC
2 pcs	• Steering stem bearing	\$90.00 SCR
1 pc	Front right fork assembly	\$1,085.00 SCR / SVL
1 pc	• Front left fork assembly	SVC \$1,085.00 SCR ? X
1 pc	Steering head crown	\$405.00 XSVL
1 pc	• Steering stem underbracket	\$440.00 SCR ? / DEF
1 set	Crash bar	BT / \$395.00 SCR right
1 pc	Brake lever	SCR / \$105.00 SCR
1 pc	Right balancer	\$65.00 / SVL
1 pc	Right view mirror	\$145.00 / SCR
1 pc	• handle bar	\$245.00 SCR ? / DEF
1 pc	Right front signal	\$165.00 / SCR
1 pc	Right body fairing	\$395.00 / SVL
1 pc	Honda wing decal	\$58.00 / NEC
1 set	• Right black cover	\$350.00 ? / CRK
1 pc	• Radiator assembly	\$655.00 ?
1 pc	Brake pedal	\$175.00 / SVL
1 pc	Right front footrest	\$85.00 / SVL
1 pc	Right front footrest holder	\$295.00 XSVL
1 pc	Right rear footrest	\$65.00 / SVL
1 pc	Exhaust heat shield	\$195.00 / SVL
1 pc	Exhaust assembly	\$950.00 / SCR
		\$9,038.00
		\$903.80
		\$8,134.20
	<u>Special nett items</u>	
1 pc	Front sport rim	\$750.00 / DMK
1 pc	• coolant	SVC X \$50.00 ?
1 pc	Box bracket	\$250.00 / DEF
1 pc	Top case	\$480.00 / MIS
1)	• Towing charges	\$100.00 / NN
2)	Replace, reallgn and adjust above damaged parts	\$800.00 300
		450

- Repair left fork
- 3) Repair and balancing front wheel rim
 - 4) • To remove/refit, replace (If damage) check and straighten front fork tubes
 - 5) Reset Meter
 - 6) To knock, straighten chassis & body balancing
 - 7) Spray painting

Total Estimate

~~\$150 X~~

~~\$90.00 40~~

~~\$180.00~~ ~~100~~ ?

~~\$120.00 X NN~~

~~\$450.00 X NN~~

~~\$300.00 100~~

\$11,704.20

Note: The above estimate is subjected to the prevailing GST of 7%

NAL LK

4/9/2020 1200

L/S

3 DAYS

CHECK ITEM PHOTO

AFTER REPAIR PHOTO



For Bike Production Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____