

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Azlan, Syazairdina

Date: 08 Sep 2020

**Preliminary Advice**

Vehicle No	: FBN9093A	Accident Date	: 31/08/2020
Make	: HONDA NC750XA	Policy No.	: 1900265080
Assignment Date	: 03/09/2020	Excess	: S\$750.00
Date of Inspection	: 04/09/2020	Est. Duration of Repair	: 3
Inspection At	: BIKE PRODUCTION (HQ) NO 610 SERANGOON ROAD SINGAPORE 218216		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,236.70
Revised Amount	:S\$	8,947.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,947.20

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	18,000.00
COE / PARF Rebate	:S\$	2,827.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,173.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :