

BIKE PRODUCTION PTE LTD
610, Serangoon Road S(218216)
Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 3 Sept 2020

ASSESSMENT FOR REPAIR: HONDA NC750XA - FBN9093A

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front mudguard	\$345.00
1 pc	Front mudguard brace	\$145.00
1 pc	Front wheel axle	\$135.00
1 pc	Front brake disk	\$335.00
1 pc	Front brake ABS disk	\$235.00
1 pc	Front brake caliper	\$395.00
2 pcs	Steering stem bearing	\$90.00
1 pc	Front right fork assembly	\$1,085.00
1 pc	Front left fork assembly	\$1,085.00
1 pc	Steering head crown	\$405.00
1 pc	Steering stem underbracket	\$440.00
1 set	Crash bar	\$395.00
1 pc	Brake lever	\$105.00
1 pc	Right balancer	\$65.00
1 pc	Right view mirror	\$145.00
1 pc	handle bar	\$245.00
1 pc	Right front signal	\$165.00
1 pc	Right body fairing	\$395.00
1 pc	Honda wing decal	\$58.00
1 set	Right black cover	\$350.00
1 pc	Radiator assembly	\$655.00
1 pc	Brake pedal	\$175.00
1 pc	Right front footrest	\$85.00
1 pc	Right front footrest holder	\$295.00
1 pc	Right rear footrest	\$65.00
1 pc	Exhaust heat shield	\$195.00
1 pc	Exhaust assembly	\$950.00
		<hr/>
		\$9,038.00
	Less discount 10%	\$903.80
		<hr/>
		\$8,134.20
	<u>Special nett items</u>	
1 pc	Front sport rim	\$750.00
1 pc	coolant	\$50.00
1 pc	Box bracket	\$250.00
1 pc	Top case	\$480.00
1)	Towing charges	\$100.00
	Replace, realign and adjust above	
2)	damaged parts	\$800.00

3)	Repair and balancing front wheel rim	\$90.00
4)	To remove/refit, replace (if damage) check and straighten front fork tubes	\$180.00
5)	Reset Meter	\$120.00
6)	To knock, straighten chassis & body balancing	\$450.00
7)	Spray painting	\$300.00
Total Estimate		<u><u>\$11,704.20</u></u>

Note: The above estimate is subjected to the prevailing GST of 7%

For Bike Production Pte Ltd