

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 17 Sep 2020

Preliminary Advice

Vehicle No	: FBN9093A	Accident Date	: 31/08/2020
Make	: HONDA NC750XA	Policy No.	: 1900265080
Assignment Date	: 03/09/2020	Excess	: S\$750.00
Date of Inspection	: 04/09/2020	Est. Duration of Repair	: 3
Inspection At	: BIKE PRODUCTION (HQ) NO 610 SERANGOON ROAD SINGAPORE 218216		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,236.70 (inclusive supp \$ 532.50)
Revised Amount	:S\$	8,199.70 (inclusive supp)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,199.70
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	18,000.00
COE / PARF Rebate	:S\$	2,827.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,173.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Kindly approve on supplementary.