

Not Authorised  
11 Sep @ 3450h

AAD2009-003

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5088D**

02 SEP 2020

**SHC 5088D**

VF1ABL15AUC275910

RENAULT

LATITUDE

1.9.2020

III

27/12/2013

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

	PART
1	BUMPER COVER REAR
1	BUMPER LOWER REAR
1	BUMPER BRACKET CTR REAR
1	BUMPER BRACKET SIDE REAR
1	BUMPER RETAINER REAR
1	BUMPER REFLECTOR REAR
1	BUMPER BEAM REAR
1	BUMPER BEAM BRACKET LH REAR
1	BUMPER BEAM BRACKET RH REAR
1	OUTER PANEL REAR (End Panel)
1	OUTER PANEL REAR (End Panel) TRIM
1	TAIL-LAMP
1	BOOT REAR
1	BOOT FINISHER
1	BOOT WEATHERSTRIP
1	BOOT REFLECTOR LAMP LH
1	BOOT REFLECTOR LAMP RH
1	BOOT BADGE 'RENAULT'
1	BOOT BADGE
1	BOOT HINGE
1	EXHAUST CAP REAR

	LIST	
\$	Bm	561.70 ✓
\$	Pal/Gn	411.90 ✓
\$	Sn	98.10 X
\$	Sn	82.10 X
\$	Sn	59.80 X
\$	Sn	16.60 X
\$	Ry	547.80 ✓
\$	R	114.50 X
\$	R	114.50 X
\$	R	745.80 X
\$	Sn	404.56 X
\$	Sn	401.40 X
\$	Ry	1,677.20 ✓
\$	Sn	344.70 X
\$	Sn	178.20 X
\$	Sn	277.70 X
\$	Sn	277.70 X
\$	R	82.40 ✓
\$	R	95.80 ✓
\$	R	254.20 X
\$	R	125.40 X
<b>TOTAL</b>	<b>\$</b>	<b>6,872.06</b>
<b>10%</b>	<b>\$</b>	<b>687.21</b>
	<b>\$</b>	<b>6,184.85</b>

**Special Nett**

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5088D****AAD2009-003**

1SET PARKING AID	\$	Sm	700.00	X
1SET REAR BUMPER CLIP	\$	nn	75.00	✓
1SET BUMPER BRACKET CTR CLIP	\$	nn	55.00	X
1SET BUMPER RETAINER CLIP RR	\$	nn	60.00	X
1SET BUMPER BRACKET SIDE CLIP RR	\$	nn	65.00	X
1SET BUMPER LOWER REAR RIVET	\$	nn	69.00	X
1SET BUMPER LOWER REAR CLIP	\$	nn	75.00	✓
1 BOOT STICKER "Trans-cab"	\$	nn	80.00	305N
1 BOOT STICKER "6555-3333"	\$	nn	80.00	305N
1SET BOOT FINISHER CLIP	\$	nn	55.00	X
1 TAILLAMP CLIP	\$	nn	40.00	X
1 Rear Bumper Protector	\$	nn	170.00	305N
1 REAR LICENCE PLATE WITH HOLDER	\$	Sm	140.00	X
1 END PANEL TRIM CLIP	\$	nn	55.00	X
<b>TOTAL</b>	<b>\$</b>		<b>1,719.00</b>	

**TOTAL PARTS \$ 7,903.85****LABOUR**

To transfer of bootlid fittings, attachments and perform water seepage test.	\$		170.00	601
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$		250.00	301
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,200.00	4001

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5088D****AAD2009-003**

To reinstall rear bumper parking sensor.

\$ 170.00 60%

To Check Electrical Lighting Concerned.

\$ 170.00 15%

To repair and realign rear exhaust pipe.

\$ 170.00 X

Putty and spray painting of the affected portion.

\$ 1,200.00 440%

**TOTAL \$ 3,880.00****Over All Total \$ 11,783.85****LUMP SUM ( REPAIR DAY)****15 DAYS****2 1/2****For Official Use**Prepared By : \_\_\_\_\_  
(Accident Dept)Verify By : \_\_\_\_\_  
(Accident Workshop)Checked By : \_\_\_\_\_  
(Finance Dept)**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: