



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III20006331/Esf3s2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 04-09-2020



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1042L	Veh. Inspected	SLN 8843R
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT20060114	Excess (\$)	0.00
Assign From	MEKAVATHANAN	Assign Date	12/07/2020

2. Vehicle Particulars & Condition

Make & Model	LEXUS ES300H	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTHBW1GGX02046325	Colour	GREY
Odometer	111865	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	VEURO	4 mm
L/H Front Tyre	225/50 R17	VEURO	4 mm
R/H Rear Tyre	225/50 R17	VEURO	4 mm
L/H Rear Tyre	225/50 R17	VEURO	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/06/2020	Inspection Date	16/06/2020
Survey held at	H S AUTOMOTIVE SERVICES 2 KAKI BUKIT AVE 2 #01-15 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**