



## Section A - Accident Details

Registration Number	SHD6315L
Case Reference Number	TAX/08/20/2078
Registration Date	28/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	YEO SEE HUAN
Type of Accident	Others
Accident Date and Time	29/8/2020 12:30 PM
Accident Reported Date and Time	31/8/2020 11:00 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108016
Special Instruction to ARC, if any	FRONT PORTION
Prepared Date and Time	31/8/2020 12:05 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

## Section B - Summary of Repair Estimates

## Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$300.00
Total Spray Cost	\$1,494.00	\$400.00
Total Spare Part Cost	\$8,441.48	\$2,342.69
Total Other Cost	\$780.00	\$50.00
<b>TOTAL COST</b>	<b>\$11,391.48</b>	<b>\$3,092.69 (P/P)</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / China Taiping
ARC / Surveyor Sign Off Date	03/09/2020 8:33 AM	03/09/2020 8:23 AM
Signature		
Remarks	Total number of repair days = 3 days. SUP = 0 day.	P/P, Before paint photo.

## Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2009-0201	Invoice Number	
Quotation Date	15.09.2020	Invoice Date	
Invoice Amount		Prepared Date	

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$676.00	\$300.00
<b>Total Labour</b>	<b>\$676.00</b>	<b>\$300.00</b>

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO REPSRAY FRONT HOOD	\$378.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,494.00</b>	<b>\$400.00</b>

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
<b>Total Other Costs</b>	<b>\$780.00</b>	<b>\$50.00</b>

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119479 62	COVER, FR BUMPER	1.00	\$495.50	100.00	\$0.00	Replace	Repair
		52127479 07	COVER, FR BUMPER RH	0.00	\$28.10	0.00	\$0.00	Replace	Not Given
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	0.00	\$1.50	0.00	\$0.00	Replace	Not Given
		53112472 40	GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Not Given
		52115470 50	SUPPORT, FR BUMPER RH	0.00	\$76.90	0.00	\$0.00	Replace	Check
		52611471 40	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Check
		52021471 10	REINFORCEMENT FRONT UPPER	0.00	\$691.10	0.00	\$0.00	Replace	Check
		52618470 90	ABSORBER, FR BUMPER LOWER	0.00	\$117.00	0.00	\$0.00	Replace	Check
		52132470 10	REINFORCEMENT FRONT LOWER	0.00	\$238.50	0.00	\$0.00	Replace	Check
		52102470 20	EXTENSION SUBASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Not Given
		81210470 20	LAMP ASSY, FOG, RH	0.00	\$910.20	0.00	\$0.00	Replace	Check
		51420470 30	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Check

# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
60 Woodlands Industrial Park E4, Singapore  
FAX Number : 63685592  
Estimator Telephone Number : 68662623  
Accident Reporting Number : 68662672

Date Generated : 15/09/2020

User ID : PohSuan

	53301471 10	HOOD SUB-ASSY	0.00	\$938.40	0.00	\$0.00	Replace	Not Given X
	53341470 40	INSULATOR, HOOD	0.00	\$393.90	0.00	\$0.00	Replace	Not Given X
	53420471 30	HINGE ASSY, HOOD, LH	0.00	\$57.00	0.00	\$0.00	Replace	Not Given X
	53410471 30	HINGE ASSY, HOOD, RH	0.00	\$57.00	0.00	\$0.00	Replace	Not Given X
	53630470 90	CABLE ASSY, HOOD	0.00	\$53.20	0.00	\$0.00	Replace	Not Given X
	53213470 50	SUPPORT, RADIATOR UPPER RH	0.00	\$76.70	0.00	\$0.00	Replace	Not Given X
	81145476 91	UNIT, HEADLAMP, RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace X
	53801470 80	FENDER SUB-ASSY, FR, RH	1.00	\$933.10	100.00	\$0.00	Replace	Repair 12
	75374471 40	EMBLEM, SIDE PANEL ( HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace X
	53807470 20	SEAL SUB-ASSY, RH	0.00	\$50.20	0.00	\$0.00	Replace	Not Given X
	53875470 70	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Not Given X
	42611- 47450	WHEEL, DISC FRONT	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given X
		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X
	85315471 60	WIPER WASHER JAR	0.00	\$183.60	0.00	\$0.00	Replace	Not Given X
Total				\$10,325.64		\$2,342.69		

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		51420470 30	COVER ASSY, ENGINE	1.00	\$180.10	100.00	\$0.00	Replace	Old Damage X
Total					180.10		0.00		

SVC

2342.69 /  
+ 300.00 /  
+ 450.00 /

3092.69 /

P/P

\$3,092.69

3 days