



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2103223

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 10/05/2021
Reference CC3/CTI20009403/Qpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 6315L
Insured Veh. GBF 1772T
Claim No. SNM20D203196
Policy No. DMCVSNW00049102001
Accident Date 29/08/2020
Inspection Date 31/08/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI20009403/Qpa3q2 Date: 10/05/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 1772T	Veh. Inspected	SHD 6315L	
Policy No.	DMCVSNW00049102001	Coverage (\$)	0.00	
Claim No.	SNM20D203196	Excess (\$)	0.00	
Assign From		Assign Date	31/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS 4	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU003575261	Colour	MAROON	
Odometer	303322 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	SAILUN	6 mm	
L/H Front Tyre	195/65 R15	SAILUN	6 mm	
R/H Rear Tyre	195/65 R15	SAILUN	6 mm	
L/H Rear Tyre	195/65 R15	SAILUN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/08/2020	Inspection Date	31/08/2020	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6315L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	EMBLEM ,SIDE PANEL (HYBRID) (DISC 25%)	NECESSARY	52.90	39.68
1	UNIT ,HEADLAMP ,RH (DISC 10%)	CRACKED	2,558.90	2,303.01
1	COVER ,FR BUMPER RH	SERVICEABLE	28.10	-
1	CLIPS PIECE ,FRT & RR BUMPER	SERVICEABLE	1.50	-
1	GRILLE ,RADIATOR	SERVICEABLE	165.00	-
1	SUPPORT ,FR BUMPER RH	SERVICEABLE	76.90	-
1	ABSORBER ,FR BUMPER	SERVICEABLE	70.30	-
1	REINFORCEMENT FRONT UPPER	SERVICEABLE	691.10	-
1	ABSORBER ,FR BUMPER LOWER	SERVICEABLE	117.00	-
1	REINFORCEMENT FRONT LOWER	SERVICEABLE	238.50	-
1	EXTENSION SUBASSY,RH	SERVICEABLE	116.30	-
1	LAMP ASSY ,FOG ,RH	SERVICEABLE	910.20	-
1	COVER ASSY ,ENGINE	SERVICEABLE	180.10	-
1	HOOD SUB-ASSY	SERVICEABLE	938.40	-
1	INSULATOR HOOD	SERVICEABLE	393.90	-
1	HINGE ASSY ,HOOD ,LH	SERVICEABLE	57.00	-
1	HINGE ASSY ,HOOD ,RH	SERVICEABLE	57.00	-
1	CABLE ASSY ,HOOD	SERVICEABLE	53.20	-
1	SUPPORT RADIATOR UPPER RH	SERVICEABLE	76.70	-
1	SEAL SUB-ASSY ,RH	SERVICEABLE	50.20	-
1	LINER ,FR FENDER RH	SERVICEABLE	198.40	-
1	WHEEL DISC FRONT	SERVICEABLE	1,555.10	-
1	TYRE	SERVICEABLE	126.74	-
1	WIPER WASHER JAR	SERVICEABLE	183.60	-
1	COVER ASSY , HINGE	SERVICEABLE	180.10	-
1	FENDER SUB-ASSY ,FR RH	TO REPAIR SEE LABOUR	933.10	-
1	COVER ,FR BUMPER	TO REPAIR SEE LABOUR	495.50	-
			10,505.74	2,342.69



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF FENDER SUB-ASSY ,FR RH AND COVER ,FR BUMPER .		676.00	300.00
	SPRAY PAINT.		1,494.00	400.00
	TO CHECK WIRING AND SYSTEM FUNCTION .		80.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	30.00
	TO DO WHEEL ALIGNMENT /TYRE BALANCING .	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).	NOT NECESSARY	120.00	-
	TO REMOVE AQND REFIT WIRE HARDESS.	NOT NECESSARY	200.00	-
	TO REPLACE SUNDRY PARTS .	NOT NECESSARY	100.00	-
			2,890.00	750.00
	GRAND TOTAL		13,395.74	3,092.69
RECOMMENDED COST OF REPAIRS				3,092.69

Report Ref No. CC3/CTI20009403/Qpa3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 6315L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 6315L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

