

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE


Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	S1000021 / ICEQI1	Mr Chen Zhi 77 Bodmin Drive Singapore 559676 Mobile: 90289577 <i>117820637-27</i>
	Document No	
	0	
	Document Date	
	03/09/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	ANTMT	E1	ASU60R	23/09/2019	SMP3432D	0	20281 67/TP/SMP3432D
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEZB3GH10J004921	8ARZ162525	30	Sam San Joi	03/09/2020	9.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI SUNDRIES TP CLAIM TP-SLZ2342X ACC DATE:03/09/2020 DRIVE IN:03/09/2020 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				30.00
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON FRT ACCIDENT AREAS				274.77
3	S	BP-SUBLET FRT NUMBER PLATE				80.00
4	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM				122.40
5	Z	BP-SLANT SUPPLY SEALANT (NETT)- FRT SUPPORT PANEL , BONNET				120.00
6	B	BP-LAB2 REMOVE & INSTALL AIRCON CONDENSER ASSY A ND CHARGE UP GAS				360.00
7	B	BP-MECH2 TO CONDUCT ADJUSTMENT ON FRT WAVE RADAR SENSOR				180.00
8	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
9	B	BP-LAB2 REPLACE FRT ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN FRT ACCIDENT AFFECTED AREAS				3600.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	the Repairer of the following:	
	Please acknowledge receipt of vehicle	Parts	• To resurvey before/after spray painting
		Labour	• To display damaged part(s) during resurvey
		Materials	• Parts prices are subject to confirmation
		Lubrication/Fluid	• Third party survey is on a "Without Prejudice" basis
		Others	• No illegal modification(s) is allowed
			• Supplementary item(s) must be resurveyed and
			is subject to final approval from Insurance Company
			Amount Due

Acknowledged by Repairer

Signature:

Date:

PLEASE TEAR ALONG PERFORATED LINE

4221699

4221699

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SMP3432D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	S1000021 / ICEQI1	Mr Chen Zhi 77 Bodmin Drive Singapore 559676 Mobile: 90289577
	Document No	
	Document Date	
	0	
	03/09/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	ANTMT	E1	23/09/2019	SMP3432D	0	20281	67/TP/SMP3432D
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEZB3GH10J004921	8ARZ162525	30	Sam San Joi	03/09/2020	9.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	B	BP-RES2 RESPRAY JOB ON FRT ACCIDENT AFFECTED ARE			1770	3540.00
		AS				
11	1	T52119-4D946 COVER, FR BUMPER	1.00	811.30		811.30
12	2	T52536-48030 RETAINER, FR BUMPER	1.00	115.20		115.20
13	3	T52535-48040 R/FRT BPR RETAINER,	1.00	115.20		115.20
14	4	T75392-42030 RETAINER, OUTSIDE	1.00	11.20		11.20
15	5	L53879-30050 RETAINER, FR FENDER	2.00	16.80		33.60
16	6	L47749-50090 CLIP	2.00	1.80		3.60
17	7	T52614-48050 ABSORBER, FR BUMPER	1.00	112.20		112.20
18	8	T52021-48090 REINFORCEMENT	1.00	521.70		521.70
19	9	T52029-48010 REINFORCEMENT	1.00	301.10		301.10
20	0	T52538-48040 RETAINER, FR BUMPER	1.00	117.40		117.40
21	1	T52537-48040 RETAINER, FR BUMPER	1.00	117.40		117.40
22	2	T52612-48050 ABSORBER, FR BUMPER	1.00	49.80		49.80
23	3	T52611-48210 ABSORBER, FR BUMPER	1.00	49.80		49.80
24	4	T52618-48030 ABSORBER, FR BUMPER	1.00	172.00		172.00
25	5	T52701-48010 MOULDING SUB-ASSY,	1.00	465.60		465.60
26	6	T52411-48050 GUARD, FR BUMPER	1.00	340.20		340.20
27	7	T48691-48040 DAMPER, SUSPENSION	1.00	1343.10		1343.10
28	8	T53102-48081 GRILLE SUB-ASSY,	1.00	417.70		417.70

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4221700

4221700

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/09/2020
TIME 11:34

VEHICLE NO SMP3432D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	S1000021 / ICEQI1	Mr Chen Zhi 77 Bodmin Drive Singapore 559676 Mobile: 90289577
	Document No 0	
	Document Date 03/09/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	ANTMT	E1	ASU60R	23/09/2019	SMP3432D	0	20281 67/TP/SMP3432D
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEZB3GH10J004921	8ARZ162525	30	Sam San Joi	03/09/2020	9.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
29	9	T53286-48090 COVER, FR BUMPER ARM	1.00	38.80		38.80
30	0	T52126-48100 BRACKET, FOG LAMP	1.00	98.20		98.20
31	1	S52161-OK040 CLIPS	10.00	4.10		41.00
32	2	T53101-48920 GRILLE SUB-ASSY,	1.00	1351.40		1351.40
33	3	T53141-48130 GARNISH, RADIATOR	1.00	1673.50		1673.50
34	4	T53301-48170 HOOD SUB-ASSY	1.00	1983.90		1983.90
35	5	T53812-48190 PANEL, FR FENDER, LH	1.00	1446.30		1446.30
36	6	T53876-48120 LINER, FR FENDER, LH	1.00	522.50		522.50
37	7	T90467-07201 CLIPS	10.00	3.50		35.00
38	8	T53510-48260 LOCK ASSY, HOOD	1.00	164.60		164.60
39	9	T53420-48140 HINGE ASSY, HOOD, LH	1.00	87.10		87.10
40	0	T53410-48140 HINGE ASSY, HOOD, RH	1.00	87.10		87.10
41	1	T53208-48091 SUPPORT SUB-ASSY,	1.00	407.30		407.30
42	2	T53205-48030 SUPPORT SUB-ASSY,	1.00	1111.90		1111.90
43	3	T53203-48130 SUPPORT SUB-ASSY,	1.00	176.20		176.20
44	4	T53202-48090 SUPPORT SUB-ASSY,	1.00	216.80		216.80
45	5	T53804-48020 BRACKET SUB-ASSY, FR	1.00	85.00		85.00
46	6	T81185-48E40 UNIT, HEADLAMP	1.00	6714.50		6714.50
47	7	T81145-48E40 UNIT, HEADLAMP	1.00	6714.50		6714.50
48	8	T52134-48070 REINFORCEMENT, FR	1.00	69.80		69.80

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4221701

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 03/09/2020
TIME 11:34

4221701

VEHICLE NO SMP3432D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Inchcape

Borneo Motors



Online Service Booking :

www.toyota.com.sg
Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE


Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail	
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110		S1000021 / ICEQI1	Mr Chen Zhi 77 Bodmin Drive Singapore 559676 Mobile: 90289577	
		Document No		
		0		
		Document Date		
		03/09/2020		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	ANTMT	E1	ASU60R	23/09/2019	SMP3432D	0	20281 67/TP/SMP3432D
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEZB3GH10J004921	8ARZ162525	30	Sam San Joi	03/09/2020	9.00 --/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
49	9	T52133-48060 REINFORCEMENT, FR 11	1.00	69.80		69.80
50	0	T81156-48E30 BRACKET, HEADLAMP, A 11	1.00	31.60		31.60
51	1	T81116-48E30 BRACKET, HEADLAMP, A 11	1.00	31.60		31.60
52	2	T81440-48010 LAMP ASSY, DAYTIME C/A	1.00	907.60		907.60
53	3	T89341-58060 A0 SENSOR, ULTRASONIC, 11	2.00	481.90		963.80
54	4	T89348-58140 A0 RETAINER, ULTRASONIC 11	2.00	21.30		42.60
55	5	T89341-48040 C3 SENSOR, ULTRASONIC, shorts 11	2.00	481.90		963.80
56	6	T89348-58120 RETAINER, ULTRASONIC 11	2.00	16.00		32.00
57	7	T89348-58130 CLIP, ULTRASONIC 11	2.00	12.30		24.60
58	8	S08889-80102 COOLANT, SLLC&&& 11	1.00	79.50		79.50

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	39,661.87
	Please acknowledge receipt of vehicle	Parts	31,174.70	GST 7.00% 2,776.33
		Labour	8,132.40	
		Materials	354.77	
		Lubrication/Fluid	0.00	
		Others	0.00	
			Less	0.00
			Amount Due	42,438.20

PLEASE TEAR ALONG PERFORATED LINE

4221702

4221702

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/09/2020

TIME 11:34

40,852.97#

VEHICLE NO SMP3432D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors