

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CC4/EP120009409/Ug93

ASSIGNMENT

From:

Date:

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SM73432D

at Workshop m/s

Borneo ub,

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

€123k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

1.31

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Sam 98476209

Vehicle: IN / OUT

Veh No:

SM73432D

Yr Regn:

*9.19*Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CAI

Make:

*Toyota harrier**M Grade*

C.C.

1998

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

32005

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235/55 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

mm

L/Bal.

mm

D.O.A.

3/9/20

Rear

R/Bal.

mm

L/Bal.

mm

D.O.I.

4/9/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*Videos at folder 47A58926
rep 12k. 9 yrt. net 64074**25/9/20 confirmed final by 20637.27 with Sam.*

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) __ S + RS, __ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Online Service Booking :
www.toyota.com.sg
Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail	
BQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110		S1000021 / ICEQI1	Mr Chen Zhi 77 Bodmin Drive Singapore 559676 Mobile: 90289577 <i>11/2820637-27</i>	
		Document No		
		0		
		Document Date		
		03/09/2020		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	ANTMT E1	ASU60R	23/09/2019	SMP3432D	0	20281	67/TP/SMP3432D
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEZB3GH10J004921	8ARZ162525	30	Sam San Joi	03/09/2020	9.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI SUNDRIES TP CLAIM TP-SLZ2342X ACC DATE:03/09/2020 DRIVE IN:03/09/2020 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				30.00
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON FRT ACCIDENT AREAS				274.77
3	S	BP-SUBLET FRT NUMBER PLATE				80.00
4	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM				122.40
5	Z	BP-SLANT SUPPLY SEALANT (NETT)- FRT SUPPORT PANEL , BONNET				120.00
6	B	BP-LAB2 REMOVE & INSTALL AIRCON CONDENSER ASSY A ND CHARGE UP GAS				360.00
7	B	BP-MECH2 TO CONDUCT ADJUSTMENT ON FRT WAVE RADAR SENSOR				180.00
8	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
9	B	BP-LAB2 REPLACE FRT ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN FRT ACCIDENT AFFECTED AREAS				3600.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Parts	Acknowledged by Repairer Signature: _____ Date: _____
	Please acknowledge receipt of vehicle	Labour	
		Materials	
		Lubrication/Fluid	
		Others	

the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company
Amount Due

PLEASE TEAR ALONG PERFORMED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/09/2020
TIME 11:34

VEHICLE NO SMP3432D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

4221699

4221699



Online Service Booking :
www.toyota.com.sg
Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No S1000021 / ICEQI1	Customer Detail
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	Document No 0	Mr Chen Zhi 77 Bodmin Drive Singapore 559676 Mobile: 90289577
	Document Date 03/09/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	ANTMT	E1	ASU60R	23/09/2019	SMP3432D	0	20281 67/TP/SMP3432D
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEZB3GH10J004921	8ARZ162525	30	Sam San Joi	03/09/2020	9.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	B	BP-RES2 RESPRAY JOB ON FRT ACCIDENT AFFECTED ARE				1770 3540.00
		AS				
11	1	T52119-4D946 COVER, FR BUMPER	1.00	811.30		811.30
12	2	T52536-48030 RETAINER, FR BUMPER	1.00	115.20		115.20
13	3	T52535-48040 R/FRT BPR RETAINER,	1.00	115.20		115.20
14	4	T75392-42030 RETAINER, OUTSIDE	1.00	11.20		11.20
15	5	L53879-30050 RETAINER, FR FENDER	2.00	16.80		33.60
16	6	L47749-50090 CLIP	2.00	1.80		3.60
17	7	T52614-48050 ABSORBER, FR BUMPER	1.00	112.20		112.20
18	8	T52021-48090 REINFORCEMENT	1.00	521.70		521.70
19	9	T52029-48010 REINFORCEMENT	1.00	301.10		301.10
20	0	T52538-48040 RETAINER, FR BUMPER	1.00	117.40		117.40
21	1	T52537-48040 RETAINER, FR BUMPER SVC	1.00	117.40		117.40
22	2	T52612-48050 ABSORBER, FR BUMPER	1.00	49.80		49.80
23	3	T52611-48210 ABSORBER, FR BUMPER	1.00	49.80		49.80
24	4	T52618-48030 ABSORBER, FR BUMPER	1.00	172.00		172.00
25	5	T52701-48010 MOULDING SUB-ASSY,	1.00	465.60		465.60
26	6	T52411-48050 GUARD, FR BUMPER	1.00	340.20		340.20
27	7	T48691-48040 DAMPER, SUSPENSION	1.00	1343.10		1343.10
28	8	T53102-48081 GRILLE SUB-ASSY,	1.00	417.70		417.70

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4221700

TO SECURITY GUARD

4221700

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/09/2020
TIME 11:34

VEHICLE NO SMP3432D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail				
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110		S1000021 / ICEQI1	Mr Chen Zhi 77 Bodmin Drive Singapore 559676 Mobile: 90289577				
		Document No			0		
		Document Date			03/09/2020		
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	ANTMT E1	ASU60R	23/09/2019	SMP3432D	0	20281	67/TP/SMP3432D
Chassis No		Engine No	Terms	Service Engineer	Vehicle In	Collected On	
JTEZB3GH10J004921		8ARZ162525	30	Sam San Joi	03/09/2020	9.00	--/--/---- 0.00
L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
29	9	T53286-48090	COVER, FR BUMPER ARM	1.00	38.80		38.80
30	0	T52126-48100	BRACKET, FOG LAMP	1.00	98.20		98.20
31	1	S52161-0K040	CLIPS	10.00	4.10		41.00
32	2	T53101-48920	GRILLE SUB-ASSY,	1.00	1351.40		1351.40
33	3	T53141-48130	GARNISH, RADIATOR	1.00	1673.50		1673.50
34	4	T53301-48170	HOOD SUB-ASSY	1.00	1983.90		1983.90
35	5	T53812-48190	PANEL, FR FENDER, LH	1.00	1446.30		1446.30
36	6	T53876-48120	LINER, FR FENDER, LH	1.00	522.50		522.50
37	7	T90467-07201	CLIPS	10.00	3.50		35.00
38	8	T53510-48260	LOCK ASSY, HOOD	1.00	164.60		164.60
39	9	T53420-48140	HINGE ASSY, HOOD, LH	1.00	87.10		87.10
40	0	T53410-48140	HINGE ASSY, HOOD, RH	1.00	87.10		87.10
41	1	T53208-48091	SUPPORT SUB-ASSY,	1.00	407.30		407.30
42	2	T53205-48030	SUPPORT SUB-ASSY,	1.00	1111.90		1111.90
43	3	T53203-48130	SUPPORT SUB-ASSY,	1.00	176.20		176.20
44	4	T53202-48090	SUPPORT SUB-ASSY,	1.00	216.80		216.80
45	5	T53804-48020	BRACKET SUB-ASSY, FR	1.00	85.00		85.00
46	6	T81185-48E40	UNIT, HEADLAMP	1.00	6714.50		6714.50
47	7	T81145-48E40	UNIT, HEADLAMP	1.00	6714.50		6714.50
48	8	T52134-48070	REINFORCEMENT, FR	1.00	69.80		69.80
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.							
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total	
		Please acknowledge receipt of vehicle		Parts		Less	
				Labour			
				Materials			
				Lubrication/Fluid			
				Others		Amount Due	

PLEASE TEAR ALONG PERFORATED LINE

4221701

TO SECURITY GUARD

4221701

 PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

 DATE 03/09/2020
 TIME 11:34

 VEHICLE NO **SMP3432D**

CUSTOMER

 SIGNATURE
 FOR **BORNEO MOTORS (SINGAPORE) PTE LTD**

Borneo Motors

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9
ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail BQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	Account No	Customer Detail Mr Chen Zhi 77 Bodmin Drive Singapore 559676 Mobile: 90289577
	S1000021 / ICEQI1	
	Document No	
	0	
	Document Date	
	03/09/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	ANTMT	E1	ASU60R	23/09/2019	SMP3432D	0	20281 67/TP/SMP3432D
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEZB3GH10J004921	8ARZ162525	30	Sam San Joi	03/09/2020	9.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
49	9	T52133-48060 REINFORCEMENT, FR	1.00	69.80		69.80
50	0	T81156-48E30 BRACKET, HEADLAMP, A	1.00	31.60		31.60
51	1	T81116-48E30 BRACKET, HEADLAMP, A	1.00	31.60		31.60
52	2	T81440-48010 LAMP ASSY, DAYTIME	1.00	907.60		907.60
53	3	T89341-58060 AO SENSOR, ULTRASONIC,	2.00	481.90		963.80
54	4	T89348-58140 AO RETAINER, ULTRASONIC	2.00	21.30		42.60
55	5	T89341-48040 C3 SENSOR, ULTRASONIC,	2.00	481.90		963.80
56	6	T89348-58120 RETAINER, ULTRASONIC	2.00	16.00		32.00
57	7	T89348-58130 CLIP, ULTRASONIC	2.00	12.30		24.60
58	8	S08889-80102 COOLANT, SLLC&&&	1.00	79.50		79.50

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature Please acknowledge receipt of vehicle	Change Summary Parts 31,174.70 Labour 8,132.40 Materials 354.77 Lubrication/Fluid 0.00 Others 0.00	Total	39,661.87
			GST 7.00%	2,776.33
			Less	0.00
			Amount Due	42,438.20

PLEASE TEAR ALONG PERFORATED LINE

4221702

4221702

TO SECURITY GUARD

 PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

 DATE 03/09/2020
 TIME 11:34

VEHICLE NO SMP3432D

CUSTOMER

 SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD
**Borneo Motors**

TAX INVOICE

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110

S1000021 /ICEQI1

39011049

17/09/2020

Mr Chen Zhi
77 Bodmin Drive
Singapore 559676
Mobile: 90289577

19 ANTMT E1 ASU60R 23/09/2019 SMP3432D 26624 20281 67/TP/SMP3432D

JTEZB3GH10J004921 8ARZ162525 30 Sam San Joi 03/09/2020 11.10 17/09/2020 8.52

32	4	T52618-48030	ABSORBER, FR BUMPER,	1.00	172.00	172.00
33	5	T52411-48050	GUARD, FR BUMPER +	1.00	340.20	340.20
34	6	T52126-48100	BRACKET, FOG LAMP +	1.00	98.20	98.20
35	7	T81185-48E40	UNIT, HEADLAMP LH	1.00	6714.50	6714.50
36	8	T81440-48010	LAMP ASSY, DAYTIME LH	1.00	907.60	907.60
37	9	T16683-36100	PLATE, RADIATOR LWR	1.00	121.90	121.90
38	0	T16695-36140	PLATE, RADIATOR SIDE	1.00	53.70	53.70
39	1	T16697-36070	PLATE, RADIATOR SIDE	1.00	90.90	90.90
40	2	L81220-48051	LAMP ASSY, FOG LH	1.00	516.00	516.00
41	3	T48696-48020	BRACKET, TOWER BAR,	1.00	312.90	312.90

sent
sent
sent
sent
sent

supp

20,637.27

15,840.10 GST 7.00% 1,444.61

4,442.40

354.77

0.00

0.00

22,081.88

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128462

17/09/2020
08:52

SMP3432D

TAX INVOICE

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110

S1000021 /ICEQI1

39011049

17/09/2020

Mr Chen Zhi
77 Bodmin Drive
Singapore 559676
Mobile: 90289577

19	ANTMT E1	ASU60R	23/09/2019	SMP3432D	26624	20281	67/TP/SMP3432D
JTEZB3GH10J004921	8ARZ162525	30	Sam San Joi	03/09/2020	11.10	17/09/2020	8.52
1	Z	BP-SUNDRY-AI SUNDRIES	TP CLAIM				30.00
		TP-SLZ2342X	ACC DATE:03/09/2020				
		DRIVE IN:03/09/2020					
		DATE-IN:04/09/2020	DATE SURVEY:04/09/2020				
		NO OF REPAIR DAYS:6 DAYS					
		BY:MARCUS CHUA (LKK)					
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE	0619				274.77
		PER PANEL APPLICATION ON FRT ACCIDENT AREAS					
3	S	BP-SUBLET FRT NUMBER PLATE	0263				80.00
4	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM	*				122.40
5	B	BP-MECH2 TO CONDUCT ADJUSTMENT ON FRT WAVE RADAR	*				180.00
		SENSOR					
6	B	BP-ECU2 TO RESET ECU AND REPROGRAMME	*				180.00
7	B	BP-LAB2 REPLACE FRT ACCIDENT DAMAGED PARTS	*				2160.00
		STRAIGHTEN & ALIGN FRT ACCIDENT AFFECTED AREAS					
8	B	BP-RES2 RESPRAY JOB ON FRT ACCIDENT AFFECTED ARE	*				1770.00
		AS					
9	1	T52119-4D946 COVER, FR BUMPER	1.00	811.30			811.30
10	2	T52536-48030 RETAINER, FR BUMPER	1.00	115.20			115.20
11	3	T52535-48040 RETAINER, FR BUMPER	1.00	115.20			115.20

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128462

17/09/2020
08:52

SMP3432D

TAX INVOICE

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110

S1000021 /ICEQI1

39011049

17/09/2020

Mr Chen Zhi
77 Bodmin Drive
Singapore 559676

Mobile: 90289577

19 ANTMT E1 ASU60R 23/09/2019 SMP3432D 26624 20281 67/TP/SMP3432D

JTEZB3GH10J004921 8ARZ162525 30 Sam San Joi 03/09/2020 11.10 17/09/2020 8.52

12	4	T75392-42030	RETAINER, OUTSIDE	1.00	11.20	11.20
13	5	L53879-30050	RETAINER, FR FENDER	2.00	16.80	33.60
14	6	L47749-50090	CLIP, PIN HOLD	2.00	1.80	3.60
15	7	T53102-48081	GRILLE SUB-ASSY,	1.00	417.70	417.70
16	8	T53286-48090	COVER, FR BUMPER ARM	1.00	38.80	38.80
17	9	S52161-0K040	PIECE,RR BUMPER	10.00	4.10	41.00
18	0	T53101-48920	GRILLE SUB-ASSY,	1.00	1351.40	1351.40
19	1	T53141-48130	GARNISH, RADIATOR	1.00	1673.50	1673.50
20	2	T90467-07201	CLIP	10.00	3.50	35.00
21	3	T53420-48140	HINGE ASSY, HOOD, LH	1.00	87.10	87.10
22	4	T53410-48140	HINGE ASSY, HOOD, RH	1.00	87.10	87.10
23	5	L89341-48040 C3	SENSOR, ULTRASONIC,	1.00	481.90	481.90
24	6	T89348-58120	RETAINER, ULTRASONIC	2.00	16.00	32.00
25	7	L89348-58130	CLIP, ULTRASONIC	2.00	12.30	24.60
26	8	T52614-48050	ABSORBER, FR BUMPER	1.00	112.20	112.20
27	9	T52021-48090	REINFORCEMENT	1.00	521.70	521.70
28	0	T52029-48010	REINFORCEMENT	1.00	301.10	301.10
29	1	T52538-48040	RETAINER, FR BUMPER	1.00	117.40	117.40
30	2	T52612-48050	ABSORBER, FR BUMPER	1.00	49.80	49.80
31	3	T52611-48210	ABSORBER, FR BUMPER	1.00	49.80	49.80

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128462

17/09/2020
08:52

SMP3432D