



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2006819
INV Date 02/10/2020
Reference CC4/FCI20009412/R1da3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. GBF 2988G
Insured Veh. SHD 3309A
Claim No. D20003507MFSH/1
Policy No. D-20094922MFSH
Accident Date 01/09/2020
Inspection Date 04/09/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20009412/R1da3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-10-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3309A	Veh. Inspected	GBF 2988G	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20003507MFSH/1	Excess (\$)	0.00	
Assign From	VIC	Assign Date	03/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI CANTER FEA01	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	FEA01BA20303	Colour	RED	
Odometer	129252	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	AUSTONE	6 mm	
L/H Front Tyre	195 R15C	AUSTONE	6 mm	
R/H Rear Tyre	195 R15C	AUSTONE	6 mm	
L/H Rear Tyre	195 R15C	AUSTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/09/2020	Inspection Date	04/09/2020	
Survey held at	VENDA ENGINEERING & TRADING PTE LTD 174 WESTWOOD CRESCENT WESTVILLE SINGAPORE 648541			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 2988G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>	CUT		
	REAR RIGHT OUTER TYRE (70%)(SN)		240.00	168.00
			240.00	168.00
	<u>LABOUR</u>	NOT NECESSARY		
	REMOVE & RENEW TYRES.		50.00	30.00
	TOWING FEES.		100.00	-
			150.00	30.00
GRAND TOTAL			390.00	198.00

RECOMMENDED COST OF REPAIRS			198.00
------------------------------------	--	--	---------------

Report Ref No. CC4/FCI20009412/R1da3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 2988G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 2988G

RE-INSPECTION

