

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20009418/EEA3Q2**Date:** 04/03/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	FBN799G	Insured Vehicle No :	SHC2012S
Date of Loss:	31/08/2020	Nature of Claim:	TP
		Claim No:	MCT20080491

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN799G	Engine No:	H336E0031911
Make & Model:	YAMAHA CZD300A / XMAX300, 292cc	Chassis No:	MH3SH0842JK003918
Reg. Date:	28/06/2018 (Man. Year: 2018)	Odometer:	74744 km
Colour:	Brown		
Engine Capacity:	292 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70-14	Rear Tyre Size:	140/70-14
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,228.70	2,381.30	4,847.40	67.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	480.00	800.00	62.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,508.70	2,861.30	5,647.40	66.37
Approved Total (Overridden) (S\$)		2,300.00		
(S\$)	8,508.70	2,300.00	6,208.70	72.97
+ GST 7.00/7.00% (S\$)	595.61	161.00	434.61	72.97
Nett Amount (S\$)	9,104.31	2,461.00	6,643.31	72.97
+ Loss of Use (4.0 x S\$30.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		2,588.49		

INSPECTION

Date of Assignment:	03/09/2020	
Date Inspected:	03/09/2020	Inspected At: My Car Consultant Pte Ltd - Ubi (HQ) 53 Ubi Ave 1, #01-33 Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 Aug 2021)	
Parts:	N/A	YAMAHA CZD300A / XMAX300 292cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN799G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET FRONT HANDLE	Bent	898.00 FL	*165.00 FL
2	1		*FRONT HANDLE GRIP LH	Not Necessary	65.00 FL	*- FL
3	1		*FRONT HANDLE LEVER LH	Cut	85.00 FL	*85.00 FL
4	1		*FRONT HANDLE BALANCER LH	Cut	79.00 FL	*60.00 FL
5	1		*FRONT FAIRING GARNISH LH	Cut	387.00 FL	*250.00 FL
6	1		*SET FRONT SIDE MIRROR LH	Cut	254.00 FL	*90.00 FL
7	1		*FRONT WHEEL LOCK NUT LH	Cut	12.00 FL	*12.00 FL
8	1		*FRONT MUDGUARD	Cut	212.00 FL	*145.00 FL
9	1		*FRONT FORK SIDE GARNISH LH	Not Necessary	125.00 FL	*- FL
10	1		*HEADLAMP LH	Not Necessary	336.00 FL	*- FL
11	1		*REAR MUDGUARD	Cut	321.00 FL	*321.00 FL
12	1		*REAR TAILAMP GARNISH	Not Necessary	258.00 FL	*- FL
13	1		*SET TAILAMP	Not Necessary	412.00 FL	*- FL
14	1		*REAR SIDE ENGINE COVER LH	Cut	358.00 FL	*156.00 FL
15	1		*REAR SEAT LOWER GARNISH LH	Cut	287.00 FL	*287.00 FL
16	1		*RIDER SEAT	Not Necessary	417.00 FL	*- FL
17	1		*SET REAR SHOCK ABSORBER	Not Necessary	574.00 FL	*- FL
18	1		*RIDER STEP BOARD LH	Cut	398.00 FL	*220.00 FL
19	1		*RIDER STEP BOARD GARNISH LH	Cut	198.00 FL	*198.00 FL
20	1		*REAR NUMBER PLATE LAMP	Not Necessary	45.00 FL	*- FL
21	1		*PILLION FOOT REST LH	Cut	68.00 FL	*68.00 FL
22	1		*EXHAUST SILENCER HEAT SHIELD	Not Necessary	159.00 FL	*- FL
23	1		*EXHAUST SILENCER	Not Necessary	798.00 FL	*- FL
24	1		*REAR NUMBER PLATE	Bent	50.00 FS	*30.00 FS
25	1		*REAR NUMBER PLATE BRACKET	Not Necessary	150.00 FS	*- FS
26	1		*REAR BOX	Cut	350.00 FS	*300.00 FS
27	1		*REAR BOX BRACKET	Cut	120.00 FS	*120.00 FS
28	1		*SET FAIRING STICKER	Necessary	150.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,566.00	2,587.00
- List Item Discount on L Items 5.00/10.00% (\$\$)	337.30	205.70
Total Parts (\$\$)	7,228.70	2,381.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL WIRING	New	80.00	30.00
2	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	0.00
3	SPRAY PAINTING ON AFFECTED AREAS	New	500.00	200.00
4	PANEL BEATING ON AFFECTED AREAS	New	500.00	250.00
Gross Labour Cost (\$\$)			1,280.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >