



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date: 9/3/2020

Vehicle: *FBN 7996* YAMAHA CZD300A

Make / Model: PIAGGIO Yamaha XMAX

Chassis No:

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	FRONT HANDLE SET (<i>Bar</i>) / <i>BT</i>	1	\$ 898.00	\$ 898.00
2	FRONT HANDLE GRIP LH <i>X NM</i>	1	\$ 65.00	\$ 65.00
3	FRONT HANDLE LEVER LH / <i>CUT</i>	1	\$ 85.00	\$ 85.00
4	FRONT HANDLE BALANCER <i>RH LH</i> / <i>CUT</i>	1	\$ 79.00	\$ 79.00
5	FRONT FAIRING GARNISH LH / <i>CUT</i>	1	\$ 387.00	\$ 387.00
6	FRONT SIDE MIRROR LH SET / <i>CUT</i>	1	\$ 254.00	\$ 254.00
7	FRONT WHEEL LOCK NUT LH / <i>CUT</i>	1	\$ 12.00	\$ 12.00
8	FRONT MUDGUARD (<i>failing</i>) / <i>CUT</i>	1	\$ 212.00	\$ 212.00
9	FRONT FORK SIDE GARNISH LH <i>X NM</i>	1	\$ 125.00	\$ 125.00
10	HEADLAMP LH <i>X NM</i>	1	\$ 336.00	\$ 336.00
11	REAR MUDGUARD / <i>CUT</i>	1	\$ 321.00	\$ 321.00
12	REAR TAILAMP GARNISH <i>X NM</i>	1	\$ 258.00	\$ 258.00
13	TAILAMP SET <i>X NM</i>	1	\$ 412.00	\$ 412.00
14	REAR SIDE ENGINE COVER LH / <i>CUT</i>	1	\$ 358.00	\$ 358.00
15	REAR SEAT LOWER GARNISH LH / <i>CUT</i>	1	\$ 287.00	\$ 287.00
16	RIDER SEAT <i>X NM</i>	1	\$ 417.00	\$ 417.00
17	REAR SHOCK ABSORBER SET <i>X NM</i>	1	\$ 287.00	\$ 574.00
18	RIDER STEP BOARD LH / <i>CUT</i>	1	\$ 398.00	\$ 398.00
19	RIDER STEP BOARD GARNISH LH / <i>CUT</i>	1	\$ 198.00	\$ 198.00
20	REAR NUMBER PLATE LAMP <i>X NM</i>	1	\$ 45.00	\$ 45.00
21	PILLION FOOT REST LH / <i>CUT</i>	1	\$ 68.00	\$ 68.00
22	EXHAUST SILENCER HEAT SHIELD <i>X NM</i>	1	\$ 159.00	\$ 159.00
23	EXHAUST SILENCER <i>X NM</i>	1	\$ 798.00	\$ 798.00
			10%	\$ 6,746.00
			Less 5%	\$ 337.30
			Total	\$ 6,408.70
S/Nett items:				
1	REAR NUMBER PLATE / <i>BT</i>	1	\$ 50.00	\$ 50.00
2	REAR NUMBER PLATE BRACKET <i>X NM</i>	1	\$ 150.00	\$ 150.00
3	REAR BOX / <i>CUT</i>	1	\$ 350.00	\$ 350.00
4	REAR BOX BRACKET / <i>CUT</i>	1	\$ 120.00	\$ 120.00
5	FAIRING STICKER SET / <i>PEC</i>	1	\$ 150.00	\$ 150.00
				\$ 820.00
Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
3	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00

165 /

X

/

60 /

250 /

90 /

/

145 /

X

X

/

X

156 /

/

X

X

220 /

/

X

/

X

X

2057

-10%

1851.30 /

30 /

X

300 /

/

80 /

530 /

30 /

X

4	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 500.00	\$ 500.00
5	PANEL BEATING ON AFFECTED AREAS	1	\$ 500.00	\$ 500.00
				\$ 1,280.00
			Parts Replacement Amount	\$ 7,228.70
			Total Amount for Labour	\$ 1,280.00
			Total Amount	\$ 8,508.70

209

250

480 ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve (LKK)

3/9/20, 3.00 pm

WHL PrijuL

3 days

L/S

Ry AL spy

P- 1851.30

NI- 530

L- 480

2861.30

L/S- 2289-94

= 2300