



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:PETER			Ref: CC4/ASM20009419/Bga3q2 Date: 09/02/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMG 1118Y	Veh. Inspected	SJR 8952L	
Policy No.	GA366178/1	Coverage (\$)	0.00	
Claim No.	S0M02T60	Excess (\$)	0.00	
Assign From		Assign Date	03/09/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	SUZUKI SWIFT	c.c	1586	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JSAEZC31S00204388	Colour	WHITE	
Odometer	190345 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	POOR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	BRIDGESTONE	5 mm	
L/H Front Tyre	195/55 R15	BRIDGESTONE	5 mm	
R/H Rear Tyre	195/55 R15	KAPSEN	5 mm	
L/H Rear Tyre	195/55 R15	KAPSEN	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	02/09/2020	Inspection Date	03/09/2020	
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>10 Working Days</b>	