

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Sep 2020)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHD4849B/03/09/2020 11:26

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY	20.00	0.00	de - *499.40 F
2	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	de - *451.25 F
3	1		*REVERSE SENSOR	0.00	0.00	Xing *135.70 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,086.35
- List Item Discount on L Items (\$\$)	190.13
Total Parts (\$\$)	896.22

ComfortDelGro Engineering Pte Ltd/SHD4849B/03/09/2020 11:26. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

760.52.

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1		OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	320 400.00
2	SPRAYPAINT	New	200 300.00
3	REMOVE/REFIX REVERSE SENSOR	New	30 80.00
Gross Labour Cost (S\$)			550 780.00

ComfortDelGro Engineering Pte Ltd/SHD4849B/03/09/2020 11:26. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tougher 974957A
WP 3/9/20 04pm

2 days

p/p heavy before paint

for fairlie (handover)

Duration -

760.52

11

550

\$1321.52

2 days. #

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: