

REPAIR DETAILS

Reference

Part Source: (Last Synchronised 03 Sep 2020)
 Parts: N/A MITSUBISHI FUSO 12 0 D FV51SS3VDEA (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Kan Fook Sing Motor Workshop/XE7767P/03/09/2020 17:12
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET / DD ? X NN	0.00	0.00	*2,250.00 F ✓
2	1		*FRONT BONNET LOCK RH / ? X NN	0.00	0.00	*90.00 F X
3	1		*FRONT BONNET LOCK LH / X NN	0.00	0.00	*90.00 F X
4	1		*FRONT BONNET FUSO EMBLEM / MC	0.00	0.00	*120.00 F ✓
5	1		*FRONT GRILLE TOP / DR	0.00	0.00	*300.00 F ✓
6	1		*FRONT GRILLE LOWER / DR	0.00	0.00	*350.00 F ✓
7	1		*FRONT GRILLE EMBLEM / MC	0.00	0.00	*65.00 F ✓
8	1		*FRONT GRILLE SUPER GREAT EMBLEM / MC	0.00	0.00	*85.00 F ✓
9	1		*FRONT CORNER PANEL RH / ? X NN	0.00	0.00	*650.00 F X
10	1		*FRONT CORNER PANEL LH / ? X NN	0.00	0.00	*650.00 F X
11	1		*FRONT BUMPER / DD (upper)	0.00	0.00	*185.00 F ✓
12	1		*FRONT BUMPER TOP RH / DR	0.00	0.00	*140.00 F ✓
13	1		*FRONT BUMPER TOP LH / DT	0.00	0.00	*140.00 F ✓
14	1		*FRONT BUMPER (lower) / DT	0.00	0.00	*1,500.00 F ✓
15	1		*FRONT BUMPER LOWER PANEL RH / DR	0.00	0.00	*150.00 F ✓
16	1		*FRONT BUMPER LOWER PANEL LH / M/I	0.00	0.00	*150.00 F ✓
17	1		*FRONT BUMPER REINFORCEMENT / XXXXNN ✓	0.00	0.00	*840.00 F X ✓ BT
18	1		*FRONT BUMPER BRACKET RH / XXXXNN ✓	0.00	0.00	*98.00 F X ✓ BT
19	1		*FRONT BUMPER BRACKET LH / XXXXNN ✓	0.00	0.00	*98.00 F X ✓ BT
20	1		*FRONT BUMPER CENTRE GARNISH / (CUT) ✓	0.00	0.00	*120.00 F ✓
21	1		*FRONT BUMPER LAMP RH / ? CUT	0.00	0.00	*185.00 F ✓
22	1		*FRONT BUMPER LAMP LH / ? CUT	0.00	0.00	*185.00 F ✓
23	1		*FRONT BUMPER LAMP RIM RH / CR4 DR	0.00	0.00	*90.00 F ✓
24	1		*FRONT BUMPER LAMP RIM LH / ? CUT (no photo)	0.00	0.00	*90.00 F ✓
25	1		*FRONT HEADLAMP RH / XXXXXXXXNN (no photo)	0.00	0.00	*650.00 F X ✓ CRA
26	1		*FRONT HEADLAMP LH / ? CUT	0.00	0.00	*650.00 F ✓
27	1		*FRONT HEADLAMP RIM RH / CR4	0.00	0.00	*95.00 F ✓
28	1		*FRONT HEADLAMP RIM LH / ? CR CUT	0.00	0.00	*95.00 F ✓
29	1		*AIR CON CONDENSER X NN	0.00	0.00	*1,190.00 F X

F=Franchise part.

Sub Total (S\$) 11,301.00
 + Margin on L,N Items 15.00% (S\$) 1,695.15
 Total Parts (S\$) 12,996.15

Kan Fook Sing Motor Workshop/XE7767P/03/09/2020 17:12 Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

6945 7595
 + 15%
 7986.75

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT NUMBER PLATE / 117	30.00 /
Sub Total (S\$)			30.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New 700	820.00
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New	30.00 /
3	TO REMOVE/REFIT/REFILL AIR CON GAS	New	80.00 X
4	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New 600	900.00
Gross Labour Cost (S\$)			1,830.00

Kan Fook Sing Motor Workshop/XE7767P/03/09/2020 17:12. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK)

OD - Not Authorize

EX PER - \$1000

L/S

Ry At 11

4/9/20, 2.00pm

5 days

P- 7986.75

N- 30

L- 1330

9346.75

Supp- 2041.25

= 11,388.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: