

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

Fax : 64816131

L H Car Rental Pte Ltd
Blk 5038 #01-405
Ang Mo Kio Industrial Pk 2
Singapore 569541

Vehicle No : SML 7837 P
Make : Toyota Voxy
Year : 2019

Not Authorized
LI Sup @ 5050h
Resony Aka Paint

5 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy	<i>1712.85</i>	<i>Bu</i> \$1,825.60 ✓
1 pc	Rear tail-gate emblem " Hybrid "		<i>mm</i> \$75.20 ✓
1 pc	Rear tail-gate outer chrome handle	<i>photo</i>	<i>mm</i> \$407.10 ✓
1 pc	Rear tail-gate inner lock		<i>mm</i> \$325.60 ✓
1 pc	Rear tail-gate inner trim board	<i>371.75</i>	<i>Bu</i> \$525.60 ✓
1 pc	Rear tail-gate glass moulding		<i>mm</i> \$187.30 ✓
1 pc	Rear boot rubber		<i>mm</i> \$265.70 ✓
1 pc	Rear end panel	<i>photo</i>	<i>Bu</i> \$550.90 ✓
1 pc	Rear end panel garnish		<i>mm</i> \$197.30 ✓
1 pc	Rear bumper		<i>Bu</i> \$1,120.30 ✓
2 pcs	Rear bumper bracket	<i>x</i>	<i>R</i> \$125.00 \$251.20 <i>x</i>
2 pcs	Rear bumper side retainer	<i>x</i>	<i>mm</i> \$135.10 \$270.20 <i>x</i>
2 pcs	Rear bumper reflector	<i>x</i>	<i>mm</i> \$135.20 \$270.40 <i>x</i>
2 pcs	Rear fender inner trim board	<i>rlh photo</i>	<i>Bu</i> \$685.10 \$1,370.20 <i>708x</i>
1 pc	Rear boot floor panel top cover		<i>mm</i> \$552.70 ✓
1 pc	Rear antenna	<i>185.70 - photo</i>	<i>mm</i> \$8,195.30
1 pc	Rear inner lock sensor	<i>197.10 - photo</i>	Less 25 % \$2,048.83
S Nett			<i>mm</i> \$6,146.47
1 set	Rear reverse sensor	<i>7101.20</i>	<i>mm</i> \$200.00 ✓
20 pcs	Bumper clip	<i>50% 1778.30</i>	<i>mm</i> \$50.00 ✓
1 pc	Rear tail-gate glass sealant	<i>5325.90</i>	<i>mm</i> \$40.00 ✓
			\$290.00

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,200.00 *600*

To putty & spray paint rear accident affected portion.

\$1,200.00 *600*

balance c/f

\$8,836.47

SML 7837 P

balance b/f \$8,836.47

Labour Charges

Check and reconnect wiring.

\$45.00 201

To spray anti rust on accident affected portion.

\$120.00 301

Remove/refit rear tail-gate mechanism to new door.

\$180.00 } 601

Remove/refit rear tail-gate to facilitate repair. 5 (ax)

\$120.00 } 150

\$9,301.47

1500

Hi Kenneth,

Part - 5,325.90 including additional items
S Net - 290.00
Labour - 1,500.00

7,115.90

4/sum - 5700.00 - 5 days,