

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMF 7733 L

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 280.00 /	
2	To remove and transfer both headlight control units and power modules.	S/N \$ 800.00	500
3	To renew front windscreen.	S/N \$ 480.00 /	
4	To install solar film for front windscreen.	S/N \$ 400.00 /	
5	To carry out water seepage test for front windscreen.	S/N \$ 200.00 /	
6	To remove and renew aircon condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,400.00 /	
7	To dismantle and renew front bumper, both front fenders, bonnet and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 6,400.00	2900 + 1250 = 3250 /
8	To respray front bumper, bonnet, hinges, rhs upper A-pillar and both front fenders.	\$ 5,500.00	2750 + 300 = 3050 /
9	To carry out diagnostic check.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: \$ 15,652.00	

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 7733 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER / DEF	\$ 1,854.00	1482 /
2	FRONT BUMPER FIXING PARTS ? X NN	\$ 343.00	
3	FRONT BUMPER GRILLE - CENTRE ? X NN	\$ 195.00	
4	FRONT BUMPER AIR GUIDE GRILLE - LH / RH ? / SCR	\$ 334.00	133.60 /
5	FRONT BUMPER END CAP - LH / RH X NN 2	\$ 68.00	
6	FRONT BUMPER SPOILER X SCR	\$ 296.00	236.40 /
7	FRONT BUMPER CLOSING ELEMENT ? X NN	\$ 154.00	
8	WHEEL SPOILER - LH / RH X NN 2	\$ 68.00	
9	FRONT BUMPER ADAPTER - LH ? X NN 35	\$ 35.00	
10	FRONT BUMPER ADAPTER - RH ? X NN	\$ 42.00	
11	RADIATOR GRILLE / BR	\$ 1,395.00	1116 /
12	RADIATOR GRILLE STRIKER PLATE ? / CRA	\$ 123.00	98 /
13	FRONT BUMPER CARRIER / BT	\$ 679.00	543.20 /
14	FRONT BUMPER COVER / CRU	\$ 99.00	79.94 /
15	FRONT BUMPER FOAM FILLER PIECE / BR	\$ 77.00	61.20 /
16	FRONT BUMPER DISTANCE PIECE ? X NN	\$ 14.00	
17	FRONT BUMPER GUIDE SECTION - LH / RH ? X NN 2	\$ 70.00	
18	CAUTION SIGN STICKER ? / MC	NEC \$ 14.00	10.80 /
19	AIRCON STICKER ? / MC	NEC \$ 8.00	5.60 /
20	HORN - LH LOW TONE X NN	\$ 283.00	
SUB TOTAL SPARE PARTS CHARGES		: \$ 6,151.00	

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 7733 L

Damage Parts & Prices
S/NETT **REMARKS**

S/N	Parts Description					
21	SIGNAL HORN - RH HIGH TONE	X	N/A	\$	180.00	
22	SPRING SHACKLE - LH / RH	X	N/A	2	\$ 62.00	
23	FRONT FENDER - LH / RH	/	00	2	\$ 2,268.00	1814.40 /
24	FRONT FENDER ATTACHMENT PARTS	?	X N/A		\$ 40.00	
25	FRONT FENDER BRACKET - LH / RH	?	X N/A	2	\$ 32.00	
26	FRONT FENDER BRACKET - LH / RH	?	X N/A	2	\$ 94.00	
27	FRONT FENDER BRACKET - LH / RH	?	X N/A	2	\$ 32.00	
28	FRONT FENDER BRACE - LH / RH	?	X N/A	2	\$ 74.00	
29	FRONT FENDER BRACKET - LH / RH	?	X N/A	2	\$ 46.00	
30	WHEEL HOUSING LINER SEAL - UPPER	X	N/A	2	\$ 73.00	
31	BONNET	/	00		\$ 2,757.00	2205.60 /
32	BONNET ATTACHMENT PARTS	/	MC		\$ 163.00	
33	BONNET LID HINGE - LH / RH	?	BT	2	\$ 122.00	96.48 /
34	BONNET GAS FILLED STRUT	X	N/A		\$ 101.00	
35	BONNET STRIKER - LH / RH	?	X N/A	2	\$ 218.00	
36	BONNET SOUND ABSORBER	?	X N/A		\$ 217.00	
37	BONNET IMPACT PROTECTION - CENTRE / LH / RH	?	/ MC	3	\$ 90.00	70.48 /
38	FRONT FENDER TOP COVER - LH / RH	X	N/A	2	\$ 82.00	
39	FRONT FENDER INNER TOP COVER - LH / RH	X	N/A	2	\$ 32.00	
40	PLENUM CHAMBER COVER - FRONT	/	(MC) (2nd pd)		\$ 156.00	124.40 /
SUB TOTAL SPARE PARTS CHARGES				:	\$ 6,839.00	

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 7733 L

		Damage Parts & Prices		REMARKS
S/N	Parts Description	S/NETT		
41	BONNET LID LOCK ? X NAI	2	\$ 423.00	
42	BONNET BOWDEN CABLE - CENTRE ? X NAI		\$ 57.00	
43	BONNET LID LOCK CABLE ? X NAI		\$ 73.00	
44	BONNET RELEASE ELEMENT ? X NAI		\$ 57.00	
45	BONNET BOWDEN CABLE - LH / RH ? X NAI	2	\$ 114.00	
46	BONNET RELEASE LEVER ? X NAI		\$ 13.00	
47	HEADLIGHT MOUNTING - LH / RH ? / CRA	2	\$ 234.00	93.60 /
48	LED HEADLIGHT - LH / RH ? SCR	2	\$ 9,718.00	3887.20 /
49	LIFT CYLINDER - LH / RH X NAI	2	\$ 282.00	
50	LIFT CYLINDER HOSE X / CUT		\$ 175.00	140 /
51	LOCK CARRIER ? / CRA		\$ 983.00	786.40 /
52	AIRCON CONDENSER X NAI		\$ 545.00	
53	READY MIX COOLANT X / NEC		\$ 91.00	72.32 /
54	RADIATOR AIR GUIDE - LH / RH ? / CUT	2	\$ 60.00	23.92 /
55	RADIATOR AIR GUIDE - UPPER CENTRE ? / CRA		\$ 22.00	17.94 /
56	WHEEL HOUSING LINER - LH / RH X NAI	2	\$ 388.00	
57	WHEEL HOUSING LINER ATTACHMENT PARTS X NAI		\$ 57.00	
58	FRONT WHEEL COVER - LH / RH / NEC	2	\$ 636.00	528.80 /
59	FRONT WINDSCREEN / DR		\$ 990.00	791.60 /
60	RAIN SENSOR GEL FOIL. / NEC		\$ 132.00	105.12 /
61	RETAINING SPRING / NEC		\$ 20.00	
62	FRONT WINDSCREEN SEALANT / NEC	S/N	\$ 200.00	/
63	FRONT NO PLATE / MIS	S/N	\$ 60.00	/
64	SUNDRIES ? / NEC		\$ 400.00	51.52 /
TOTAL SPARE PARTS CHARGES		:	\$ 28,720.00	
TOTAL LABOUR CHARGES		:	\$ 15,652.00	
GRAND TOTAL		:	\$ 44,372.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Steve CLKK)
83228813

4/9/22, 11.00 am

OD - Not Authorised, Excess - ?

P/P

Ry Bel SM

11 & days

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant