

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305420387
 REGN NO : SHC 111C
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ
 DATE OF REGN : 24.02.2017
 DATE/TIME IN : 03.09.2020 12:00
 ACCIDENT DATE : 03.09.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40 20.00 367.52 do ✓
0002	04-01-0104-2533-G	IONIQV2-4 MOULDING ASSY-R	1	451.25 20.00 361.00 aut ✓
0003	04-01-0104-1150-A	IONIQVC PROTECTOR MAT	1 N	50.00 2.00- 50.00 net ✓
0004	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10	22.00 20.00 17.60 net ✓

SUB-TOTAL : 796.12 ✓

JOB NATURE

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0000	PB	PANEL BEATING		400.00 320
0001	SP	SPRAYPAINT CHARGE		500.00 400 750.
0002	L	REMOVE/REFIX REVERSE SENSOR		80.00 30

SUB-TOTAL : 980.00

TOTAL : 1,776.12

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: