

16/14/09 @ 10am  
 DR

SJW3138C

# Performance Motors Limited

A Sime Darby Motors Company  
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
 Toll-Free Number (1800-2255269)

303, Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159941  
 Fax: 64747770

280, Kampong Arang Road  
 East Coast Centre  
 Singapore 438180  
 Fax: 63449773

315, Alexandra Road  
 Sime Darby Business Centre  
 Singapore 159944  
 Fax: 64796601 (AfterSales)  
 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

01 SEP 2020

## ESTIMATE

|                             |                   |
|-----------------------------|-------------------|
| Estimate No. : b1 55888     | Page No. : 1 of 4 |
| Date Estimated : 31/08/2020 |                   |
| Prepared By : Han Kwan Yong |                   |

|                                                                                               |                                                               |
|-----------------------------------------------------------------------------------------------|---------------------------------------------------------------|
| <b>- ESTIMATE REPAIR FOR -</b><br>Rani Bahety<br>11 Nathan Road<br>#22-02<br>Singapore 248732 | <b>- ACCOUNT - 40000</b><br>Cash Sales - Service<br>Singapore |
|-----------------------------------------------------------------------------------------------|---------------------------------------------------------------|

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL     | MILEAGE |
|-----------|-------------------|------------|-----------|---------|
| SJW3138C  | WBA8E360XONU32351 | 30/11/2016 | 318iA/4Dr | 0       |

### DESCRIPTION

To make good rear bumper including to knock out rear left fender and dented area caused by the accident

To respray rear bumper and rear left fender

To remove and install boot compartment carpet and garnish to facilitate repairs.

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

| VALUE        |
|--------------|
| 1700 2550.00 |
| 1731 1823.00 |
| 231 271.00   |
| 150 177.00   |
| ? 80.00      |

Total Labour 1: 5,001.00

### DESCRIPTION

REAR BUMPER LH SIDE GUIDE ?

| QTY | PRIC  | VALUE |
|-----|-------|-------|
| 1   | 55.75 | 55.75 |

Total Parts : 55.75

### Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No \_\_\_\_\_ Claim No. \_\_\_\_\_  
 Date & Time 14/09/2020 0111X Excess S\$ \_\_\_\_\_

Surveyor's Name R. P. S. Sign \_\_\_\_\_

Surveyor's Tel 90010668 Authorised Yes / No \_\_\_\_\_

Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No \_\_\_\_\_ PML Yes / No \_\_\_\_\_

Surveyor's E-mail \_\_\_\_\_

No. of Working Days Recommend 5 days

|                |   |          |
|----------------|---|----------|
| Labour 1       | : | 5,001.00 |
| Parts          | : | 55.75    |
| Labour 2       | : | 0.00     |
| Excess         | : | 0.00     |
| Total GST @ 7% | : | 353.97   |
| Grand Total    | : | 5,410.72 |



\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*