

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009445/BRA3Q2

Date: 20/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993962

Claimant
Vehicle No : GBK4638C **Insured Vehicle No :** GBA5786D

Date of Loss: 04/09/2020 Nature of Claim: TP Claim No: 1401446488SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK4638C		
Make & Model:	CITROEN BERLINGO, 1.5 D BLUEHDI EAT8 (M)	Engine No:	10Q4DR0017401
Reg. Date:	11/08/2020 (Man. Year: 2020)	Chassis No:	VR7EFYHZRLJ662681
Colour:	White	Odometer:	1125 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,872.10	3,838.67	4,033.43	51.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,880.00	1,650.00	2,230.00	57.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,752.10	5,488.67	6,263.43	53.30
Approved Total (Overridden) (\$\$)		4,300.00		
(\$\$)	11,752.10	4,300.00	7,452.10	63.41
+ GST 7.00/7.00% (\$\$)	822.65	301.00	521.65	63.41
Nett Amount (\$\$)	12,574.75	4,601.00	7,973.75	63.41
+ Loss of Use (7.0 x S\$60.00/day) (\$\$)		420.00		
+ Doc/Search Fee (\$\$)		36.45		
Nett Liability (\$\$)		5,057.45		

INSPECTION

Date of Assignment: 04/09/2020

Date Inspected: 04/09/2020 Inspected At:

Team Autopro Pte Ltd - Sin Ming (HQ)
160 SIN MING DRIVE #02-12 SIN
MING AUTOCITY
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: Lim Teow Guan**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Dented	1,341.20 FL	*1,341.20 FL
2	1		*REAR DOOR LOGO	Necessary	188.00 FL	*80.00 FL
3	1		*REAR DOOR EMBLEM CITROEN	Necessary	145.00 FL	*100.00 FL
4	1		*REAR DOOR EMBLEM C&C	Necessary	87.50 FL	*50.00 FL
5	1		*REAR DOOR INNER LOCK RH	Not Damaged	253.10 FL	*- FL
6	2		*REAR DOOR HINGE RH	Not Damaged	369.60 FL	*- FL
7	1		*REAR DOOR INNER TRIM BOARD RH	Not Damaged	144.00 FL	*- FL
8	1		*REAR DOOR WEATHERSTRIP	Not Damaged	163.80 FL	*- FL
9	1		*REAR DOOR WINDSCREEN	Broken	487.50 FL	*487.50 FL
10	1		*REAR DOOR WINDSCREEN MOULDING	No such part	186.90 FL	*- FL
11	1		*REAR BUMPER	Dented	782.30 FL	*782.30 FL
12	2		*REAR BUMPER BRACKET	Not Damaged	296.00 FL	*- FL
13	2		*REAR BUMPER SIDE RETAINER	Not Damaged	376.60 FL	*- FL
14	1		*REAR BUMPER REINFORCEMENT	Dented	587.30 FL	*587.30 FL
15	1		*REAR BUMPER TOW CAP	Not Damaged	78.60 FL	*- FL
16	1		*REAR END PANEL	Not Damaged	985.60 FL	*- FL
17	1		*REAR END PANEL TOP GARNISH	Not Damaged	248.00 FL	*- FL
18	1		*TAILLAMP RH	Broken	548.00 FL	*548.00 FL
19	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
20	1		*REAR DOOR SEALANT	Necessary	100.00 FS	*30.00 FS
21	1		*REAR DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
22	1		*REAR DOOR STICKER 6 PAX	Necessary	30.00 FS	*20.00 FS
23	1		*REAR DOOR WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
24	1		*REAR DOOR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
25	1		*REAR DOOR WINDSCREEN PRIMER & CLEANER	Not Necessary	80.00 FS	*- FS
26	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
27	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
28	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
29	1		*TAILLAMP SEAL	Necessary	60.00 FS	*30.00 FS
30	1		*TAILLAMP CLIPS	Necessary	50.00 FS	*30.00 FS
31	2		*REVERSE SENSOR	No such part	500.00 FS	*- FS
					Sub Total (\$\$)	8,599.00 4,236.30
					- List Item Discount on L Items 10.00/10.00% (\$\$)	726.90 397.63
					Total Parts (\$\$)	7,872.10 3,838.67

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R REAR DOOR COMPARTMENT	New	150.00	80.00
2	R&R REAR DOOR WINDSCREEN	New	250.00	100.00
3	R&R REVERSE SENSOR	New	100.00	30.00
4	UPHOLSTERY	New	300.00	0.00
5	CHECK WIRING	New	80.00	40.00
6	RUST PROOFING	New	200.00	0.00
7	PANEL BEAT	New	1,400.00	800.00
8	SPRAY PAINTING	New	1,400.00	600.00
Gross Labour Cost (\$\$)			3,880.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >