Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd

> 64 Cecil Street #04-00 IOB Building Singapore 049711

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

> Paya Ubi Industrial Park Singapore 408933

Attn: Gabriel Wee 08 Sep 2020 Date:

Preliminary Advice

Vehicle No : SMA2856A Accident Date : 04/09/2020

Policy No. : D19MPC0002427 01 Make : BMW 520I

Assignment Date : 07/09/2020 Excess : S\$0.00 Date of Inspection : 07/09/2020 Est. Duration of Repair : 6

: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) Inspection At

BLK 1008, #01-04/06/08/94, BUKIT MERAH LANE 3

SINGAPORE 159722

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 21,903.51 |
|-----------------------------|------|-----------|
| Revised Amount | :S\$ | 15,945.17 |
| Check Items (Estimated) | :S\$ | 5,529.76 |
| Total | :S\$ | 21,474.93 |

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 155,000.00 COE / PARF Rebate :S\$ 76,201.00

Salvage Value :S\$

Margin for Repair :S\$ 60,701.00

Remarks

| (X |) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. |
|-----|---|---|
| (|) | The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. |
| (|) | Other comments : |