

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)
 8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
 Singapore 415875
 Tel : 6341 6789 Fax: 6341 6778
 E-mail: visionautowork@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

DATE : 07.09.20
 Acknowledged by Repairer
 Signature: *Seise*
 Date:

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : GBJ3351R
 MODEL : TOYOTA REGIUSACE
 DATE OF ACCIDENT : 12.08.20
 TIME OF ACCIDENT : 16:15HRS

GDA 2012003245

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Delat</i>	1	\$ 571.60	\$ 571.60
2	FRONT BUMPER TOW HOOK COVER LH <i>Ne</i>	1	\$ 25.10	\$ 25.10
3	FRONT BUMPER FOGLAMP COVER LH <i>Ne</i>	1	\$ 48.70	\$ 48.70
4	FRONT BUMPER SIDE RETAINER <i>Ne</i>	2	\$ 148.70	\$ 297.40
5	FRONT BUMPER CENTRE BEAM <i>Ne</i>	1	\$ 176.90	\$ 176.90
6	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 357.10	\$ 357.10
7	HEADLAMP <i>LH combd</i> * <i>\$2584.50</i>	2	\$ 3,033.10	\$ 6,066.20
8	FRONT GRILLE (UPPER) BASE <i>Comb</i>	1	\$ 568.90	\$ 568.90
9	FRONT GRILLE (LOWER) <i>Delat Delat</i>	1	\$ 383.70	\$ 383.70
10	FRONT GRILLE COVER GARNISH (UPPER) <i>Comb</i>	1	\$ 221.70	\$ 221.70
11	FRONT GRILLE COVER GARNISH (LOWER)	1	\$ 383.70	\$ 383.70
12	FRONT STEP PANEL GARNISH LH <i>2</i>	1	\$ 186.20	\$ 186.20
13	FRONT SUPPORT PANEL	1	\$ 377.91	\$ 377.91
14	FRONT BRACE PANEL	1	\$ 75.20	\$ 75.20
15	AIR CON CONDENSER <i>Ne</i>	1	\$ 1,949.60	\$ 1,949.60
16	ADBLUE TANK	1	\$ 1,365.80	\$ 1,365.80
17	ADBLUE TANK WIRE HARNESS <i>Ne</i>	1	\$ 451.20	\$ 451.20

5311.20
3983.40
 TOTAL PRICE \$ 13,506.91
 LESS 25% \$ 3,376.73
SUB TOTAL PRICE \$ 10,130.18

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>Ne</i>	1	\$ 80.00	\$ 80.00
2	FRONT BUMPER CLIP (SET) <i>Ne</i>	1	\$ 50.00	\$ 50.00
3	FRONT GRILLE COVER GARNISH (UPPER) CLIP (SET) <i>Ne</i>	1	\$ 50.00	\$ 50.00
4	FRONT GRILLE COVER GARNISH (LOWER) CLIP (SET) <i>Ne</i>	1	\$ 50.00	\$ 50.00
5	FRONT STEP PANEL GARNISH CLIP (SET) <i>Ne</i>	1	\$ 50.00	\$ 50.00
6	FRONT GRILLE STICKER (SPECIAL TYPE) <i>Ne</i>	1	\$ 850.00	\$ 850.00

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : GBJ3351R
 MODEL : TOYOTA REGIUSACE
 DATE OF ACCIDENT : 12.08.20
 TIME OF ACCIDENT : 16:15HRS

7	FRONT SUPPORT PANEL SEALANT	1	\$ 150.00	\$ 150.00	X
8	FRONT BRACE PANEL SEALANT	1	\$ 150.00	\$ 150.00	X
9	FRONT AIR GUARD CLIP (SET)	1	\$ 60.00	\$ 60.00	X
10	COOLANT	1	\$ 60.00	\$ 60.00	X
11	ADBLUE FUEL	1	\$ 150.00	\$ 150.00	X

470
TOTAL \$ 1,700.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,000.00	350
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	200
3	TUFF COAT	\$ 250.00	X
4	REFOCUS HEADLAMP BEAM	\$ 60.00	X
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	X
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	X
7	REMOVE AND REFIX AIR COLLER	\$ 120.00	X
8	REMOVE AND REFIX ADBLUE TANK	\$ 350.00	X
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 3,160.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,830.18
 TOTAL LABOUR COST : \$ 3,160.00
 TOTAL REPAIR COST : \$ 14,990.18

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

Adrian L
 L/S 08/09/20
 032ys

AK

total 500340
 L/S: 4K