



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2102429

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 10/04/2021  
Reference CC6/CTI20009505/Uga3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SKN 2519D  
Insured Veh. SKC 7332A  
Claim No. SNM20D203276  
Policy No. DMPCSNW00075712000  
Accident Date 05/09/2020  
Inspection Date 07/09/2020

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (7%)</b>                | <b>28.00</b>  |
| <b>Grand Total</b>             | <b>428.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                           |                 |                                                              |  |
|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|-----------------|--------------------------------------------------------------|--|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909                                         |                                                                                           |                 | Ref: CC6/CTI20009505/Uga3q2<br>Date: 10/04/2021<br>Code: CTI |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                           |                 |                                                              |  |
| Insured Veh.                                                                                                                           | SKC 7332A                                                                                 | Veh. Inspected  | SKN 2519D                                                    |  |
| Policy No.                                                                                                                             | DMPCSNW00075712000                                                                        | Coverage (\$)   | 0.00                                                         |  |
| Claim No.                                                                                                                              | SNM20D203276                                                                              | Excess (\$)     | 0.00                                                         |  |
| Assign From                                                                                                                            |                                                                                           | Assign Date     | 07/09/2020                                                   |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                           |                 |                                                              |  |
| Make & Model                                                                                                                           | HYUNDAI ELANTRA (A)                                                                       | c.c             | 1591                                                         |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                    | Year of Reg.    | 2014                                                         |  |
| Chassis No.                                                                                                                            | KMHDH41CMEU208558                                                                         | Colour          | SILVER                                                       |  |
| Odometer                                                                                                                               | 111302 KM                                                                                 | Steering        | IN ORDER                                                     |  |
| Brakes                                                                                                                                 | IN ORDER                                                                                  | Modification    | SPORTS RIM                                                   |  |
| General                                                                                                                                | GOOD                                                                                      |                 |                                                              |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                           |                 |                                                              |  |
|                                                                                                                                        | Size                                                                                      | Make            | Balance                                                      |  |
| R/H Front Tyre                                                                                                                         | 205/55 R16                                                                                | PIRELLI         | 5 mm                                                         |  |
| L/H Front Tyre                                                                                                                         | 205/55 R16                                                                                | PIRELLI         | 5 mm                                                         |  |
| R/H Rear Tyre                                                                                                                          | 205/55 R16                                                                                | PIRELLI         | 5 mm                                                         |  |
| L/H Rear Tyre                                                                                                                          | 205/55 R16                                                                                | PIRELLI         | 5 mm                                                         |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                           |                 |                                                              |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                             |                                                                                           |                 |                                                              |  |
| <b>5. General Information</b>                                                                                                          |                                                                                           |                 |                                                              |  |
| Accident Date                                                                                                                          | 05/09/2020                                                                                | Inspection Date | 07/09/2020                                                   |  |
| Survey held at                                                                                                                         | FASTECH AUTO PTE LTD<br>1 KAKI BUKIT AVENUE 6<br>#01-46/48/50 AUTOBAY<br>SINGAPORE 417883 |                 |                                                              |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                           |                 |                                                              |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                           |                 |                                                              |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                           |                 |                                                              |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                           |                 | 4 Working Days                                               |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 2519D

| Qty                                | Description of Parts                              | Condition         | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---------------------------------------------------|-------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |                                                   |                   |                           |                   |
| 1                                  | BOOTLID                                           | NOT NECESSARY     | 1,280.20                  | -                 |
| 1                                  | BOOTLID 'H' LOGO                                  | NOT NECESSARY     | 48.50                     | -                 |
| 1                                  | BOOTLID 'ELANTRA' EMBLEM                          | NOT NECESSARY     | 62.00                     | -                 |
| 1                                  | BOOTLID 'ELITE' EMBLEM                            | NOT NECESSARY     | 65.00                     | -                 |
| 2                                  | BOOTLID REFLECTORS @\$450.00                      | NOT NECESSARY     | 900.00                    | -                 |
| 1                                  | BOOTLID INNER LOCK SENSOR                         | CRACKED           | 215.00                    | 215.00            |
| 1                                  | BOOTLID WEATHERSTRIP                              | NOT NECESSARY     | 288.00                    | -                 |
| 1                                  | REAR BUMPER                                       | DEFORMED / DENTED | 788.50                    | 459.40            |
| 1                                  | REAR BUMPER LOWER GARNISH                         | GRAZED            | 452.00                    | 241.50            |
| 2                                  | REAR BUMPER REFLECTORS @\$105.00                  | NOT NECESSARY     | 210.00                    | -                 |
| 1                                  | REAR BUMPER SPONGE                                | NOT FITTED        | 188.00                    | -                 |
| 1                                  | REAR BUMPER REINFORCEMENT                         | CRACKED           | 495.00                    | 382.00            |
| 2                                  | REAR BUMPER REINFORCEMENT BRACKETS @\$165.00      | SERVICEABLE       | 330.00                    | -                 |
| 3                                  | REAR BUMPER REINFORCEMENT LOWER BRACKETS @\$25.00 | SERVICEABLE       | 75.00                     | -                 |
| 2                                  | TAILLAMPS @\$981.00                               | NOT NECESSARY     | 1,962.00                  | -                 |
| 1                                  | REAR END PANEL                                    | DENTED            | 666.00                    | 452.20            |
| 1                                  | REAR END PANEL TOP GARNISH                        | NOT NECESSARY     | 215.00                    | -                 |
|                                    | LESS 20% DISCOUNT                                 |                   | -                         | -350.02           |
|                                    |                                                   |                   | 8,240.20                  | 1,400.08          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |                                                   |                   |                           |                   |
| 1                                  | SET REAR BUMPER REVERSE SENSOR (SN)               | SHORTED           | 280.00                    | 200.00            |
| 1                                  | SET REAR BUMPER CLIPS (SN)                        | NECESSARY         | 50.00                     | 50.00             |
| 1                                  | REAR END PANEL SEALANT (SN)                       | NECESSARY         | 50.00                     | 50.00             |
|                                    |                                                   |                   | 380.00                    | 300.00            |
| <b><u>LABOUR</u></b>               |                                                   |                   |                           |                   |
|                                    | TO CHECK WIRING .                                 |                   | 50.00                     | 20.00             |
|                                    | TO DISMANTLE & REPLACED REVERSE SENSOR .          |                   | 80.00                     | 50.00             |
|                                    | TO TRANSFER BOOTLID MECHANISM .                   | NOT NECESSARY     | 80.00                     | -                 |
|                                    | TO DISMANTLE & REFIX CUSHION UPHOLSTERY .         |                   | 120.00                    | 80.00             |

Report Ref No. CC6/CTI20009505/Uga3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                                                     | Description of Parts                       | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-------------------------------------------------------------------------|--------------------------------------------|-----------|---------------------------|-------------------|
|                                                                         | TO SPRAY RUST PROOFING .                   |           | 100.00                    | 30.00             |
|                                                                         | LABOUR FOR PANEL BEATING & REPLACED PARTS. |           | 1,200.00                  | 600.00            |
|                                                                         | TO PUTTY & SPRAY PAINTING .                |           | 1,500.00                  | 680.00            |
|                                                                         |                                            |           | 3,130.00                  | 1,460.00          |
| GRAND TOTAL                                                             |                                            |           | 11,750.20                 | 3,160.08          |
| RECOMMENDED COST OF LUMP SUM REPAIRS<br>(TO ITS PRE-ACCIDENT CONDITION) |                                            |           |                           | 2,500.00          |

Report Ref No. CC6/CTI20009505/Uga3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SKN 2519D

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SKN 2519D**

**RE-INSPECTION**

