



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

07/09/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPA16

Xiao Tong

Accident date: 30/08/2020

Estimated repair cost for vehicle no: SLB490R SUBARU FORESTER 2.0XT CVT 16'

CHASSIS: JF1SJGK85GG068694

S/n	Qty	Items	U/price	Amount
1	1	Front R/H Head Lamp <i>ut</i>		(\$2,504.30) 2380
2	1	Front R/H Head Lamp Lower Bracket <i>not me</i>		\$55.00 +
3	1	Front R/H Fender <i>Regis</i>		\$380.30 x
4	1	Front R/H Fender Cowling <i>2 x 1</i>		\$125.20 +
5	8	Front R/H Fender Cowling Clip <i>2 x 1</i>	\$6.50	\$52.00 x
6	1	Front Bumper <i>Debond</i>		\$694.50 ✓
7	10	Front Bumper Clip <i>per</i>	\$6.50	\$65.00 30
8	1	Front R/H Bumper Side Retainer <i>Nec</i>		\$26.00 ✓
9	1	Front R/H Bumper Fog Lamp <i>Cracked</i>		\$360.40 ✓
10	1	Front R/H Bumper Fog Lamp Cover <i>Debond</i>		\$48.30 x
11	1	Front R/H Bumper Air Duct <i>not me</i>		\$65.30 x
12	1	Front R/H Sport Rim <i>not me</i>		\$980.00 x
13	1	Front R/H Shock Absorber <i>2</i>		\$340.60 +
14	4	Front R/H Knuckle Arm <i>Not me</i>		\$264.90 x
15	4	Front R/H Knuckle Arm Bearing		\$261.00 +
16	1	Front R/H Lower Arm		\$493.20 x

Subtotal :- \$6,716.00

3539.20

283136

Labour charges

Remove & refit front undercarriage		\$350.00	X
Wheel Alignment		\$150.00	X
Tuff kote		\$150.00	X
To check wiring		\$80.00 30	
Panel beating	680	\$1,000.00 250	
Spray painting		\$1,000.00 400	

Subtotal :- \$2,730.00

Total:- \$9,446.00

total: 351136

k/s: 2.8K.

03 Days.

2.8K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: