



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20009514/Uyf3e2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 17-09-2020



Code : SMO

#### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                 |                |            |
|--------------|-----------------|----------------|------------|
| Insured Veh. | SLT 3523R       | Veh. Inspected | SKP 5287S  |
| Policy No.   | D19MTRENT000063 | Coverage (\$)  | 0.00       |
| Claim No.    | CMTD2002599/RUC | Excess (\$)    | 0.00       |
| Assign From  | GRACE TEO       | Assign Date    | 07/09/2020 |

#### 2. Vehicle Particulars & Condition

|              |                          |              |            |
|--------------|--------------------------|--------------|------------|
| Make & Model | TOYOTA COROLLA ALTIS (A) | c.c          | 1598       |
| Engine No.   | HIDDEN                   | Year of Reg. | 2014       |
| Chassis No.  | MR053REH104514371        | Colour       | BROWN      |
| Odometer     | 98051                    | Steering     | IN ORDER   |
| Brakes       | IN ORDER                 | Modification | SPORTS RIM |
| General      | GOOD                     |              |            |

#### 3. Conditions of Tyres

|                | Size       | Make   | Balance |
|----------------|------------|--------|---------|
| R/H Front Tyre | 205/55 R16 | DUNLOP | 6 mm    |
| L/H Front Tyre | 205/55 R16 | DUNLOP | 6 mm    |
| R/H Rear Tyre  | 205/55 R16 | DUNLOP | 6 mm    |
| L/H Rear Tyre  | 205/55 R16 | DUNLOP | 6 mm    |

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.

DAMAGES SEE DETAILS.

#### 5. General Information

|                |                                                                                           |                 |            |
|----------------|-------------------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 04/09/2020                                                                                | Inspection Date | 07/09/2020 |
| Survey held at | FASTECH AUTO PTE LTD<br>1 KAKI BUKIT AVENUE 6<br>#01-46/48/50 AUTOBAY<br>SINGAPORE 417883 |                 |            |

#### 5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 8 Working Days |
|-------------------------------------|----------------|