

Date: 07.09.2020

Vehicle No: SMJ9129Y

Model: TOYOTA NOAH HYBRID 1.8X

Chassis: ZWR800358684-2018

Reg. Year: 2019

Third Party Insurer: AUTO & GENERAL

Third Party Veh No: SKF2008D

Date of Accident: 06.09.2020

86197.89

Not Authored

Philly B4 point

## ESTIMATE

| NO. | DESCRIPTION                           | QTY | UNIT \$S    | AMOUNT \$S  |
|-----|---------------------------------------|-----|-------------|-------------|
| 1   | REAR TAILGATE                         | 1   |             |             |
| 2   | REAR TAILGATE "HYBRID" EMBLEM         | 1   |             |             |
| 3   | REAR TAILGATE CHROME MOULDING         | 1   |             |             |
| 4   | REAR TAILGATE RUBBER                  | 1   |             |             |
| 5   | REAR TAILGATE INNER TRIM CLIPS        | 8   | \$5.50      |             |
| 6   | REAR TAIL LAMP LH                     | 1   |             |             |
| 7   | REAR TAIL LAMP RH                     | 1   |             |             |
| 8   | REAR BUMPER                           | 1   |             |             |
| 9   | REAR BUMPER CLIPS                     | 10  | \$5.80      |             |
| 10  | REAR BUMPER SIDE BRACKET LH           | 1   |             |             |
| 11  | REAR BUMPER FIXING COVER              | 1   |             |             |
| 12  | REAR WINDSCREEN RUBBER                | 1   |             |             |
| 13  | REAR END PANEL UPPER COVERING         | 1   |             |             |
| 14  | REAR END PANEL UPPER COVERING CLIPS   | 6   | \$5.80      |             |
| 15  | REAR SPARE TYRE UPPER BOARD           | 1   |             |             |
| 16  | REAR SPARE TYRE INNER COVER           | 1   |             |             |
| 17  | REAR TAIL LAMP LOWER GARNISH COVER LH | 1   |             |             |
| 18  | REAR END PANEL                        | 1   |             |             |
|     |                                       |     | SUB TOTAL   | \$7,253.30  |
|     |                                       |     | LESS 25%    | -\$1,813.33 |
|     |                                       |     | PARTS TOTAL | \$5,439.98  |

| NO. | SPECIAL NETT               | QTY | UNIT \$S  | AMOUNT \$S |
|-----|----------------------------|-----|-----------|------------|
| 1   | REAR WINDSCREEN SEALANT    | 1   |           | 880.00     |
| 2   | REAR BUMPER REVERSE SENSOR | 1   |           | 350.00     |
|     |                            |     | S/N TOTAL | 1230.00    |

**LABOUR CHARGES:**

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST REAR ACCIDENT AREAS & ETC

6001  
\$700.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR TAIL LAMP GARNISH COVER LH, REAR END PANEL & ETC.

7201  
\$900.00

# OPTIMA WERKZ <sup>TM</sup> / SINGAPORE

OPTIMA WERKZ PTE LTD  
Co. Reg. No. 201512455W  
www.ow.sg



Third Party Insurer: AUTO & GENERAL  
Third Party Veh No: SKF2008D  
Date of Accident: 06.09.2020

Date: 07.09.2020  
Vehicle No: SMJ9129Y  
Model: TOYOTA NOAH HYBRID 1.8X  
Chassis: ZWR800358684-2018  
Reg. Year: 2019

LABOUR CHARGES TO REMOVE, REPLACE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT & ETC. TO EFFECT REPLACE OF REAR TAILGATE.

120l  
\$150.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

60l  
\$120.00

LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC. TO EFFECT REPLACE OF REAR BUMPER.

30l  
\$100.00

TO DIAGNOSIS FAULTY CODE & RESET MEMORY.

nn \$180.00 x

LABOUR TOTAL \$2,150.00

TOTAL \$8,019.98

Ting An

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey & resprayer spray painting
- To display & repair part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be insured and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Head Office

14 Ang Chuan Road Singapore 159143  
Tel: (+65) 6453 1313 Fax: (+65) 6453 2112

Branch

14 Serangoon North Ave 5 Singapore 554288  
Tel: (+65) 6484 9919 Fax: (+65) 6481 1811

Branch

831 Upper Thomson Road Singapore 574419  
Tel: (+65) 6452 6888 Fax: (+65) 6452 9229

oil