ASS. REC. BY:	2000 9521 /KV f3
Kenner	ASSIGNMENT
From	CM 101294 YOURS 081 19
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD TP/WS/TP RES/OD RES/EVA/INV/MV	Touch / Trailor or
To Inspect Vehicle No:	Make: Tuy Nogh c.c 1797
at Workshop m/s Optime	Colour M. Black AC: Insured / Std / NI / NA
of Options	Sp.Reading 92603 T/Radio: Insured / Std / NI / NA 0358684
Insured:	Eng/No:
Policy No.	
Claims No.	Gen. Cond: 8000 / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inopde? / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: NII I STRIM I STDATRIM Or 185/15015
	Tyre Size: F: Westlake 195/65R15
(Policy Condition) Payratis The year had commenced its N/S O/S	W
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	TOYO / YOKO or
,	Front Rear
Bal, or Market Value: IDAC Accident Root: Consistent?: Yes or No	R/Bal. 9 mm R/Bal. P mm
O selected Ven as No	UBal. 9 mm L/Bal. P mm
GIA / PR Seen: Consistent /: Yes or No Est. Repairs: Adays Res.: Yes or No	D.O.A. 6/9/20 DOI 8/9/2020
Lum Sum: /.B./ % 3 Val.: Yes or No	Survey held at
	Des. of Damages : Frt Rear Y O/S N/S U/C Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
0/40/00 5: 15 00407.00 5	(Red 1822 09, 23%)
8/10/20 Final fig \$6197.89 confirmed	d by email (Red 1822.09, 23%)
1	
Oate/Time, File Pass to? : Prell. Report Da	ays Of Repair: 6
i) : Final Report Re	survey No. of Trip: 1 Survey Fee:
Cuto/Fine, File Return to?	Transportation:
7 16/10/20-Typist Add Fee:	: Site Insp (\$) _ s - Rssi
Danad Samuel. TD	: Interview (\$) Finds
Report Format: TP	Tech Invs (\$) Others
Lump Sum / I.B.I: (\$ 6197.89	Weekend (\$
	TOTAL



OPTIMA WERKZ PTE LTD Co. Reg. No. 201212455W

www.ow.sg

n /optimaWerkz

OptimaWerkz

Date:

07.09.2020

Vehicle No: SMJ9129Y

Model:

TOYOTA NOAH HYBRID 1.8X

Chassis:

ZWR800358684-2018

Reg. Year:

2019

Third Party Insurer:

AUTO & GENERAL

Third Party Veh No: SKF2008D

06.09.2020

Date of Accident: Nos Norhonsel

Phenony B&paint

ESTIMATE

	LOTHWALL	QTY	UNIT S\$	AMOUNT S\$
NO.	DESCRIPTION	1		\$1,988.80
1	REAR TAILGATE	1		My \$95.80
2	REAR TAILGATE "HYBRID" EMBLEM	$\frac{1}{1}$	N	9 cm \$767.20
3	REAR TAILGATE CHROME MOULDING			Dd/Dir \$380.70
4	REAR TAILGATE RUBBER	$\frac{1}{2}$	\$5.50	ner \$44.00
5	REAR TAILGATE INNER TRIM CLIPS	8	\$5.50	an \$667.80
6	REAR TAIL LAMP LH	1		CM \$667.80
7	REAR TAIL LAMP RH	1		Ry \$820.00
8	REAR BUMPER	1	\$5.80	ne \$58.00
9	REAR BUMPER CLIPS	10	\$3.80	Pry \$156.70
10	REAR BUMPER SIDE BRACKET LH	1		\$38.40
11	REAR BUMPER FIXING COVER	11		Mr. \$116.00
12	REAR WINDSCREEN RUBBER	1		Nu \$207.30
	REAR END PANEL UPPER COVERING	1	45.00	
14	REAR END PANEL UPPER COVERING CLIPS	6	\$5.80	
	REAR SPARER TYRE UPPER BOARD	1		4000.00
	REAR SPARER TYRE INNER COVER	1		<i>DII</i> \$380.00
17	REAR TAIL LAMP LOWER GARNISH COVER LH	1		REPAIR
5000000	REAR END PANEL	1		REPAIR
			SUB TOTAL	\$7,253.30
			LESS 25%	-\$1,813.33
			PARTS TOTAL	\$5,439.98

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOU	NT S\$	1
0.000	REAR WINDSCREEN SEALANT	1		nu	¥ 0 0 1 1 1	4012
	REAR BUMPER REVERSE SENSOR	1		Net	\$350.00	200m
			S/N TOTAL		\$430.00	

LABOUR CHARGES:

PANEL & ETC.

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST REAR ACCIDENT AREAS & ETC.

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR TAIL LAMP GARNISH COVER LH, REAR END

Head office

6 Kung Chong Road Singapore 159143 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

9A Serangoon North Ave 5 Singapore 554500 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223





OPTIMA WERKZ PTE LTD Co. Reg. No. 201212455W

www.ow.sg

OptimaWerkz

Third Party Insurer:

Third Party Veh No:

Date of Accident:

OptimaWerkz

AUTO & GENERAL

SKF2008D

06.09.2020

Date:

07.09.2020

Vehicle No: SMJ9129Y

Model:

TOYOTA NOAH HYBRID 1.8X

Chassis:

ZWR800358684-2018

Reg.Year:

2019

1201

\$150.00

LABOUR CHARGES TO REMOVE, REPLACE & REFIX REAR WINDSCREEN GLASS, REAR

WINDSCREEN SEALANT & ETC. TO EFFET REPLACE OF REAR TAILGATE.

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM

\$120.00

& ETC. BACK TO ORIGINAL OPERATIONS.

501

LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC. TO EFFECT REPLACE OF REAR BUMPER.

\$100.00

TO DIAGNOSIS FAULTY CODE & RESET MEMORY.

\$180.00 7

LABOUR TOTAL

\$2,150.00

TingAn

TOTAL

\$8,019.98

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the Indempert of this report to the insurers of the I
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT
07/09/2020 13:26
06/09/2020 13:25
YIO CHU KANG ROAD
SINGAPORE
DETAILS OF OWN VEHICLE
SMJ9129Y
KINETIC HOLDINGS PTE LTD
2XXXXX392N
SUPPORT@KINETIC-ALLIANCE.COM
OFFICE-97849075
TOYOTA
NOAH HYBRID-1.8 X CVT (A)
t GRAB SERVICE
NO
THIRD PARTY
PRIVATE HIRE
TO DESCRIPTION OF THE PROPERTY
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
COMPREHENSIVE
NO
DMHCSNA00003502000
08/06/2020 - 07/06/2021
ABDUL YAMIN BIN BADARUDDIN
SXXXX699Z
28/05/1973
OUTDOOR
22/07/2004
16 YEARS AND 1 MONTH
MALE
(LUCAL) +65-67610439
(LOCAL) +65-87816439
(LOCAL) +65-67610435

Page 1 of 16

Address

BLK 470B FERNVALE LINK #07-440

Postcode

792470

Was driver an employee of the Insured's Company

NO

If No., Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

NO

involved in the accident

3

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance. Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

NO

If Yes.Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKF2008D

Vehicle Make/Model/Colour

VOLKSWAGEN JETTA

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SHC7139K

Page 2 of 16

Sketch Plan #2

SKETCH PLAN (A) - CAMPAINTY (E) - CUT 2008D (C) - CHC PD-6H
(4) - CMANINAL (7) - CILPONED (C) - CHENDER
YIU CHIN KANG ROMD
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT VEHICLE No SMATGLETY (CHIMA)
EN OFFINA NOTIONS OF METHAND 13:35 HOLDES, I WAS DEMINED MY VEHICLE AT SMITHAY MUNICIPALITY
YOU ARE EARLY KOAD WATER I WAS DISMARY ALONG THE CARD ROAD, ALL OF SUPPONT. THE
TEMICES (BAIN) MERCALL OF THE SUDDENIN JAMMED BEARS. I BLUCKLY STEPPED ON MY
0.04570040
CEROCETO : & JUSTIAN THE STATEMENT OF CONTRACT OF CONTRACT OF STANKS
FALSO TO CTOP AND ICILIZED INTO MY VEHICE A: SMITHOUT REAR PORTION! CAMEING
WHANGE. THERE WERE S NEHICLES IMPORTED IN THIS WILDENT. FID ONE IT WITHERD WHEN
THE THIS OF ACCIDENTS.
OECLARATION We destate the foresoing particulars are true in every respect.
Olivyholder's Signature of Driver's Signature Reporting Centre Personnel's Signature
Date & Time: UT (If driver is not the policyholder) Name: NRIC/FIN No.: (AWK)
CHIMING AT DINGS MORECHOP: OPTIMA WEAKS PTE CID GOUNT
EMAIL: KULLANI ENIO & DIN-74