

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/ SMO 20009524/4yf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKT 5177E
Team work

at Workshop m/s

of

Insured:

SLG 7741U

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

31k.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Dunn

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKT 5177E

Yr Regn:

13/9/12

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make:

Volkswagen Jetta c.c. 1390

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

127360

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVWZZZ16Z CM 155584

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/35ZR19

R:

BS / DUN / EXNOVA / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

2/9/20

D.O.I.

8/9/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rr.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 27619 Deplok. net 3381

14/9/20 4/5 \$3000 confirmed with Durance.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



Teamwork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Payu Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

REPAIR PERFORMA INVOICE

SOMPO INSURANCE

Mr. Arthur
N/A

8/5/20

1/5 #3000

Mr. Arthur

5 days

Vehicle number	SKT5177E
Make / Model	VOLKSWAGEN JETTA
Chassis number	WVWZZZ16ZCM155584
Accident date	2/9/20
Reference	2009-02

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS

1	FRONT BUMPER	1311.00 X
2	FRONT BUMPER SIDE RETAINER 11	101.54 X
1	FRONT BUMPER CENTRE GRILLE 11	306.65 X
1	FRONT BUMPER SPONGE 11	257.26 X
2	FRONT BUMPER FOGLAMP 11	608.70 X
2	FRONT BUMPER FOG LAMP COVER 11	200.10 X
1	FRONT BUMPER REINFORCEMENT 415.00	734.39 X
2	FRONT HEADLAMP 11	1459.12 X
1	REAR BUMPER 1145.23	1521.16 X
2	REAR BUMPER SIDE RETAINER 11	253.92 X
1	REAR BUMPER CENTRE GARNISH 11	167.61 X
2	REAR BUMPER REFLECTOR 11	153.06 X
1	REAR BUMPER REINFORCEMENT 11	696.96 X
1	END PANEL 11	955.90 X
1	END PANEL TOP GARNISH 11	167.61 X
1	BOOTLID 11	1868.60 X
1	BOOTLID LOCK 11	183.25 X
2	BOOTLID HINGE 11	300.20 X
2	BOOTLID LAMP 11	694.33 X
1	BOOTLID INNER TRIM 11	253.86 X
1	BOOTLID LOGO 11	71.13 X
1	BOOTLID WEATHERSTRIP 11	372.43 X
2	TAILLAMP 11	869.06 X
2	TAILLAMP PANEL 11	363.28 X

13871.12

Less 10%

Subtotal

Balance C/F

1387.11

12484.01

12484.01

1727.84

PARTS REPLACEMENT - SPECIAL NETT ITEMS

Balance B/F

12484.01

1	FRONT GRILLE ASSY	ena	480	550.00	✓
1	FRONT GRILLE EMBLEM	en		95.00	X
1	FRONT NUMBER PLATE	en		90.00	60
1 SET	FRONT BUMPER CLIP	na		40.00	X
1 SET	REVERSE SENSOR		shhd	400.00	200
1 SET	END PANEL TOP GARNISH CLIP	n1		60.00	X
1 SET	REAR BUMPER CLIP	en		40.00	✓
Subtotal				1275.00	

Balance C/F

13759.01

S/No

LABOUR AND MISCELLANEOUS CHARGES

Balance B/F

13759.01

1	CHECK FRONT & REAR WIRING AND LIGHTNING SYSTEM	80.00	30
2	REMOVE AND REFIT REAR LININ, TRIM AND GARNISH	200.00	60
3	TRANSFER OLD BOOTLID TO NEW	200.00	X
4	REMOVE AND RENEW REVERSE SENSOR	150.00	50
5	PANEL BEATING ON AFFECTED AREAS	1600.00	600
6	SPRAY PAINTING ON AFFECTED AREAS	1400.00	900
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00	X

Subtotal

3780.00

Grand total

17539.01

LOCKING CONSULTANTS hence notify the presence of the following:

- To be done before later spray painting
- To display damaged part(s) during resurvey
- Repairs are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P 15/5/05
S.N 780
L-1640