

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG20009529/R1TF3

**Date:** 08/09/2020

### REFERENCE

|                   |            |                  |            |           |              |
|-------------------|------------|------------------|------------|-----------|--------------|
| Insured/Claimant: | LOW MAGGIE | Policy No:       | 1900156779 | Claim No: | 1382152131SG |
| Date of Loss:     | 04/09/2020 | Nature of Claim: | OD         |           |              |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                 |             |                   |
|-----------------------------|---------------------------------|-------------|-------------------|
| Reg No:                     | SDQ1191M                        | Engine No:  | 3A92UHT1659       |
| Make & Model:               | MITSUBISHI ATTRAGE, 1.2 CVT (A) | Chassis No: | MMBSTA13AKH001878 |
| Reg. Date:                  | 03/09/2019 (Man. Year: 2019)    | Odometer:   | 12665 km          |
| Colour:                     | Maroon                          |             |                   |
| Engine Capacity:            | 1193 cc                         |             |                   |
| Market Value/New Car Price: | N/A                             |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price      |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |      |                  |      |
|-------------------|------|------------------|------|
| Front Tyre Size:  |      | Rear Tyre Size:  |      |
| Front Left Side:  | 6 mm | Rear Left Side:  | 6 mm |
| Front Right Side: | 6 mm | Rear Right Side: | 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                      | Repairer's       | Adjuster's       | Difference      | Diff %       |
|-------------------------------------|------------------|------------------|-----------------|--------------|
| Parts                               | 5,610.21         | 3,850.76         | 1,759.45        | 31.36        |
| Miscellaneous Items                 | 0.00             | 11.00            | -11.00          |              |
| Labour                              | 8,090.00         | 7,135.00         | 955.00          | 11.80        |
| Paintwork Labour                    | 0.00             | 0.00             | 0.00            |              |
| Towing                              | 0.00             | 0.00             | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b> | <b>13,700.21</b> | <b>10,996.76</b> | <b>2,703.45</b> | <b>19.73</b> |
| <b>- Excess (S\$)</b>               | <b>300.00</b>    | <b>300.00</b>    | <b>0.00</b>     | <b>0.00</b>  |
| <b>Nett Amount (S\$)</b>            | <b>13,400.21</b> | <b>10,696.76</b> | <b>2,703.45</b> | <b>20.17</b> |

### INSPECTION

|                             |            |               |                                                                                                |
|-----------------------------|------------|---------------|------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 07/09/2020 |               |                                                                                                |
| Date Inspected:             | 07/09/2020 | Inspected At: | Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)<br>209 Pandan Gardens<br>Singapore 609339 |
| Estimated Period of Repair: | 14.0 days  |               |                                                                                                |

**Adjuster:** MOHD RASUL

**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars                   | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *SUNDRIES                     | Necessary     | 20.00 FS    | *20.00 FS    |
| 2   | 1   |          | *FACE, RR BUMPER              | Dented        | 748.00 FL   | *748.00 FL   |
| 3   | 4   |          | *CLIP, RR BUMPER              | Necessary     | 16.00 FL    | *16.00 FL    |
| 4   | 1   |          | *BRACKET, RR BUMPER, LH       | Check         | 28.00 FL    | *- FL        |
| 5   | 1   |          | *BRACKET, RR BUMPER, RH       | Check         | 28.00 FL    | *- FL        |
| 6   | 1   |          | *REFLECTOR LH                 | Not Necessary | 23.00 FL    | *- FL        |
| 7   | 1   |          | *REFLECTOR RH                 | Not Necessary | 23.00 FL    | *- FL        |
| 8   | 1   |          | *LAMP ASSY, COMB, RR LH       | Cracked       | 335.00 FL   | *335.00 FL   |
| 9   | 1   |          | *LAMP ASSY, COMB, RR RH       | Cracked       | 335.00 FL   | *335.00 FL   |
| 10  | 1   |          | *PANEL, RR END                | Check         | 425.00 FL   | *- FL        |
| 11  | 1   |          | *BOARD, TRUNK ROOM FLOOR      | Check         | 195.00 FL   | *- FL        |
| 12  | 1   |          | *TRIM, RR END                 | Check         | 66.00 FL    | *- FL        |
| 13  | 1   |          | *MUD GUARD, RR LH             | Not Necessary | 41.00 FL    | *- FL        |
| 14  | 1   |          | *MUD GUARD, RR RH             | Not Necessary | 41.00 FL    | *- FL        |
| 15  | 1   |          | *DUCT, RR VENTILATOR          | Not Necessary | 30.00 FL    | *- FL        |
| 16  | 1   |          | *COVER, RR VENTILATOR         | Not Necessary | 40.00 FL    | *- FL        |
| 17  | 1   |          | *BUZZER, KEYLESS OPERATIO, RR | Check         | 91.00 FL    | *- FL        |
| 18  | 1   |          | *ANT, KEYLESS OPERATION, RR   | Check         | 96.00 FL    | *- FL        |
| 19  | 1   |          | *PANEL, TRUNK LID             | Bent          | 791.00 FL   | *791.00 FL   |
| 20  | 1   |          | *WEATHERSTRIP, TRUNK LID      | Necessary     | 157.00 FL   | *157.00 FL   |
| 21  | 1   |          | *HINGE, TRUNK LID, LH         | Check         | 203.00 FL   | *- FL        |
| 22  | 1   |          | *HINGE, TRUNK LID, RH         | Check         | 203.00 FL   | *- FL        |
| 23  | 1   |          | *LATCH, TRUNK LID             | Not Necessary | 218.00 FL   | *- FL        |
| 24  | 1   |          | *STRIKER, TRUNK LID LATCH     | Not Necessary | 20.00 FL    | *- FL        |
| 25  | 1   |          | *MARK, THREE-DIA              | Necessary     | 69.00 FL    | *69.00 FL    |
| 26  | 1   |          | *MARK, ATTRAGE                | Necessary     | 21.00 FL    | *21.00 FL    |
| 27  | 1   |          | *GARNISH, RR END PANEL        | Check         | 336.00 FL   | *- FL        |
| 28  | 1   |          | *PANEL, QTR, OTR RH           | Necessary     | 763.00 FL   | *763.00 FL   |
| 29  | 1   |          | *PANEL, RR COMB LAMP HSG, RH  | Check         | 60.00 FL    | *- FL        |
| 30  | 1   |          | *EXTN, QTR PANEL, UPR OTR RH  | Check         | 118.00 FL   | *- FL        |
| 31  | 2   |          | *STOPPER WINDSHIELD GLASS     | Necessary     | 6.00 FL     | *6.00 FL     |
| 32  | 3   |          | *SPACER,RR WINDOW             | Necessary     | 27.00 FL    | *27.00 FL    |
| 33  | 1   |          | *UNPAINTED BODYKITS           | Cracked       | 1,643.00 FN | *1,643.00 FN |

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

|                                                    |          |          |
|----------------------------------------------------|----------|----------|
| Sub Total (S\$)                                    | 7,216.00 | 4,931.00 |
| - List Item Discount on L Items 23.00/23.00% (S\$) | 1,277.19 | 751.64   |
| - Nett Item Discount on N Items 20.00/20.00% (S\$) | 328.60   | 328.60   |
| Total Parts (S\$)                                  | 5,610.21 | 3,850.76 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

| No                         | Qty | Particulars           | Repairer's | Amount |
|----------------------------|-----|-----------------------|------------|--------|
| <u>Miscellaneous Items</u> |     |                       |            |        |
| 1                          | 1   | *OD/TP Case (Insurer) | -          | 11.00  |
| Sub Total (\$\$)           |     |                       | 0.00       | 11.00  |

Recommended Labour

| No                       | Particulars                                                                                                       | Lab.Type | Repairer's | Amount   |
|--------------------------|-------------------------------------------------------------------------------------------------------------------|----------|------------|----------|
| <u>Labour Items</u>      |                                                                                                                   |          |            |          |
| 1                        | RENEW RR BUMPER, BODY KIT, BOOTLID, RR END & RHR FENDER REPAIR LHR FENDER & RR FLR PNL                            | New      | 4,050.00   | 3,600.00 |
| 2                        | RESURVEY RR BUMPER, RR BUMPER BODY KIT, RR END PNL, RR LR PNL, BOOTLID, BOOT LID SPOILER, LHF FENDER & RHR FENDER | New      | 2,800.00   | 2,625.00 |
| 3                        | REMOVE & REFIT BOOTLID COMPONENT                                                                                  | New      | 120.00     | 120.00   |
| 4                        | REMOVE & REFIT RR FLR BOARD, TRIM, SEAT & CARPET                                                                  | New      | 120.00     | 120.00   |
| 5                        | CHECK WIRING ELECTRICAL SYSTEM                                                                                    | New      | 30.00      | 30.00    |
| 6                        | TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST                                       | New      | 120.00     | 120.00   |
| 7                        | APPLY ANTI CORROSION ON AFFECTED AREAS                                                                            | New      | 80.00      | 40.00    |
| 8                        | SUPPLY BODY PNL SEALANT                                                                                           | New      | 80.00      | 60.00    |
| 9                        | REMOVE & REFIT RR WINDSCREEN GLASS                                                                                | New      | 240.00     | 240.00   |
| 10                       | SUPPLY WINDSCREEN SEALANT                                                                                         | New      | 80.00      | 80.00    |
| 11                       | SUPPLY RR NUMBER PLATE WITH CASING                                                                                | New      | 50.00      | 0.00     |
| 12                       | REMOVE & REFIT REVERSE SENSOR                                                                                     | New      | 60.00      | 60.00    |
| 13                       | SUPPLY REVERSE SENSOR                                                                                             | New      | 220.00     | 0.00     |
| 14                       | SUPPLY C&C BADGE                                                                                                  | New      | 40.00      | 40.00    |
| Gross Labour Cost (\$\$) |                                                                                                                   |          | 8,090.00   | 7,135.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >