



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV11985/LOW MAGGIE
	Reg No/Reg Date	SDQ1191M / 03/09/201
	Date In/Mileage	/ 12665
	Chassis No	MMBSTA13AKH001878
	Engine No	3A92UHT1659
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	07/09/2020/ 13:40	BLE	261 / Edwin Caina	57049			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								3600 4050.00
RENEW RR BUMPER , BODY KIT , BOOTLID , RR END & RHR FENDER								
REPAIR LHR FENDER & RR FLR PNL								2625 2800.00
E PNT98000								
RESPRAY RR BUMPER , RR BUMPER BODY KIT , RR END PNL , RR FLR PNL ,								
BOOTLID , BOOTLID SPOILER , LHF FENDER & RHR FENDER								120.00
E PNT88000								120.00
REMOVE & REFIT BOOTLID COMPONENT								
E PNT88000								30.00
REMOVE & REFIT RR FLR BOARD,TRIM,SEAT & CARPET								120.00
A 54900099								
CHECK WIRING ELECTRICAL SYSTEM								40 80.00
A 10028901								60 80.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								240.00
M SUNDRY								50.00X
APPLY ANTI CORROSION ON AFFECTED AREAS								60 80.00
M SUNDRY								240.00
SUPPLY BODY PNL SEALANT								80.00
E PNT88000								
REMOVE & REFIT RR WINDSCREEN GLASS								50.00X
M SUNDRY								60.00
SUPPLY WINDSCREEN SEALANT								220.00
M SUNDRY								40.00
SUPPLY RR NUMBER PLATE WITH CASING								20.00
PNT88000								
REMOVE & REFIT REVERSE SENSOR								
SUNDRY								
SUPPLY REVERSE SENSOR								
SUNDRY								
SUPPLY C&C BADGE								
SUNDRY								
Sundries								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV11985/LOW MAGGIE
	Reg No/Reg Date	SDQ1191M / 03/09/201
	Date In/Mileage	/ 12665
	Chassis No	MMBSTA13AKH001878
	Engine No	3A92UHT1659
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	07/09/2020/ 13:40	BLE	261 / Edwin Caina	57049
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M FACE,RR BUMPER <i>de</i>		1.00	748.00	23.00	575.96
M CLIP,RR BUMPER <i>ren</i>		4.00	4.00	23.00	12.32
M BRACKET,RR BUMPER,LH <i>?cm</i>		1.00	28.00	23.00	21.56
M BRACKET,RR BUMPER,RH <i>?cm</i>		1.00	28.00	23.00	21.56
M REFLECTOR LH <i>XSVL</i>		1.00	23.00	23.00	17.71
M REFLECTOR RH <i>XSVL</i>		1.00	23.00	23.00	17.71
M LAMP ASSY,COMB,RR LH <i>cm</i>		1.00	335.00	23.00	257.95
M LAMP ASSY,COMB,RR RH <i>cm</i>		1.00	335.00	23.00	257.95
M PANEL,RR END <i>?cm</i>		1.00	425.00	23.00	327.25
M BOARD,TRUNK ROOM FLOOR <i>?SVLX</i>		1.00	195.00	23.00	150.15
M TRIM,RR END <i>?SVL</i>		1.00	66.00	23.00	50.82
M MUD GUARD,RR LH <i>XSVL</i>		1.00	41.00	23.00	31.57
M MUD GUARD,RR RH <i>XSVL</i>		1.00	41.00	23.00	31.57
M DUCT,RR VENTILATOR <i>XSVL</i>		1.00	30.00	23.00	23.10
M COVER,RR VENTILATOR <i>XSVL</i>		1.00	40.00	23.00	30.80
M BUZZER,KEYLESS OPERATIO,RR <i>?SVL</i>		1.00	91.00	23.00	70.07
M ANT,KEYLESS OPERATION,RR <i>?SVL</i>		1.00	96.00	23.00	73.92
M PANEL,TRUNK LID <i>cm</i>		1.00	791.00	23.00	609.07
M WEATHERSTRIP,TRUNK LID <i>ren</i>		1.00	157.00	23.00	120.89
M HINGE,TRUNK LID,LH <i>?SVL</i>		1.00	203.00	23.00	156.31
M HINGE,TRUNK LID,RH <i>?SVL</i>		1.00	203.00	23.00	156.31
M LATCH,TRUNK LID <i>XSVL</i>		1.00	218.00	23.00	167.86
M STRIKER,TRUNK LID LATCH <i>XSVL</i>		1.00	20.00	23.00	15.40
M MARK,THREE-DIA <i>ren</i>		1.00	69.00	23.00	53.13
M MARK,ATTRAGE <i>ren</i>		1.00	21.00	23.00	16.17
M GARNISH,RR END PANEL <i>?cm</i>		1.00	336.00	23.00	258.72
M PANEL,QTR,OTR RH <i>cm</i>		1.00	763.00	23.00	587.51
M PANEL,RR COMB LAMP HSG,RH <i>?cm</i>		1.00	60.00	23.00	46.20
M EXTN,QTR PANEL,UPR OTR RH <i>?cm</i>		1.00	118.00	23.00	90.86
M STOPPER,WINDSHIELD GLASS <i>ren</i>		2.00	3.00	23.00	4.62
M SPACER,RR WINDOW <i>ren</i>		3.00	9.00	23.00	20.79
M UNPAINTED BODYKITS <i>cm</i>		1.00	1643.00	23.00	1264.41
LKK Auto Consultants hence notify the Repairer of the following:		1.00	91.00	23.00	70.07
• To resurvey before/after spray painting		1.00	96.00	23.00	73.92
• To display damaged part(s) during resurvey		1.00	791.00	23.00	609.07
• Parts prices are subject to confirmation		1.00	157.00	23.00	120.89
• Third party survey is on a "Without Prejudice" basis		1.00	203.00	23.00	156.31
• No illegal modification(s) is allowed		1.00	203.00	23.00	156.31
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		1.00	218.00	23.00	167.86
Acknowledged by Repairer		1.00	20.00	23.00	15.40
Signature:		1.00	69.00	23.00	53.13
Date:		1.00	21.00	23.00	16.17
		1.00	336.00	23.00	258.72
		1.00	763.00	23.00	587.51
		1.00	60.00	23.00	46.20
		1.00	118.00	23.00	90.86
		2.00	3.00	23.00	4.62
		3.00	9.00	23.00	20.79
		1.00	1643.00	23.00	1264.41

SURVEYOR NAME: Rahul - Hp 90010088SURVEYOR SIGNATURE: [Signature]DATE: 07/09/2020 @ 1620REMARKS: 14 days

EXCESS: TBA / REVERT

Authorized signatory and company stamp

Returning before print

Nett	13,700.21
7% GST on	959.01

Total Payable	14,659.22
---------------	-----------

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.