

Date: 05/09/2020
Vehicle No: SMP4931Z
Model: TOYOTA NOAH HYBRID 1.8X
Chassis: ZWR800402802-2019
Reg. Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SMD1246B
Date of Accident: 03.09.2020

Not Authorised
Resurvey B4 paint *4 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1	<i>Res</i>	\$727.20
2	FRONT BUMPER CLIPS	10	\$5.80	<i>Res</i> \$58.00
2	FRONT BUMPER SIDE BRACKET RH	1		<i>DIT</i> \$97.40
3	FRONT HEADLAMP RH	1	<i>Res</i>	\$2,228.20
4	FRONT FENDER RH	1	<i>Res</i>	\$1,152.20
4	FRONT FENDER RH	1	<i>Res</i>	\$107.00
5	FRONT FENDER 'HYBRID' EMBLEM RH	1	<i>Res</i>	\$126.90
6	FRONT FOGLAMP COVER RH	1		\$305.20
7	FRONT BUMPER REINFORCEMENT	1		<i>Res</i> \$127.60
8	FRONT BUMPER CENTER GARNISH	1		
SUB TOTAL				\$4,929.70
LESS 25%				-\$1,232.43
PARTS TOTAL				\$3,697.28

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST, DISMANTLE ACCIDENT AREA. \$800.00 *4000*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA. \$700.00 *4400*

LABOUR CHARGES TO DIAGNOSE FAULTY CODE & RESET MEMOR (HEADLAMP). \$150.00 *?*

LABOUR CHARGES TO DISCONNECT & RECONNECT FRONT WIRING SYSTEM & ETC. TO EFFECT REPAIR AT FRONT ACCIDENT AREAS & ETC. \$150.00 *200*

TO WHEEL ALIGNMENT & BALANCING. *Res* \$100.00 *X*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LABOUR TOTAL \$1,900.00

TOTAL \$5,597.28

VICTOR

Acknowledged by Repairer
Signature:
Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

452 Tagore Industrial Avenue Singapore 787823
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

