

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:visionautowork@gmail.com

DATE : 08.09.20

TO : **BUDGET DIRECT** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLW9366Y**
MODEL : **HYUNDAI ELANTRA** Xiao Chen
DATE OF ACCIDENT : 05.09.20
TIME OF ACCIDENT : 16:10HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Rebond</i>	1	\$ 459.40	\$ 459.40
2	REAR BUMPER MUDFLAP RH <i>Nbr m</i>	1	\$ 159.00	\$ 159.00
3	REAR BUMPER REFLECTOR RH <i>lit</i>	1	\$ 40.80	\$ 40.80
4	REAR BUMPER LOWER LIP <i>lit</i>	1	\$ 250.10	\$ 250.10
5	REAR BUMPER RETAINER <i>Nbr RH.</i>	2	\$ 44.30	\$ 88.60
6	REAR BUMPER REINFORCEMENT <i>Best.</i>	1	\$ 294.80	\$ 294.80
7	REAR BUMPER BRACKET <i>Nbr m</i>	5	\$ 6.00	\$ 30.00
8	REAR BUMPER INNER GRANISH RH <i>3x2</i>	1	\$ 15.00	\$ 15.00
9	REAR BUMPER LOWER GARNISH RH <i>3x2</i>	1	\$ 37.20	\$ 37.20
10	TAILLAMP RH <i>Cracked.</i>	1	\$ 876.00	\$ 876.00
11	TAILLAMP PANEL RH <i>Repis</i>	1	\$ 197.40	\$ 197.40
12	BOOTLID LAMP RH <i>Nbr m</i>	1	\$ 664.20	\$ 664.20
13	REAR END PANEL <i>Rebond.</i>	1	\$ 454.60	\$ 454.60
14	REAR END PANEL TOP GARNISH <i>Nbr m</i>	1	\$ 59.80	\$ 59.80
15	REAR FENDER RH <i>Repis</i>	1	\$ 1,470.00	\$ 1,470.00
16	REAR FENDER COWLING RH <i>Nbr m</i>	1	\$ 250.00	\$ 250.00
17	REAR FENDER INNER TRIM <i>Nbr m</i>	2	\$ 208.00	\$ 416.00
18	REAR FENDER AIR VENT RH <i>Nbr m</i>	1	\$ 107.40	\$ 107.40
19	REAR WINDSCREEN MOULDING <i>Nbr m</i>	1	\$ 180.00	\$ 180.00

252740

TOTAL PRICE \$ 6,050.30

LESS 20% \$ 1,210.06

SUB TOTAL PRICE \$ 4,840.24

202192

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>Nbr</i>	1	\$ 80.00	\$ 80.00
2	TAILLAMP CLIP RH (SET) <i>Nbr</i>	1	\$ 30.00	\$ 30.00

TO : **BUDGET DIRECT** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLW9366Y**
 MODEL : **HYUNDAI ELANTRA**
 DATE OF ACCIDENT : 05.09.20
 TIME OF ACCIDENT : 16:10HRS

3	TAILLAMP PANEL SEALANT RH <i>Ne m</i>	1	\$ 60.00	\$ 60.00	+
4	REAR FENDER SEALANT RH <i>Ne m</i>	1	\$ 150.00	\$ 150.00	+
5	REAR FENDER COWLING CLIP (SET) <i>Ne m</i>	1	\$ 80.00	\$ 80.00	+
6	REAR FENDER INNER TRIM CLIP (SET) <i>Ne m</i>	1	\$ 80.00	\$ 80.00	+
7	REAR WINDSCREEN GLASS SEALANT <i>Ne m</i>	1	\$ 80.00	\$ 80.00	+
8	REAR WINDSCREE GLASS INNER SHIELD RH <i>Ne m</i>	1	\$ 60.00	\$ 60.00	+
9	REAR END PANEL INSULATION SEAL <i>Ne m</i>	1	\$ 150.00	\$ 150.00	60
10	REAR END PANEL TOP GARNISH CLIP (SET) <i>Ne m</i>	1	\$ 60.00	\$ 60.00	+
11	REVERSE SENSOR (SET) <i>Not Ne m</i>	1	\$ 220.00	\$ 220.00	+

100
TOTAL \$ 1,050.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (SIDE)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	<i>600</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	<i>600</i>
3	TUFF COAT	\$ 250.00	<i>50</i>
4	WIRING CHECK	\$ 250.00	<i>30</i>
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>60</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	REMOVE & REFIX REAR WINDSCREEN	\$ 120.00	<i>x</i>
8	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	<i>x</i>
9	CONDUCT WATER LEAKAGE TEST	\$ 120.00	<i>x</i>
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	<i>x</i>

TOTAL \$ 4,500.00

1390

TO : **BUDGET DIRECT** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLW9366Y**
MODEL : **HYUNDAI ELANTRA**
DATE OF ACCIDENT : 05.09.20
TIME OF ACCIDENT : 16:10HRS

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,890.24
TOTAL LABOUR COST : \$ 4,500.00
TOTAL REPAIR COST : \$ 10,390.24

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
ABBY
HP : 9856 4815

Adrian Ling
L/s 09/09/20.

05 Days.

total: 3511.92
L/s: 2.8k.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: