



TAY CHIN HOON
NO. 31 #02-07
PUNGGOL FIELD
SINGAPORE 828816

File No : SH/2020/082/09/002/TP
Date : 10-September-2020

Supplementary estimated cost of repair for vehicle no: SML3892E HYUNDAI AVANTE
Accident involving vehicle no: SML3892E & SML9100T on 04-September-2020

Description	Quantity	List Price
Rear bumper lower cover CRA	1	\$ 68.20
Rear bumper inner antenna DAM	1	\$ 353.50
		\$ 421.70
	Less 20%	\$ 84.34
		\$ 337.36
Rear number plate NEC	1	SN \$ 45.00
		\$ 382.36

T/Party: AIG ASIA PACIFIC INSURANCE PTE LTD