

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 7-Sep-20

INSURANCE: EQ

MODEL: TOYOTA PRIUS



VEHICLE NO.: SH6002M

DESCRIPTION	QTY	LIST PRICE	AMOUNT	
REAR FENDER, LH <i>Dented</i>	1	\$836.70	\$836.70	✓
REAR FENDER INNER PANEL (LH) <i>HH</i>	1	\$728.00	\$728.00	X
REAR FENDER REINFORCEMENT, ROCKER, PANEL, LH <i>HH</i>	1	\$552.30	\$552.30	X
PANEL SUB-ASSY, REAR DOOR, LH <i>Dented</i>	1	\$1,258.30	\$1,258.30	✓
REAR DOOR HINGE UPPER <i>HH</i>	1	\$82.30	\$82.30	X
REAR DOOR HINGE LOWER <i>HH</i>	1	\$82.30	\$82.30	X
REAR DOOR CHECK <i>HH</i>	1	\$153.00	\$153.00	X
REAR DOOR TRIMBOARD <i>HH</i>	1	\$725.00	\$725.00	X
MOTOR, POWER WINDOW REGULATOR FRT, LH <i>NH</i>	1	\$941.80	\$941.80	X
REGULATOR, FRONT DOOR WINDOW REAR, LH <i>NH</i>	1	\$228.40	\$228.40	X
Door Centre Pillar Outer (LH) <i>Dented</i>	1	\$1,590.60	\$1,590.60	✓
Door Centre Pillar enforcement (LH) <i>NH</i>	1	\$863.30	\$863.30	X
PANEL SUB-ASSY, FRONT DOOR, LH <i>Dented</i>	1	\$1,264.00	\$1,264.00	✓
FRONT DOOR OUTER HANDLE (LH) <i>cut</i>	1	\$378.90	\$378.90	✓
FRONT DOOR HANDLE BASE <i>NH</i>	1	\$287.70	\$287.70	X
FRONT DOOR KEY LOCK SET <i>NH</i>	1	\$428.90	\$428.90	X
FRONT DOOR WHETHER STRIP <i>SVL</i>	1	\$457.90	\$457.90	X
FRONT DOOR RUBBER SEAL <i>cut (distorted)</i>	1	\$257.00	\$257.00	✓
MOTOR ASSY, POWER WINDOW FRT, LH <i>HH</i>	1	\$941.80	\$941.80	X
REGULATOR, FRONT DOOR WINDOW FRT, LH <i>HH</i>	1	\$228.40	\$228.40	X
MIRROR ASSY, OUTER REAR VIEW, LH <i>broken</i>	1	\$1,728.70	\$1,728.70	✓
GLASS, SUB-ASSY, FRONT DOOR, LH <i>crack</i>	1	\$780.50	\$780.50	✓
MOULDING, REAR DOOR WINDOW, FRONT LH <i>vt</i>	1	\$69.20	\$69.20	✓
KEY LOCK ANTENNA <i>HH</i>	1	\$312.00	\$312.00	X
FRONT DOOR COMFORT LOGO <i>hec</i>	1 <i>SN</i>	\$75.00	\$75.00	✓
REAR TYRE RIM (LH) <i>2 distorted</i>	1	\$1,555.00	\$1,555.00	2 ✓
REAR WHEEL HUB CAP (LH) <i>cut</i>	1	\$177.70	\$177.70	✓
REAR WHEEL BEARING & HUB assy <i>2 Done</i>	1	\$610.20	\$610.20	2 ✓
REAR CROSS MEMBER <i>HH</i>	1	\$2,200.40	\$2,200.40	X
REAR SHOCK ABSORBER <i>2 distorted</i>	1	\$118.30	\$118.30	2 ✓
REAR SHOCK ABSORBER MOUNTING <i>HH</i>	1	\$125.30	\$125.30	X
REAR LOWER ARM <i>2 distorted</i>	1	\$497.50	\$497.50	2 ✓
REAR UPPER ARM <i>2 distorted</i>	1	\$356.80	\$356.80	2 ✓
REAR KNUCKLE ARM <i>2 distorted</i>	1	\$810.60	\$810.60	2 ✓
REAR COIL SPRING <i>HH</i>	1	\$191.40	\$191.40	X
REAR COIL SPRING MOUNTING <i>HH</i>	1	\$125.70	\$125.70	X
REAR BRAKE ABS SENSOR (WIRE) <i>HH</i>	1	\$278.80	\$278.80	X
REAR STABILIZER BAR <i>HH</i>	1	\$311.50	\$311.50	X
REAR STABILIZER LINK <i>HH</i>	1	\$151.60	\$151.60	X
REAR TRAILING ARM <i>2 distorted</i>	1	\$314.20	\$314.20	2 ✓
REAR ASSIST ARM <i>2 distorted</i>	1	\$342.20	\$342.20	2 ✓

REAR HEIGHT SENSOR LH only NH	1	\$789.30	\$789.30	X
SUB TOTAL			\$24,208.50	
LESS 20%			\$4,841.70	
DISCOUNTED TOTAL			\$19,366.80	
REAR DOOR COMFORT & APPS STICKER NH	1	\$80.00	\$80.00	✓
REAR TYRE (LH) NH	1	\$216.00	\$216.00	X
SUB TOTAL			\$296.00	
Labour Charge				
Panel Beating	1	\$1,400.00	\$1,400.00	800/-
Spray Painting Charge	1	\$1,200.00	\$1,200.00	800/-
Wiring Charge	1	\$140.00	\$140.00	NH
Tuff Kote	1	\$160.00	\$160.00	40/-
Towing Charge	1	\$80.00	\$80.00	NH
Remove/Refix Cushion & Upholstery Rear	1	\$150.00	\$150.00	80/-
Remove/Refix Undercarriage (RR)	1	\$400.00	\$400.00	150/-
Re-set Rear ABS System	1	\$400.00	\$400.00	NH
Transfer of Door Mechanism FRONT	1	\$80.00	\$80.00	60/-
Re-set Frt Power Window System	1	\$200.00	\$200.00	NH
Transfer of Door Mechanism REAR	1	\$80.00	\$80.00	60/-
Re-set Rear Power Window System	1	\$200.00	\$200.00	NH
Four Wheel Alignment	1	\$120.00	\$120.00	60/-
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	150/-
TOTAL LABOUR			\$5,160.00	
ESTIMATE TOTAL			\$24,822.80	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

08/09/2020 @ 1730hrs
 N/A Auction
 L/Sure 7 days.


 you
 LKK Auto


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

BIFROST AUTO PTE LTD

REPAIR SUPPLEMENTARY

DATE: 9-Sep-20

INSURANCE: EQ

MODEL: TOYOTA PRIUS

VEHICLE NO.: SH6002M (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
FENDER SUB-ASSY, FRONT LH <i>Dented</i>	1	\$945.30	\$945.30
FRONT FENDER HYBRID EMBLEM, LH <i>New</i>	1	\$86.50	\$86.50
FRONT WHEEL RIM <i>RH dented</i>	1	\$1,570.55	\$1,570.55
FRONT WHEEL HUB BEARING & HUB ASSY (RH) <i>Dam</i>	1	\$678.50	\$678.50
FRONT SUSPENSION LOWER ARM (RH) <i>dented</i>	1	\$631.90	\$631.90
FRONT SHOCK ABSORBER (RH) <i>dented</i>	1	\$398.20	\$398.20
ABSORBER TOP MOUNTING <i>NH</i>	1	\$196.20	\$196.20
KNUCKLE, STEERING, RH <i>dented</i>	1	\$580.80	\$580.80
JOINT ASSY, LOWER BALL, FRONT (RH) <i>NH</i>	1	\$199.98	\$199.98
END SUB-ASSY, TIE ROD, RH <i>dented</i>	1	\$159.30	\$159.30
SUB TOTAL			\$5,447.23
LESS 20% <i>25%</i>			\$1,089.45
DISCOUNTED TOTAL			\$4,357.78
FRONT TYRE (RH) <i>NH</i>	SN 1	\$216.00	\$216.00
SUB TOTAL			\$216.00
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Iyan
15/09/2020
LKK Ando

[Signature]

✓
 ✓
 ✓
 ✓
 ✓
 ✓
 X
 ✓
 X
 ✓
 X