



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

8/9/20, 10.00 am

wil pte

Stere (LKK)

L/S

DATE : 07-09-2020

Ry AL Spj

6 days

LONPAC INSURANCE BHD

300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555

VEHICLE NO. : YN5192B

ACCIDENT DATE : 04-09-2020 16:00

THIRD PARTY REF. : YM6866P

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE YN5192B MITSUBISHI CANTER FEB71ER4SDEC

QTY PARTS DESCRIPTION

SPECIAL NETT ITEMS

- | | | | |
|---|---|--|-------------------|
| 1 | 1 | TO FABRICATE REAR WOODEN CABIN | BT (Local repair) |
| 2 | 1 | TO SUPPLY & RENEW REAR WOODEN CAGINE REINFORCEMENT | 1 X NM |
| 3 | 1 | BEAMS REAR NO. PLATE | X NM |

TOTAL (C)

AMOUNT (SG\$)

7800.00	1800 ✓
2000.00	X
30.00	X
9,830.00	

LABOUR CHARGES

- | | | | | |
|---|---|---|------|---------|
| 1 | 1 | REMOVE & REFIX REAR WOODEN CABIN | 400 | 580.00 |
| 2 | 1 | TO CHECK WIRING SYSTEM | 30 | 50.00 |
| 3 | 1 | REMOVE ALL NECESSARY AFFECTED PARTS FOR REPAIRS, WELD/CUT, PANEL BE-
ATING & RENEW PARTS, STRAIGHT CHASSIS FRAME | 1200 | 1580.00 |
| 4 | 1 | SPRAY PAINTING | 400 | 850.00 |

TOTAL (D)

3,060.00

ESTIMATE TOTAL

12,890.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: