

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III20009569/R1ES3Q2  
**Date:** 16/06/2021**REFERENCE**

|                              |                                       |                             |                  |
|------------------------------|---------------------------------------|-----------------------------|------------------|
| Handling Insurer:            | India International Insurance Pte Ltd | Policy No:                  | D19MPC0002427_01 |
| <b>Claimant Vehicle No :</b> | SMA1496L                              | <b>Insured Vehicle No :</b> | SMA2856A         |
| Date of Loss:                | 04/09/2020                            | Nature of Claim:            | TP               |
|                              |                                       | Claim No:                   | MPC2020D0001702  |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SMA1496L</b>                   |             |                   |
| Make & Model:               | HYUNDAI ELANTRA, 1.6 AD GLS (A)   | Engine No:  | G4FGJU184508      |
| Reg. Date:                  | 30/05/2018 (Man. Year: 2018)      | Chassis No: | KMHD841CMJU684791 |
| Colour:                     | Red                               | Odometer:   | 53547 km          |
| Engine Capacity:            | 1591 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 215/45 R17    | Rear Tyre Size:  | 215/45 R17    |
| Front Left Side:  | Yokohama 6 mm | Rear Left Side:  | Yokohama 6 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 10,818.16         | 6,442.16          | 4,376.00          | 40.45         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 4,840.00          | 2,200.00          | 2,640.00          | 54.55         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>15,658.16</b>  | <b>8,642.16</b>   | <b>7,016.00</b>   | <b>44.81</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>6,900.00</b>   |                   |               |

|                                                 |                  |                 |                 |              |
|-------------------------------------------------|------------------|-----------------|-----------------|--------------|
| (S\$)                                           | 15,658.16        | 6,900.00        | 8,758.16        | 55.93        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 1,096.07         | 483.00          | 613.07          | 55.93        |
| <b>Nett Amount (S\$)</b>                        | <b>16,754.23</b> | <b>7,383.00</b> | <b>9,371.23</b> | <b>55.93</b> |
| <b>+ Car Rental (7.0 x S\$100.00/day) (S\$)</b> |                  | 700.00          |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                  | 29.00           |                 |              |
| <b>Nett Liability (S\$)</b>                     |                  | <b>8,112.00</b> |                 |              |
| <b>Global Sum Settlement (S\$)</b>              |                  | <b>8,000.00</b> |                 |              |

INSPECTION

Date of Assignment: 08/09/2020

Date Inspected: 08/09/2020

Estimated Period of Repair: 8.0 days

Inspected At: BLK 1008 BUKIT MERAH LANE 3 #01-04  
Repairer: Cas Garage Pte Ltd (HQ)**Adjuster:** MOHD RASUL**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                  |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 22 Dec 2020)                    |
| <b>Parts:</b>        | 143                                                                                                                                                                          | HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SMA1496L)                                                                                                                                    |                                                                  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                  |

### Recommended Parts

| No. | Qty | Part No. | Particulars                             | Condition   | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------------------|-------------|-------------|--------------|
| 1   | 1   |          | *BOOTLID                                | Bent        | 1,785.20 FL | *1,785.20 FL |
| 2   | 1   |          | *BOOTLID SMART KEY ANTENNA              | Cracked     | 198.70 FL   | *198.70 FL   |
| 3   | 1   |          | *BOOTLID INNER TRIM                     | Serviceable | 406.20 FL   | *- FL        |
| 4   | 2   |          | *BOOTLID REFLECTORS                     | Cracked     | 797.20 FL   | *797.20 FL   |
| 5   | 1   |          | *BOOTLID EMBLEM ELANTRA                 | Necessary   | 95.30 FL    | *95.30 FL    |
| 6   | 1   |          | *BOOTLID EMBLEM S                       | Necessary   | 72.30 FL    | *72.30 FL    |
| 7   | 1   |          | *BOOTLID LOGO                           | Necessary   | 95.40 FL    | *95.40 FL    |
| 8   | 1   |          | *BOOTLID INNER LOCK                     | Scratched   | 235.60 FL   | *235.60 FL   |
| 9   | 1   |          | *BOOTLID LOWER LATCH                    | Serviceable | 45.20 FL    | *- FL        |
| 10  | 1   |          | *BOOTLID WEATHERSTRIP                   | Necessary   | 198.60 FL   | *198.60 FL   |
| 11  | 1   |          | *REAR BUMPER                            | Cracked     | 645.30 FL   | *645.30 FL   |
| 12  | 2   |          | *REAR BUMPER REFLECTORS                 | Cracked     | 191.20 FL   | *191.20 FL   |
| 13  | 2   |          | *REAR BUMPER RETAINERS                  | Serviceable | 173.40 FL   | *- FL        |
| 14  | 1   |          | *REAR BUMPER REINFORCEMENT              | Bent        | 378.10 FL   | *378.10 FL   |
| 15  | 2   |          | *REAR REINFORCEMENT BRACKETS            | Serviceable | 179.40 FL   | *- FL        |
| 16  | 2   |          | *REAR BUMPER COVERS                     | Serviceable | 392.60 FL   | *- FL        |
| 17  | 2   |          | *TAILLAMPS                              | Scratched   | 847.20 FL   | *847.20 FL   |
| 18  | 2   |          | *REAR FENDER INNER COWLING              | Serviceable | 397.20 FL   | *- FL        |
| 19  | 1   |          | *SPARE TYRE FLOOR PANEL                 | Repair      | 689.70 FL   | *- FL        |
| 20  | 1   |          | *SPARE TYRE TOP BOARD                   | Serviceable | 398.80 FL   | *- FL        |
| 21  | 1   |          | *REAR END PANEL                         | Bent        | 585.90 FL   | *585.90 FL   |
| 22  | 1   |          | *END PANEL BOOT RELEASE ANTENNA         | Scratched   | 198.60 FL   | *198.60 FL   |
| 23  | 1   |          | *REAR END PANEL TOP GARNISH             | Deformed    | 215.60 FL   | *215.60 FL   |
| 24  | 1   |          | *SET REAR NUMBER PLATE WITH CASING      | Serviceable | 50.00 FS    | *- FS        |
| 25  | 1   |          | *REAR BUMPER CLIPS                      | Necessary   | 30.00 FS    | *30.00 FS    |
| 26  | 1   |          | *REAR BOOTLID SPOILER (ACCESSORIES)     | Necessary   | 500.00 FS   | *250.00 FS   |
| 27  | 1   |          | *SET REAR BOOTLID STICKER (ACCESSORIES) | Necessary   | 380.00 FS   | *200.00 FS   |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                           | Condition     | Repairer's | Amount     |
|-----|-----|----------|---------------------------------------|---------------|------------|------------|
| 28  | 1   |          | *REAR BUMPER DIFFUSER (ACCESSORIES)   | Cracked       | 950.00 FS  | *400.00 FS |
| 29  | 1   |          | *REAR BUMPER CENTRE LAMP              | Serviceable   | 150.00 FS  | *- FS      |
| 30  | 2   |          | *REAR BUMPER EXHAUST TIP              | Serviceable   | 400.00 FS  | *- FS      |
| 31  | 1   |          | *REAR BUMPER STICKER (ACCESSORIES)    | Necessary     | 380.00 FS  | *100.00 FS |
| 32  | 1   |          | *SET REAR END PANEL TOP GARNISH CLIPS | Necessary     | 30.00 FS   | *30.00 FS  |
| 33  | 1   |          | *EMERGENCY STOP SIGN                  | Serviceable   | 180.00 FS  | *- FS      |
| 34  | 1   |          | *SET REVERSE SENSORS                  | Not Working   | 250.00 FS  | *200.00 FS |
| 35  | 2   |          | *SET REAR FENDER INNER COWLING        | Serviceable   | 60.00 FS   | *- FS      |
| 36  | 2   |          | *END PANEL INSULATOR SEAL             | Not Necessary | 80.00 FS   | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                  |                 |
|----------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>12,662.70</b> | <b>7,750.20</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$)</b> | 1,844.54         | 1,308.04        |
| <b>Total Parts (\$)</b>                                  | <b>10,818.16</b> | <b>6,442.16</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                              | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |                                                                          |          |                 |                 |
| 1                               | TO RENEW DAMAGED PARTS ,REPLACE BEAT ,WELD ,REALIGN AND ALIGNE ALL PARTS | New      | 1,800.00        | 1,000.00        |
| 2                               | TO RESPRAY AFFECTED AREAS                                                | New      | 1,800.00        | 800.00          |
| 3                               | TO TUFFCOAT AFFECTED AREA                                                | New      | 200.00          | 80.00           |
| 4                               | TO REMOVE/REFIT INTERIOR UPHOLSTERY                                      | New      | 150.00          | 60.00           |
| 5                               | TO APPLY SEALANT AND UNDERCOATING TO THE AFFECTED AREAS                  | New      | 350.00          | 80.00           |
| 6                               | TO REMOVE/REFIT WIRING CHECKS ON REAR TAILAMP                            | New      | 120.00          | 30.00           |
| 7                               | TO CONDUCT WATER LEAKAGE TEST                                            | New      | 150.00          | 30.00           |
| 8                               | TO REMOVE/REPLACE REVERSE SENSORS AND DISTANCE SETTLING                  | New      | 150.00          | 60.00           |
| 9                               | TO REMOVE/TRANSFER & REPLACE BOOTLID MECHANISM                           | New      | 120.00          | 60.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                                                          |          | <b>4,840.00</b> | <b>2,200.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >