



Address : 1, Kaki Bukit Avenue 6 #02-22/20 Autobay S(417883)

Reg: 201828067M

VEHICLE REPAIR ESTIMATE

Insurance Company: INDIA INTERNATIONAL INSURANCE PTE LTD

Address: 64, CECIL STREET, #04-05
IOB BUILDING, S(049711)

Telephone: 63476100

Fax: 62244174

Email: motorclaim@iii.com.sg

Make/ Model : HYUNDAI ELANTRA

Date: 09.09.2020

Chassis No : KMHD841CMJU684791

Vehicle No: SMA1496L

Date/Time of Accide 04.09.2020/ 1020

Date of Reg: 30.05.2018

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	FINAL PRICE \$
1	BOOTLID <i>bt</i>	1	\$ 1,785.20	\$ 1,785.20
2	BOOTLID SMART KEY ANTENNA <i>cm</i>	1	\$ 198.70	\$ 198.70
4	BOOTLID INNER TRIM <i>X SVL</i>	1	\$ 406.20	\$ 406.20 X
5	BOOTLID REFLECTORS <i>? cm</i>	2	\$ 398.60	\$ 797.20 X
6	BOOTLID EMBLEM "ELANTRA" <i>ne</i>	1	\$ 95.30	\$ 95.30
7	BOOTLID EMBLEM "S" <i>ne</i>	1	\$ 72.30	\$ 72.30
8	BOOTLID LOGO <i>ne</i>	1	\$ 95.40	\$ 95.40
9	BOOTLID INNER LOCK <i>X SVL</i>	1	\$ 235.60	\$ 235.60
10	BOOTLID LOWER LATCH <i>X SVL</i>	1	\$ 45.20	\$ 45.20 X
11	BOOTLID WEATHERSTRIP <i>ne</i>	1	\$ 198.60	\$ 198.60
12	REAR BUMPER <i>cm</i>	1	\$ 645.30	\$ 645.30
13	REAR BUMPER REFLECTORS <i>cm</i>	2	\$ 95.60	\$ 191.20
14	REAR BUMPER RETAINERS <i>X SVL</i>	2	\$ 86.70	\$ 173.40 X
15	REAR BUMPER REINFORCEMENT <i>bt</i>	1	\$ 378.10	\$ 378.10
16	REAR REINFORCEMENT BRACKETS <i>X SVL</i>	2	\$ 89.70	\$ 179.40 X
17	REAR BUMPER COVERS <i>X SVL</i>	2	\$ 196.30	\$ 392.60 X
18	TAILAMPS <i>sc</i>	2	\$ 423.60	\$ 847.20
19	REAR FENDER INNER COWLING <i>X SVL</i>	2	\$ 198.60	\$ 397.20 X
20	SPARE TYRE FLOOR PANEL <i>repair</i>	1	\$ 689.70	\$ 689.70 XR
21	SPARE TYRE TOP BOARD <i>X SVL</i>	1	\$ 398.80	\$ 398.80 X
22	REAR END PANEL <i>bt</i>	1	\$ 585.90	\$ 585.90
23	END PANEL BOOT RELEASE ANTENNA <i>sc</i>	1	\$ 198.60	\$ 198.60
24	REAR END PANEL TOP GARNISH <i>de</i>	1	\$ 215.60	\$ 215.60
Total List Price Cost				\$ 9,222.70
PARTS DISCOUNT 20%				\$ 7,378.16

6540.20

20%

5232.16

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	REAR NUMBER PLATE WITH CASING <i>X SVL</i>	1 SET	\$ 50.00	\$ 50.00 <i>X</i>
2	REAR BUMPER CLIPS <i>ne</i>	1 SET	\$ 30.00	\$ 30.00
3	REAR BOOTLID SPOILER (ACCESSORIES) <i>ne</i>	1	\$ 500.00	\$ 250 500.00 <i>X</i>
4	REAR BOOTLID STICKER (ACCESSORIES) <i>ne</i>	1 SET	\$ 380.00	\$ 200 380.00
5	REAR BUMPER DIFFUSER (ACCESSORIES) <i>ne</i>	1	\$ 950.00	\$ 400 950.00
6	REAR BUMPER CENTRE LAMP <i>X SVL</i>	1	\$ 150.00	\$ 150.00 <i>X</i>
7	REAR BUMPER EXHAUST TIP <i>X SVL</i>	2	\$ 200.00	\$ 400.00 <i>X</i>
8	REAR BUMPER STICKER (ACCESSORIES) <i>ne</i>	1	\$ 380.00	\$ 100 380.00
9	REAR END PANEL TOP GARNISH CLIPS <i>ne</i>	1 SET	\$ 30.00	\$ 30.00
10	EMERGENCY STOP SIGN <i>X SVL</i>	1	\$ 180.00	\$ 180.00 <i>X</i>
11	REVERSE SENSORS <i>ne</i>	1 SET	\$ 250.00	\$ 200 250.00
12	REAR FENDER INNER COWLING SET <i>X SVL</i>	2 SET	\$ 60.00	\$ 60.00 <i>X</i>
13	END PANEL INSULATOR SEAL <i>X nn</i>	2	\$ 80.00	\$ 80.00 <i>X</i>
Total Special Nett Items				\$ 3,440.00

Labour Works/ Panel Beating Related Works

Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	\$ 1,800.00 <i>1000</i>

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,800.00 <i>800</i>

Others Cost (Accident Repair Related Expenses)

Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 200.00 <i>80</i>
TO REMOVE/ REFIT INTERIOR UPHOLSTERY	\$ 150.00 <i>60</i>
TO APPLY SEALANT AND UNDERCOATING TO THE AFFECTED AREAS	\$ 350.00 <i>80</i>
TO REMOVE/ REFIT WIRING CHECKS ON REAR TAILAMP	\$ 120.00 <i>30</i>
TO CONDUCT WATER LEAKAGE TEST	\$ 150.00 <i>30</i>
TO REMOVE/ REPLACE REVERSE SENSORS AND DISTANCE SETTLING	\$ 150.00 <i>60</i>
TO REMOVE /TRANSFER & REPLACE BOOTLID MECHANISM	\$ 120.00 <i>60</i>
Total Others Cost	\$ 1,240.00

GRAND TOTAL

\$ 15,658.16

CAS GARAGE PTE LTD

UEN 201828067M
1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
Direct Contact: +65 8782 7171
Email: allangoh.cas@gmail.com
Fax: +65 6509 9501

5232.16
1210.00
2200.00
8642.16

2020
6913.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4/5 - 6900

8 days

Ram
4p 9000068

8 days

4/3

08/09/2020 @ 1500

Repair after repair