



Address : 1, Kaki Bukit Avenue 6 #02-22/20 Autobay S(417883)

Reg: 201828067M

VEHICLE REPAIR ESTIMATE

Insurance Company: INDIA INTERNATIONAL INSURANCE PTE LTD

Address: 64, CECIL STREET, #04-05
IOB BUILDING, S(049711)

Telephone: 63476100 Fax: 62244174

Email motorclaim@iii.com.sg

Make/ Model : HYUNDAI ELANTRA

Date: 09.09.2020

Chassis No : KMHD841CMJU684791

Vehicle No: SMA1496L

Date/Time of Accide 04.09.2020/ 1020

Date of Reg: 30.05.2018

Materials Cost/ Spare Parts Cost:

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	BOOTLID <i>bt/</i>	1	\$ 1,785.20		\$ 1,785.20
2	BOOTLID SMART KEY ANTENNA <i>X</i>	1	\$ 198.70		\$ 198.70
4	BOOTLID INNER TRIM <i>X</i>	1	\$ 406.20		\$ 406.20
5	BOOTLID REFLECTORS <i>?</i>	2	\$ 398.60		\$ 797.20
6	BOOTLID EMBLEM "ELANTRA" <i>ne/</i>	1	\$ 95.30		\$ 95.30
7	BOOTLID EMBLEM "S" <i>ne/</i>	1	\$ 72.30		\$ 72.30
8	BOOTLID LOGO <i>ne/</i>	1	\$ 95.40		\$ 95.40
9	BOOTLID INNER LOCK <i>SCA/</i>	1	\$ 235.60		\$ 235.60
10	BOOTLID LOWER LATCH <i>X</i>	1	\$ 45.20		\$ 45.20
11	BOOTLID WEATHERSTRIP <i>ne/</i>	1	\$ 198.60		\$ 198.60
12	REAR BUMPER <i>cm/</i>	1	\$ 645.30		\$ 645.30
13	REAR BUMPER REFLECTORS <i>cm/</i>	2	\$ 95.60		\$ 191.20
14	REAR BUMPER RETAINERS <i>X</i>	2	\$ 86.70		\$ 173.40
15	REAR BUMPER REINFORCEMENT <i>bt/</i>	1	\$ 378.10		\$ 378.10
16	REAR REINFORCEMENT BRACKETS <i>X</i>	2	\$ 89.70		\$ 179.40
17	REAR BUMPER COVERS <i>X</i>	2	\$ 196.30		\$ 392.60
18	TAILAMPS <i>SCA/</i>	2	\$ 423.60		\$ 847.20
19	REAR FENDER INNER COWLING <i>X</i>	2	\$ 198.60		\$ 397.20
20	SPARE TYRE FLOOR PANEL <i>repair</i>	1	\$ 689.70		\$ 689.70
21	SPARE TYRE TOP BOARD <i>X</i>	1	\$ 398.80		\$ 398.80
22	REAR END PANEL <i>bt/</i>	1	\$ 585.90		\$ 585.90
23	END PANEL BOOT RELEASE ANTENNA <i>X</i>	1	\$ 198.60		\$ 198.60
24	REAR END PANEL TOP GARNISH <i>de/</i>	1	\$ 215.60		\$ 215.60
Total List Price Cost					\$ 9,222.70
PARTS DISCOUNT 20%					\$ 7,378.16

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	REAR NUMBER PLATE WITH CASING X	1 SET	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIPS ne	1 SET	\$ 30.00	\$ 30.00
3	REAR BOOTLID SPOILER (ACCESSORIES) X	1	\$ 500.00	\$ 500.00
4	REAR BOOTLID STICKER (ACCESSORIES) ne	1 SET	\$ 380.00	\$ 380.00
5	REAR BUMPER DIFFUSER (ACCESSORIES) ne	1	\$ 950.00	\$ 950.00
6	REAR BUMPER CENTRE LAMP X	1	\$ 150.00	\$ 150.00
7	REAR BUMPER EXHAUST TIP X	2	\$ 200.00	\$ 400.00
8	REAR BUMPER STICKER (ACCESSORIES) ne	1	\$ 380.00	\$ 380.00
9	REAR END PANEL TOP GARNISH CLIPS ne	1 SET	\$ 30.00	\$ 30.00
10	EMERGENCY STOP SIGN X	1	\$ 180.00	\$ 180.00
11	REVERSE SENSORS ne	1 SET	\$ 250.00	\$ 250.00
12	REAR FENDER INNER COWLING SET X	2 SET	\$ 60.00	\$ 60.00
13	END PANEL INSULATOR SEAL X	2	\$ 80.00	\$ 80.00
Total Special Nett Items				\$ 3,440.00
Labour Works/ Panel Beating Related Works				
Job Scope				Quotation
TO RENEW DAMAGED PARTS, REPLACE BEAT, WELD, REALIGN AND ALIGNE ALL PARTS				\$ 1,800.00 1000
Spray Painting				
Job Scope				Quotation
TO RESPRAY AFFECTED AREAS				\$ 1,800.00 800
Others Cost (Accident Repair Related Expenses)				
Job Scope				Quotation
TO TUFFCOAT AFFECTED AREA				\$ 200.00 80
TO REMOVE/ REFIT INTERIOR UPHOLSTERY				\$ 150.00 60
TO APPLY SEALANT AND UNDERCOATING TO THE AFFECTED AREAS				\$ 350.00 80
TO REMOVE/ REFIT WIRING CHECKS ON REAR TAILAMP				\$ 120.00 30
TO CONDUCT WATER LEAKAGE TEST				\$ 150.00 30
TO REMOVE/ REPLACE REVERSE SENSORS AND DISTANCE SETTLING				\$ 150.00 60
TO REMOVE /TRANSFER & REPLACE BOOTLID MECHANISM				\$ 120.00 60
Total Others Cost				\$ 1,240.00
GRAND TOTAL				\$ 15,658.16

CAS GARAGE PTE LTD

UEN 201828067M

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan

Direct Contact: +65 8782 7171

Email: allangoh.cas@gmail.com

Fax: +65 6509 9501

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
4p 90010068

8 days

4/3

08/07/2020 @ 1500

Repair after repair