

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:visionautowork@gmail.com

DATE : 21.09.20

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **GW4924D**
MODEL : **TOYOTA HIACE**
DATE OF ACCIDENT : 03.09.20
TIME OF ACCIDENT : 12:30HRS

LH1621009353.

Ashes

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Replaced</i>	1	\$ 680.00	\$ 680.00
2	FRONT BUMPER SIDE RETAINER <i>LH Rnd</i>	2	\$ 55.00	\$ 110.00
3	FRONT BUMPER MOULDING <i>Cut</i>	1	\$ 115.00	\$ 115.00
4	FRONT BUMPER CENTRE BRACKET <i>new</i>	1	\$ 280.00	\$ 280.00
5	FRONT BUMPER INNER AIR VENT LH <i>Replaced</i>	1	\$ 108.10	\$ 108.10
6	FRONT BUMPER INNER CROSS MEMBER <i>new</i>	1	\$ 690.00	\$ 690.00
7	CENTRE GRILLE <i>new</i>	1	\$ 598.00	\$ 598.00
8	HEADLAMP C/W HOUSING LH <i>Replaced</i>	1	\$ 720.10	\$ 720.10
9	HEADLAMP RING LH <i>new</i>	1	\$ 199.00	\$ 199.00
10	SIDE LAMP LH <i>new</i>	1	\$ 195.00	\$ 195.00
11	FRONT PANEL <i>Replaced</i>	1	\$ 1,470.00	\$ 1,470.00
12	FRONT WINDSCREEN RUBBER <i>new</i>	1	\$ 310.00	\$ 310.00
13	FRONT STEP PANEL PANEL LH <i>Replaced</i>	1	\$ 411.10	\$ 411.10
14	FRONT STEP PANEL GARNISH LH <i>new</i>	1	\$ 299.10	\$ 299.10
15	FRONT DOOR PILLAR LH <i>Replaced</i>	1	\$ 980.00	\$ 980.00
16	FRONT DOOR LH <i>Replaced</i>	1	\$ 1,580.00	\$ 1,580.00
17	FRONT DOOR INNER LOCK LH <i>new</i>	1	\$ 457.00	\$ 457.00
18	FRONT DOOR HINGE (LOWER) LH <i>Best</i>	1	\$ 125.00	\$ 125.00
19	FRONT DOOR WEATHERSTRIP LH <i>new</i>	1	\$ 370.00	\$ 370.00
20	FRONT DOOR OUTERSTRIP LH <i>new</i>	1	\$ 195.10	\$ 195.10
21	CENTER PILLAR (OUTER) LH <i>new</i>	1	\$ 896.10	\$ 896.10
22	SLIDING DOOR LH <i>new</i>	1	\$ 1,594.00	\$ 1,594.00
23	SLIDING DOOR INNER LOCK LH <i>new</i>	1	\$ 364.00	\$ 364.00
24	SLIDING DOOR INNER BOARD LH <i>new</i>	1	\$ 180.00	\$ 180.00

TOTAL PRICE \$ 12,926.60
LESS 25% \$ 3,231.65
SUB TOTAL PRICE \$ 9,694.95

2720.10
204007

158

1266

458

55

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

+

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GW4924D**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 03.09.20
 TIME OF ACCIDENT : 12:30HRS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>plate m</i>	1	\$ 80.00	\$ 80.00
2	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	CENTRE GRILLE CLIP (SET) <i>new m</i>	1	\$ 50.00	\$ 50.00
4	FRONT STEP PANEL GARNISH RH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
5	FRONT DOOR INNER TRIM CLIP (SET) <i>NP</i>	1	\$ 80.00	\$ 80.00
6	SLIDING DOOR INNER TRIM CLIP <i>new</i>	1	\$ 80.00	\$ 80.00
7	REAR SIDE PANEL SEALANT	1	\$ 150.00	\$ 150.00

TOTAL \$ 570.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 2,200.00	700.
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	500.
3	TUFF COAT	\$ 250.00	50
4	WIRING CHECK	\$ 180.00	30
5	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
6	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	X.
7	REFOCUS HEADLAMP BEAM	\$ 60.00	X
8	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
9	TRANSFER FRONT DOOR MECHANISM	\$ 80.00	✓
10	REMOVE AND REFIX FUEL TANK TO FACILITATE CENTER PILLAR REPLACEMENT	\$ 120.00	X
11	TRANSFER SLIDING DOOR MECHANISM LH	\$ 80.00	X
12	REMOVE AND REFIX DASHBOARD	\$ 650.00	X.

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **GW4924D**
MODEL : **TOYOTA HIACE**
DATE OF ACCIDENT : 03.09.20
TIME OF ACCIDENT : 12:30HRS

13	REMOVE AND REFIX FRONT WINDSCREEN	\$ 120.00	X
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$6,170.00

1360

ESTIMATE REPORT

TOTAL PARTS COST : \$ 10,264.95
TOTAL LABOUR COST : \$ 6,170.00
TOTAL REPAIR COST : \$ 16,434.95

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
ABBY
HP : 9856 4815

Adrian Lj
1/s 22/09/20.
05 Days.

total: 3450.07
1/s 2.7k.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: