

...CLAIM SUBFOLDER...(Pending for Survey Report)

Midnight Accident

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Sep 2020 16:37 Edit Reg		08 Sep 2020 00:00 Edit Adj Rpt	S\$1,335.00 Edit Estimates	S\$1,335.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: 0 , Co. Reg. No.: 0, Email: fleetsafety@cdgetaxi.com.sg									
Main Claimant: -									
Vehicle Reg. No.: SHA1330R		Date of Loss: 06/09/2020 00:00 - :59 [50 Months and 28 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / DMPC2000142H		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SMM2173Z		Policy No. (Claimant):							
		Excess:							
Repairer: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300									
Handling Insurer: ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Liu Chun Cheong]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 17/09/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHA1330R (DMPC2000142H)
[SMM2173Z]**

TP

-

Sep 6 2020 12:00AM

[0]

ComfortDelGro Engineering Pte Ltd

View

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/09/20 16:57	Adjuster Immediate Advice	 Load HTM	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/09/20 17:57	Odometer Reading	 Load JPG	☒
2	14/09/20 17:57	General View	 Load JPG	☒
3	14/09/20 17:57	General View	 Load JPG	☒
4	14/09/20 17:57	Chassis Number	 Load JPG	☒
5	14/09/20 17:57	General View	 Load JPG	☒
6	14/09/20 17:57	General View	 Load JPG	☒
7	14/09/20 17:57	General View	 Load JPG	☒
8	14/09/20 17:57	General View	 Load JPG	☒
9	14/09/20 17:57	General View	 Load JPG	☒
10	14/09/20 17:57	General View	 Load JPG	☒
11	14/09/20 17:57	General View	 Load JPG	☒
12	14/09/20 17:57	General View	 Load JPG	☒
13	14/09/20 17:57	General View	 Load JPG	☒
14	14/09/20 17:57	General View	 Load JPG	☒
15	14/09/20 17:57	General View	 Load JPG	☒
16	14/09/20 17:57	General View	 Load JPG	☒
17	14/09/20 17:57	General View	 Load JPG	☒
18	14/09/20 17:57	General View	 Load JPG	☒
19	14/09/20 17:57	General View	 Load JPG	☒
20	14/09/20 17:57	General View	 Load JPG	☒
21	14/09/20 17:57	General View	 Load JPG	☒
22	14/09/20 17:57	General View	 Load JPG	☒
23	14/09/20 17:58	After Repair Photo	 Load JPG	☒
24	14/09/20 17:58	After Repair Photo	 Load JPG	☒
25	14/09/20 17:58	After Repair Photo	 Load JPG	☒
26	14/09/20 17:58	After Repair Photo	 Load JPG	☒
27	14/09/20 17:58	After Repair Photo	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS20009575/T1TF3S2**Date:** 21/09/2020**REFERENCE**

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SHA1330R	Insured Vehicle No :	SMM2173Z
Date of Loss:	06/09/2020	Nature of Claim:	TP
		Claim No:	DMPC2000142H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1330R		
Make & Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Engine No:	D4FDGU626532
Reg. Date:	09/06/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMGU090135
Colour:	Blue	Odometer:	416660 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	701.24	155.00	546.24	77.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	1,180.00	220.00	15.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,101.24	1,335.00	766.24	36.47
+ GST 7.00/7.00% (S\$)	147.09	93.45	53.64	36.47
Nett Amount (S\$)	2,248.33	1,428.45	819.88	36.47

INSPECTION

Date of Assignment:	08/09/2020		
Date Inspected:	08/09/2020	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Sep 2020)

Parts: 143 HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA1330R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ROCKER PANEL OUTER GARNISH (LH)	Repair	682.80 FL	*- FL
2	1		*FRONT DOOR COMFORTDELGRO LOGO	Necessary	75.00 FS	*75.00 FS
3	1		*REAR DOOR APPS LOGO	Necessary	80.00 FS	*80.00 FS
					Sub Total (\$\$)	837.80 155.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	136.56 0.00
					Total Parts (\$\$)	701.24 155.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING.	New	400.00	280.00
2	SPRAY PAINTING.	New	1,000.00	900.00
Gross Labour Cost (S\$)			1,400.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >