

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 07/09/20

3P INSURANCE: ECICS

MODEL: HYUNDAI I 40

SURVEYOR:

VEH NO.: SHA1330R

MVA: HONG

DESCRIPTION	QTY	LIST PRICE	REMARKS
Rocker Panel Outer Garnish (LH)	1		\$682.80
SPARE PARTS SUB TOTAL			\$682.80
LESS 20%			\$136.56
DISCOUNTED SPARE PARTS TOTAL			\$546.24
FRONT DOOR COMFORTDELGRO LOGO	1		Net \$75.00
Rear Door APPS LOGO	1		Net \$80.00
NETT TOTAL			\$155.00
SPARE PARTS & NETT TOTAL			\$701.24
Panel Beating			\$400.00
Spray Painting			\$1,000.00
LABOUR TOTAL			\$1,400.00
ESTIMATE TOTAL			\$2,101.24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Panel Beating

Spray Painting

Tanghin 97495749

8/9/2020 3pm

c/s Resurvey after repair.

2 days

Tanghin @ 10/10/2020

Worth

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.